




Typ	A1 mm	A2 mm	H mm	H1 mm	W mm	D mm	D1 mm
A	33	18	19	11	13	5	4,5
B	40	22	26	17	16	6	4,5
C	50	28	32	21	20	8	4,5