



MAST
ULTRA CHARGE



MAST



English

A. Screen

①Voltage value display; ②Working status display; ③Battery level display; ④ Instant start-up mode display; ⑤Timing display;

B. Switch Buttons

Power on, power off & pause, start button;

Long press the button to turn on & off, click the button to start & pause the work in power-on mode;

C.Type-C charging port

D.Voltage Adjustment Button

Adjust the voltage to high and low.

Simultaneously press the adjust voltage +/- key to turn on/off the instant start-up mode.

E.Battery Module

The battery module is placed in the grip part

Rotate the grip to adjust the length of the needle.

F.Cartridges connector

Insert the cartridge and tighten it clockwise.

Parameters:

Stroke	4.2mm
Charging Method	Type-C
Speed	12V 11500RPM

Precautions

Please keep the machine in a cool and dry place for storage and keep it away from children; Batteries, electronic equipment, boxes electrical equipment should not be disposed of with household waste; This product is designed to work at a maximum ambient temperature of 40°C(104°F) and an altitude of 2000 meters above sea level;

Polski (język)

A. Ekran

①Wyświetlanie wartości napięcia; ②Wyświetlanie stanu pracy; ③Wyświetlanie poziomu naładowania baterii; ④Wyświetlanie trybu natychmiastowego rozruchu; ⑤Wyświetlanie czasu;

B. Przyciski przełącznika

Przycisk włączania, wyłączania i pauzy, przycisk uruchamiania;

Długie naciśnięcie przycisku włącza i wyłącza urządzenie, kliknięcie przycisku uruchamia i wstrzymuje pracę w trybie włączania;

C. Port ładowania typu C

D. Przycisk regulacji napięcia

Regulacja wysokiego i niskiego napięcia.

Jednoczesne naciśnięcie przycisku regulacji napięcia +/- włącza/wyłącza tryb natychmiastowego rozruchu.

E. Moduł baterii

Moduł baterii jest umieszczony w części uchwytu

Obrócić uchwyt, aby wyregulować długość igły.

F. Złącze kartridża

Włożyć kartridż i dokręcić go zgodnie z ruchem wskazówek zegara.

Parametry:

Udar	4.2mm
Metoda ładowania	Type-C
Prędkość	12V 11500RPM

Środki ostrożności

Urządzenie należy przechowywać w chłodnym i suchym miejscu, z dala od dzieci. Baterii, sprzętu elektronicznego i skrzynek elektrycznych nie należy wyrzucać razem z odpadami domowymi. Produkt został zaprojektowany do pracy w maksymalnej temperaturze otoczenia wynoszącej 40 °C (104 °F) i na wysokości 2000 metrów nad poziomem morza;