


DE - MONTAGEANLEITUNG: *KLEIDERSCHRANK LOFT*




AUSSTATTUNGSLISTE:

- 44 x**
Schrauben 3,5x16
Screw 3,5x16
Wkręt 3,5x16


									
Klucz „4” Wrench „4” Schlüssel „4” 1 x	Śruba M6x45 Bolt M6x45 Bolzen M6x45 4 x	Komformat Comformat screw Bestätigung 14 x	Trzpień Cam lock bolt Nockenverriegelungs bolzen 10 x		Kołek 8x35 Dowel 8x35 Holzdübel 8x35 24 x		Gwóźdź Nails Nagel 60 x	Prowadnice Guides Schubladenführungen 1 x	

		
Bolec Prong Zinke 8 x	Zawias Hinge Scharnier 6 x	Uchwyt drążka Hanger holder Kleiderbügelhalter 4 x

ZESTAWIENIE ELEMENTÓW:
LIST OF ELEMENTS:
LISTE DER ELEMENTE:



1 ROZDZIELENIE PROWADNICY
GUIDE SEPARATION
FÜHRUNGSABTEILUNG



Exploded view diagram of a mechanical assembly. The main component is a large rectangular plate labeled "D/E". Two small yellow pins, each labeled "6", are shown at the top left corner. A smaller rectangular component labeled "O/P" is shown at the bottom left, with a black rod passing through it. The "O/P" component has several numbered holes: "10" at the top left, "10" at the top right, "9" at the bottom right, and "10" at the bottom left. A long, thin metal rod is shown at the bottom right, passing through the "D/E" plate. This rod has several numbered holes: "4" at the top left, "10" at the top right, "10" at the bottom left, and "9" at the bottom right. A small yellow pin, labeled "6", is shown at the bottom right corner of the "D/E" plate. A small red and white pin, labeled "4", is shown at the bottom left corner of the "D/E" plate. A small yellow pin, labeled "6", is shown at the bottom right corner of the "O/P" component.


This exploded view diagram illustrates the assembly of a three-panel display system, consisting of panels C, F, and G. The components and their quantities are as follows:

- Panel C (Bottom):** Requires 6 screws (6) for the bottom edge, 5 screws (5) for the top edge, and 5 screws (5) for the side edges.
- Panel F (Middle):** Requires 6 screws (6) for the top edge, 4 screws (4) for the side edges, and 6 screws (6) for the bottom edge.
- Panel G (Left):** Requires 5 screws (5) for the top edge, 5 screws (5) for the bottom edge, and 5 screws (5) for the side edges.


The diagram uses a color-coded system for fasteners: yellow for screws (6), grey for screws (5), and red for screws (4). The panels are shown in a light grey color, and the background is white.

4


WIDOK SZAFY OD TYŁU
 BACK VIEW OF THE WARDROBE
 RÜCKANSICHT DES KLEIDERSCHRANK




5



6



7




8

UWAGA! PRZED MONTAŻEM CZĘŚCI „I” SPRAWDŹ PRZEKĄTNĄ!!!

NOTE! BEFORE INSTALLING PART "I", CHECK THE DIAGONAL!!!

AUFMERKSAMKEIT! VOR DER MONTAGE VON TEIL „I“ DIE DIAGONALE PRÜFEN!!!



UWAGA! GWOŹDZIE NALEŻY WBIJAĆ DO PŁYTY.

PRZEZ ŚRODEK SZUFLADY JEST TYLKO PŁYTA HDF.


NOTE! NAILS SHOULD BE HIT INTO THE BOARD.

THROUGH THE MIDDLE OF THE DRAWER THERE IS ONLY THE HDF BOARD.


AUFMERKSAMKEIT! NÄGEL MÜSSEN IN DIE PLATTE GESCHLAGEN WERDEN.

DURCH DIE MITTE DER SCHUBLADE VERLÄUFT NUR DIE HDF-PLATTE.


9




10



11



12



13

