











1,5h






G57



3,5x16 x...(4)

F15



x...(8)

P25



x...(2)

A1



ø7x50 x...(8)

G50




6x13 x...(4)

F12



x...(4)

I1



x...(8)

M8



350mm x...(1)

W1



x...(1)

A6




ø7x40 x...(4)

H4



350mm x...(2)

W2



x...(1)

K1




ø15x12 x...(12)

P4




x...(8)

C3



Z35PR x...(4)

D3



H=2


PZ35PR x...(4)

G34



3,5x16 x...(70)

K10



x...(12)

B1




ø8x35 x...(20)

I7



x...(12)

L13




x...(2)




N1




M4x9 x...(2)














I








II






IV







V




VI




1.




2.







VII




1.





2.




P25










VIII










IX

 $a=b$ 






XI









XII




XIII








XIV





XV



XVI

