



















PP 	T1 	E5x13 	RP 
4	8	6	3




M1 	K30 	MF 
12	12	4













M1	K30	T1	E5x13	KF	Q	RL
12	18	12	12	6	1	6








x3






A=B




STB



SM

A=B






SM



6


6

9



Click

Click



UM

M22