



A




x1

B




x1

C




x1

D



x1

E



x1

F




x1

G




x1

H




x10

I




x1


1




2



3



INSTRUKCJA SKRĘCANIA STELAŻU



14	8
13	4
12	2
11	8
10	12
9	1L+1P
8	34
7	17
6	34
5	1
4	1
3	2
2	4
1	1
POZ.	SZTUK