




RJ45 Tip Replacement Guide



- 1 screw cable gland
- 2 slide clamping ring
- 3 release half shells
- 4 pull wire manager out
- 5 insert new tip
- 6-9 reverse steps 4 to 1

ORDERING INFORMATION

Item number	
WX_AC_6AL-CORDR1	Single CAT6A test cord with replaceable RJ45 tip for performing CAT6A (and below) Permanent Link testing
WX_AC_6AL-CORDRIT	Single replacement RJ45 connector for CAT6A Permanent Link test cord