

# Calibration Manual



1 - Turn on device, enter 1977 and press tare.

2 - Press the number 1 and press tare.

3 - Put on the weighing balance and press tare.

4 - Input the weight of this weighing balance, such as 25KG input 2500 and press tare.

5 - Input the maximum capacity of the scale, such as 100KG input 10000 and press tare.

6 - Input the division of the scale, such as 1,2,5,10,20,(means 10g,20g,50g,100g), press tare.

7 - Completion of calibration.