

952CB-P CardBus

System Requirements

Hardware:

- A notebook computer with a Pentium Pro®, Pentium® III, IV , or equivalent processor with 1 available PCMCIA slot.
- Microsoft® Windows® 98SE/ME/NT4.0/2000/XP or later.


Package Contents

This CardBus package includes the following:

- Hardware installation guide
- Software installation guide
- Driver CD

Configuration


The Super CardBus



Installing the Software Drivers

Windows® 98SE/ME Driver Installation



1. At the Add New Hardware Wizard windows®, click on "Next".
2. Select the option "Search for the best driver for your devices (Recommend)" and click on "Next".



3. Select the option "Specify the location " and type in D:\(CD-ROM) then click on "Next", Click "Next" and then "Finish" respectively.
4. Remove the CD, then select "Yes" to restart the computer for the setup to take effect.

To verify successful installation in Windows® 95/98/ME:

1. From the main desktop, click on My Computer, then double-click on Control Panel, System, and Device Manager.
1. Double-click on either Ports (COM & LPT) or Parallel port device options. CardBus Board should be displayed when successfully installed. The port is ready to connect new device.



Windows® NT 4.0 Driver Installation

Follow the steps listed below to install the Windows® NT 4.0 drivers:

1. Go to Start and Run.
2. Insert the Driver Installation CD in CDROM drive and type in: D:\WinNT4\Install_parallel, then click on "OK" (Disk D: is CD-ROM)
2. The "welcome" window will appear. Click on "Next"
3. From the "choose Destination Location" window, click on "Next"
4. From the next "setup Complete" window, select "Yes, I want to restart my computer now" and click on "Finish"
7. Remove the CD and restart the computer for the setup to take effect.

To verify successful installation in Windows® NT 4.0:

1. Go to Start / Programs/Administrative Tools (Common) / Windows NT Diagnostics, click on Resource icon.
2. A new LPT number will be assigned for the Parallel port when successfully installed. The board is ready to connect a device.

Windows 2000 Driver installation (Or Windows XP):

1. At the Add New Hardware Wizard windows®, click on "Next".
2. Select the option "Search for the best driver for your devices (Recommend)" and click on "Next".
3. Select the option "Specify the location " and type in d:\ then click on "Next" (Disk D: is CD-ROM)
4. Click "Next" and then "Finish" respectively.
5. Remove the diskette, then select "Yes" to restart the computer for the setup to take effect.

To verify successful installation in Windows® 2000/XP:

1. From the main desktop, click on My Computer, then double-click on Control Panel, System, and Device Manager.
6. Double-click on either Ports (COM & LPT) or Parallel port device options. CardBus Board should be displayed when successfully installed. The port is ready to connect new device.