

LGA775 Tool Free Clip Installation Guide



→ Step1

Spread appropriate thermal conductive paste evenly on the CPU core.



→ Step2

Be careful not to use too much thermal compound; only a thin layer of compound is needed to cover the surface of the CPU die.



→ Step3

Place the Cooler into the retention module.



→ Step4

Push the spring nut into the hole in order.



→ Step5

Connect the power cable of the fan to the motherboard.
Complete the installation.