



Technical Data Sheet



Scenix Mural & Theme Paint (“Scenix”)

Water-Based

Low VOC (40.8 g/L Reg.)

Aliphatic Acrylic-Urethane

Brush, Roll or Spray Application



Made in U.S.A.

Scenix Mural & Theme Paint (“Scenix paint”)

A durable, lightfast water-based acrylic-urethane paint that may be used for a wide variety of interior and exterior applications with long-term results that do not fade.

For exterior, top-coat with Scenix Clear, using 2-Step Application, or another durable clear. Scenix paint is generally compatible with any clear type. Always test first.

Scenix Paint Set-Up & Mix

- Thin with 4011 Reducer 2% – 10% per vol.
- For spray-gun application, reduce as needed for atomization, generally 5 – 10% per volume.
- Stir in reducer, do not shake on agitator.
- Allow Paint mix ~ 10 minutes to acclimate, then spray.

Pot-Life

- There is no pot life.

Equipment Size & Set-Up

Spray gun: 1.2 – 1.4mm tip-size ~ 22 – 24 psi

Mini-Gun: 1.2mm tip ~ 22 – 24 psi

Brush: Use quality brush made for water-based paint.

Roller: Keep wetted edge.

Spray Gun Application

- 3 coats for pinhole-free coverage:
1 tack coat (medium) and 2 medium-wet coats.
- Apply first coat lightly as a tack coat. Allow to air dry to a matte finish before applying next coat.
- Do not allow material to dry spray as this may create adhesion failure. Too much distance at high pressure creates a dry spray.
- Scenix dries to vibrant color. Any milky haze apparent when wet dries clear.

Drying Times & Curing

At 70 degrees F and 65% Relative Humidity, Scenix will dry to in approximately 5 – 10 minutes.

- Use air to assist curing and shorten drying times.
- Do not cure with heat. Use of direct heat to dry Scenix will cause a loss of adhesion due to plasticizing of paint surface.
- Allow a 1-hour cure time minimum before top-coating with clear.

Humid & Cold Conditions

- Allow for extended drying times when painting in humid conditions or temperatures lower than 65 degrees.
- Work in lighter coats with less thinning and extended re-coat times. Less thinning may also assist drying times.
- Allowing each light coat to dry tack free before applying next coat achieves quicker times to tape or clear.

Top-Coating with a Clear

Scenix may be top-coated with Scenix Clears and a wide variety of other-type clears including catalyzed, urethane clears and epoxies.

- Scuffing not required before top-coat.

Scenix Clears

7030 Gloss, 7031 Matte, 7032 Satin

1. Thin with 4011 Reducer, 2% – 20% per volume.
2. Allow Scenix Clear mix ~ 10 minutes to acclimate, then spray.
3. Apply tack coat. Subsequent coats medium-wet.
4. 3 – 4 coats should be applied for pinhole-free coverage.
5. Do not allow material to dry spray as this may create adhesion failure. Too much distance at high pressure creates a dry spray.
6. Any milkiness from over-application will dry water-clear.

Cleaning

- Use water to clean guns after use and to rinse in-between color changes.
- Soak gun and brush in 4008 Restorer after painting. 4008 helps partially remove dried paint for easy clean-up with soap & water.
- Do not use 4012 to clean.

Coverage

- Scenix paint approx. 350 sq. feet per 1 gallon.
- Coverage varies per color.

Preparation

Follow standard practices & procedures. If the surface has been damaged, remove all loose, chalking or flaking paint from the surface.

- Scenix is suitable for all direct to substrate applications except untreated metal. Prepare untreated metal with direct-to-metal primer or phosphoric acid.
- Apply Scenix High Performance direct to plastic, aluminum, fiberglass and other difficult to paint substrates.
- For especially difficult to paint plastics, Scenix Clear is an excellent adhesion promoter.

Health & Safety

Use in a well-ventilated area. Avoid contact with eyes. Wash hands thoroughly with soap and warm water after use. Do not ingest.

When spraying or sanding, use a properly-fitting NIOSH approved respirator per the manufacturer's instructions.

Skin contact: Thoroughly wash with soap and warm water before Scenix dries. Wearing gloves is recommended.

Eye contact: Rinse with clean water for 15 minutes. Seek medical attention.

Inhalation: Use in well ventilated areas and wear a NIOSH approved respirator.

Refer to Scenix SDS for additional information.

⚠ WARNING: Cancer & Reproductive Harm - www.P65Warnings.ca.gov

Warranty

This product will perform as claimed if directions are followed. Warranty is limited to replacement or refund value of product. No other warranty is expressed or implied.

Manufactured by:



PO Box 120, 14 Airport Park Rd
East Granby, CT 06026
800.243.2712 | 860.653.5505
info@createxcolors.com