

# Rally di Roma Capitale

22<sup>th</sup> – 25<sup>th</sup> July 2021



Date:	<b>Sunday, 25 July 2021</b>	Time (decision):	<b>10.15 hrs</b>
Subject:	<b>DECISION No. 09</b>	Document No.:	<b>2.12</b>
From:	The Stewards		
To:	Competitor car No: <b>87</b> Name: <b>Maurizio Morato</b> Crew: <b>Maurizio Morato / Enrico Gallinaro</b>		
Number of pages: 2		Attachments:	[...]

The Stewards, having received a report with photo from the FIA Technical Delegate, consulted the team with the help of the CRO, have considered the following matter, determine the following:

**Fact:** During routine checks at the Stop Control zone at the end of SS 7, the car was found with the control unit of the extinguisher system not in operating position.

**Offence:** Beach of Article 253-7.2 of Appendix J to the 2021 FIA International Sporting Code

**Decision:** **Fine 1.000 €**

In accordance with Article 12.7 FIA International Sporting Code, the payment of the fines must be done online, within 48 hours of their notification, at the following address: <https://fiafines.fia.com>. Any delay in making payment may entail suspension during the period the fine remains unpaid.

**Reason:** The drivers were informed accordingly by the Stewards and was given the possibility, if they wished, to bring forward any representations other than having forgotten to activate the extinguisher system. They denied adding anything.

As stipulated in Article 253-7.2.4 of Appendix J to the 2021 FIA International Sporting Code, the system must work in all positions. Article 253-7.2 of Appendix J to the 2021 FIA International Sporting Code does not specify when the system can be switched on or switched off. For this reason, it must always be active during the rally. Doubtless it must be armed on Special Stages.

The fire extinguisher system is a major safety item to protect the crew in case of fire in the car. It is essential for the driver's safety and safety is one of the major concerns by the FIA. Safety remains a key challenge and the FIA is committed to do everything possible to protect, among others, the drivers.

It is further to be noted that the Stewards issued Communication No. 2 on Thursday 22 July reminding all competitors about the activation of the extinguisher system. Competitors must always ensure that the system is activated before leaving the service park.

The Stewards therefore concluded that this was a breach of Article 253-7.2 of Appendix J to the 2021 FIA International Sporting Code.

The decision is based on the FIA International Sporting Code Art. 11.9.1, Art. 11.9.3 f; and Art. 12.4.1.c.

# Rally di Roma Capitale

22<sup>th</sup> – 25<sup>th</sup> July 2021



Competitors are reminded of their right to appeal certain decisions of the Stewards, in accordance with Article 15 of the FIA International Sporting Code and Article 9.1.1 of the FIA Judicial and Disciplinary Rules, within the applicable time limits.

According to Art. 12.3.3.b of the Code this decision of the Stewards becomes immediately binding even in the event of an appeal, since it concerns a

**Uwe M. SCHMIDT (DEU)**  
FIA Chairman of the Stewards

**Wilhelm SINGER (AUT)**  
FIA Steward

**Angelo Raffaele PELILLO**  
ASN Steward

<b>Received by the Competitor:</b>	
Name (in block letters):	GALLIARD
Position within the team:	CO-DRIVER
Signature:	
Date: 25.07.2021	Time: 13.13

Published on the Official Notice Board on 25.07.2021 at \_\_\_\_\_ hrs