



mounting holes for
top ejectors

Note. This detail sketch is prepared to enable customers who do not have Vero manufactured extender boards to enable the ejectors to function. The boards are symmetrical and the dimensions shown also apply to the other side of the board.