## **Request for Quotation (RFQ)**

## Repair of Faulty Cookers, Stoves & HD Blender in NSPT MACL Staff Canteen at VIA

(PR 100521)

## 1. 1 no - Electrical Single Compact Cooker 1 [Coil issue].



2. 1 no - Electrical Single Compact Cooker 2 [breaker falls when it is switched on].



RFQ - Repair of Faulty Cookers, Stoves & HD Blender in NSPT MACL Staff Canteen at VIA (PR 100521)

- 3. 1 no Induction Cooker 1 [Coil issue].
- 4. 1 no Induction Cooker 2 [Coil issue].





5. 1 no - Heavy Duty Blender [an error displayed in the blender].



6. 1 no - Induction cook top (Ozti Full Module 4 Induction Heaters Electric Boiling Top) (dimension: L: 800 W: 900 H: 280; weight 53kg, cannot move so needs to repair on the spot in NSPT kitchen) [breaker falls when it is switched on ].

