

Repair of Van Toyota (G5035)

Model: TOYOTA-DBA-ZRR70W-BRXSP

- The following repairs are needed for the Van.

#	Description
1	Changing front shock
2	Changing rear shock
3	Changing ball joint
4	Changing stabilizer links
5	Changing engine gasket set
6	Engine oil leakage repair
7	Changing brake pad front set
8	Changing brake pad rear set
9	Changing engine oil
10	Changing oil filter
11	Changing coolant
12	Changing CV boots
13	Servicing brake system
14	Changing steering rack
15	Changing cabin filter
16	Changing steering intermediate shaft
17	Changing stabilizer bush
18	Radiator remove and chassis bar
19	Tinkering and painting front bumper damaged areas

- All parts to be replaced with GENUINE parts.
- Van can be in garage for repairs only up to 5 days.

28 October 2020