54046 FICHA TÉCNICA



CONTÉM

	1/2″	x17	10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 24, 27, 30, 32mm
	3/8″	x10	10, 11, 12, 13, 14, 15, 16, 17, 18, 19mm
	1/4″	x13	4, 4.5, 5, 5.5, 6, 7, 8, 9, 10, 11, 12, 13, 14mm
	1/2″	x5	16, 17, 18, 19, 22mm
	3/8″	x6	10, 11, 12, 13, 14, 15mm
	1/4″	x7	4, 5, 6, 7, 8, 9, 10mm
	1/2″	x2	E20, E24
	3/8″	x6	E10, E11, E12, E14, E16, E18
	1/4″	x5	E4, E5, E6, E7, E8
	12	xЗ	1/2" - 3/8" - 1/4"
	1/2″	x1	125mm
	3/8″	x1	125mm
	1/4″	x2	50, 100mm
	1/2″	x1	250mm

x3 1/2" - 3/8"	- 1/4"
1/2" x2 16, 21mm	
3/8″ x1 18mm	
1/2″ x1 8mm	
3/8″ x1 8mm	
1/4" x1 6mm	
x7 1.27, 1.5, 2, 2 5mm	2.5, 3, 4,
• x1 1/4"	
x1 1/4"	
x3 PH1, PH2, F	РНЗ
x3 PZ1, PZ2, P	Z3
1/4" <u>x5</u> 2, 3, 4, 5, 6	mm
x3 SL4, SL5.5,	SL7
x8 T8, T9, T10, T25, T27, T	
x8 T8, T9, T10, T25, T27, T	

		6mm	x11 x9 x5	T5, T6, T7, T8, T9, T10, T15, T20, T25, T27, T30 T7, T10, T15, T20, T25, T27, T30, T40, T45 M5, M6, M7, M8, M9
	\bigcirc		xЗ	M5, M6, M8
\square	\oplus		x2	PH3, PH4
H	- AK		x2	PZ3, PZ4
	\bigcirc	8mm	x8	7, 8, 10, 12, 14mm
	\ominus		xЗ	SL8, SL10, SL12
	$\widehat{\boldsymbol{\zeta}}$		x6	T40, T45, T50, T55, T60, T70
	ΣÔζ		х6	T40, T45, T50, T55, T60, T70



