



Minnesota.
Department of Conservation.
Photographs of State Parks, Monuments,
Recreational Areas, and Staff.

Copyright Notice:

This material may be protected by copyright law (U.S. Code, Title 17). Researchers are liable for any infringement. For more information, visit www.mnhs.org/copyright.

LAC QUI PARLE

L.Q.P. - 10

Care in Main Parking Area from Parkway

5





LAC QUI PARLE

PRINTS WITHOUT NEGATIVES























LAC QUI PARLE

PRINTS WITHOUT NEGATIVES





Piling taken out by ice in spring of 1940.

Note: Pile bent on either side weakened by ice impacts making it necessary to hold piers in place with cables.



68

Piling in pier sheared off by ice
which were later spliced.



Piling taken out by ice in spring
of 1940.

Note pile bent on either side weakened
by ice inpacts making it necessary
to hold piers in place with cables.

E 4 2









Floor constructed of salvaged pine material. Deck uneven and rought. Heaving of 2 or 3 inches over pile bents due to unsuffieient piling penetration and weakening of bridge due to ice jams.

New planks have been used in spots wher old plank have been broken through by traffic.

A 1 3







LAC QUI PARLE

PRINTS WITHOUT NEGATIVES

Lac Qui Parle Mission













