

## **Always:**




## 1. Use Fall Protection when working at heights of 6'-0 or greater.




2. Check Safety Devices before



3. Verify control of energy source before starting work on equipment and plants.



4. Have authorization before entering a confined space.



5. Have an approved plan before making a critical lift.



6. Ensure protection before working in failure zone of an excavation.

7. Maintain minimum clearance from power line while operating equipment.

8. Remember the traffic control plan is for your protection, stay within its limits.

