

<b>CURB RAMPS</b>							
<b>Street/Intersection</b>	<b>Violation</b>	<b>Comment</b>	<b>Priority</b>	<b>Solution</b>	<b>Est. Cost</b>	<b>Est Corrected Date</b>	<b>Date Corrected</b>
<b>B Street/Clark</b>	No truncated domes on existing curb ramps.	Verify ramp compliance with current standards.	L	Provide truncated domes at existing curb ramps. Remove/replace ramps as needed.	\$4,500	FY2014-15	
<b>C Street/Clark</b>	No truncated domes on existing curb ramps.	Verify ramp compliance with current standards.	L	Provide truncated domes at existing curb ramps. Remove/replace ramps as needed.	\$4,500	FY2014-15	
<b>D Street/Clark</b>	No truncated domes on existing curb ramps.	Verify ramp compliance with current standards.	L	Provide truncated domes at existing curb ramps. Remove/replace ramps as needed.	\$4,500	FY2014-15	
<b>E Street/Clark</b>	No truncated domes on existing curb ramps.	Slope exceeds 8.33% at one location. Verify ramp compliance with current standards.	L	Replace Ramp	\$4,500	FY2014-15	
<b>E Street (Across from 419 &amp; 421 E Street)</b>	Slope exceeds 8.33% slope.	Sidewalk entry ramp parallel with sidewalk that leads to Sterling Park on Southside of the street.	M	Remove end row of bricks and bevel to slope less than 8.33%. Replace ramp as needed.	\$4,500	FY2014-15	
<b>F Street/ Clark</b>	No truncated domes on existing curb ramps.	Verify ramp compliance with current standards.	L	Provide truncated domes at existing curb ramps. Replace ramp as needed.	\$9,000	FY2014-15	
<b>F Street/Hillside (2 ramps)</b>	No truncated domes on existing curb ramps. Slopes are not compliant	Verify ramp compliance with current standards.	L	Replace Ramp	\$9,000	FY2014-15	

Street/Intersection	Violation	Comment	Priority	Solution	Est. Cost	Est Corrected Date	Date Corrected
Mission Rd/Holy Cross Cemetery	No Handicap Ramp at driveway	The southmost driveway into Holy Cross Cemetery.	M	Install Ramps	\$9,000	FY2013-14	
Hillside Blvd/Lawndale	No truncated domes on existing curb ramp.	slopes not compliant. Verify ramp compliance with current standards.	L	Replace Ramp	\$4,500	FY2013-14	
Mission Rd/Lawndale	No truncated domes on existing curb ramps.	Verify ramp compliance with current standards.	L	Provide truncated domes at existing curb ramps. Replace ramp as needed.	\$4,500	FY2013-14	
Serramonte Blvd/SerraCtr	No truncated domes on existing curb ramps.	Intersection at Serramonte and the main entrance to Target Shopping Plaza. Verify ramp compliance with current standards.		Provide truncated domes at existing curb ramps.	\$0		Feb-09
Serramonte Blvd/Serra Ctr	No truncated domes on existing curb ramps.	Secondary entrance to Target Shopping Plaza adjacent to Lexus dealership. Verify ramp compliance with current standards.		Provide truncated domes at existing curb ramps.	\$0		Feb-09
Serramonte Blvd/Serra Ctr	No truncated domes on existing curb ramps.	Secondary entrance to Target Shopping Plaza behind Ono BBQ. Verify ramp compliance with current standards.		Provide truncated domes at existing curb ramps.	\$0		Feb-09
Junipero Serra Blvd and Serra Center	No truncated domes on existing curb ramps.	Entrance to Target Shopping Plaza adjacent to BevMo. Verify ramp compliance with current standards.	L	Provide truncated domes at existing curb ramps. Replace ramp as needed.	\$4,500	FY2011-12	
Colma Blvd	No truncated domes on existing curb ramps.	Entire intersection that serves as main entrance to Home Depot and 280 Metro Mall. Verify ramp compliance with current standards.	L	Provide truncated domes at existing curb ramps. Replace ramp as needed.	\$9,000	FY2013-14	

Street/Intersection	Violation	Comment	Priority	Solution	Est. Cost	Est Corrected Date	Date Corrected
Colma Blvd	No truncated domes on existing curb ramps.	Behind Bridal Business between Home Depot and the Best Buy. Existing ramps are on the North side. Verify ramp compliance with current standards.	L	Provide truncated domes at existing curb ramps.	\$4,500	FY2013-14	
Serramonte Blvd	Sidewalk ends without signage	On the north side near Colma PD	L	Install signage for ped detour and barricade.	\$1,500	FY2010-11	
Colma Blvd	No truncated domes on existing curb ramps.	Entire intersection that serves as main entrance to Best Buy. Verify ramp compliance with current standards.	L	Provide truncated domes at existing curb ramps. Replace ramp as needed.	\$9,000	FY2013-14	
Serramonte Blvd/Hillside	No truncated domes on existing curb ramps	Verify ramp compliance with current standards.	L	Provide truncated domes at existing curb ramps. Replace ramp as needed.	\$16K	FY2011-12	
Mission Rd/Isabelle Cir	No truncated domes on existing curb ramps.	Verify ramp compliance with current standards.	L	Provide truncated domes to existing curb ramps. Replace ramp as needed.	\$8,000	FY2013-14	
Collins Ave/Serramonte	Ramp at Ford Dealership is not standard. C/S exceeds 2%		L	Replace ramp	\$4,500	FY2011-12	
Junipero Serra Blvd	No truncated domes and signage for end of ramp	Southmost ramp near Hickey Blvd Verify ramp compliance with current standards.	L	Install detectable ramp, signage and barricade. Replace ramp as needed.	\$6,000	FY2011-12	
Juniper Serra Blvd	No truncated domes and slopes not compliant	Driveway into the southeast corner building	L	Replace ramps	\$9,000	FY2011-12	
Junipero Serrra Blvd and Serramonte	Ramps and pedestrisn push buttons not compliant	Intesection upgraded in 2005-06 JSB Phase II Project					2005/06

Street/Intersection	Violation	Comment	Priority	Solution	Est Cost	Est Corrected Date	Date Corrected
Junipero Serra Blvd and Serra Center	Ramps not compliant	Intesection upgraded in 2005-06 JSB Phase II Project					2005/06
Junipero Serra Blvd/Southgate	Ramps not compliant	Intersection upgraded in 2005/06. JSB Phase II Project					2005/06
Junipero Serra Blvd/Colma	Ramps not compliant	Intersection upgraded in 2005/06. JSB Phase II Project					2005/06
Hillside Blvd/Olivet Pkwy	Crosswalk Not-Complaint	Ramps were installed in 2006. There is no sidewalk on the east side of Hillside.	M	Remove crosswalk	\$2,000	FY2010-11	
<b>TOTAL</b>					<b>\$132,000</b>		

