

Appendix C

Leaking Underground Storage Tanks (LUSTs) Report

**Upper Tuscarawas River Watershed
Leaking Underground Storage Tank (LUST) Report**

Map Symbol	Facility Name and Address	Facility Identification #	Priority*	Status**	Class***	Last Update****	L.U.S.T. Trust Fund (LTF) Eligibility*****
1	Service Station 1060 S. Broadway St. Akron, OH 44311	7720527-0-FY92	2	ICR	D	12/31/97	1
2	Ohio Concrete 1830 Manchester Rd. Akron, OH 44314	779757-0-9000	2	ICR	D	12/30/96	1
3	Firestone Tire and Rubber 1600 Firestone Pkwy. Akron, OH 44317	7700483-0-F900	2	ICR	D	09/05/90	1
4	Unoven 9376-125 940 S. Arlington Rd. Akron, OH 44306	7721031-0-FY92	2	SAS	D	01/13/97	1
5	Sunoco 0000-0025 (Sun Mart) 1281 S. Arlington Rd. Akron, OH 44306	7710378-0-FY91	2	SAS	A	01/07/97	1
6	BP 05625 571 W. Waterloo Rd. Akron, OH 44314	7713451-0-FY91	2	RPT	D	12/30/97	1
7	Sunoco 2168 S. Main St. Akron, OH 44319	7741277-0-FY94	2	SAC	D	01/16/97	1
8	Unocal Holland Oil 375 E. Waterloo Rd. Akron, OH 44319	7732094-1-FY93	1	ICR	D	04/15/96	1
9	Gastown 3387 389 E. Waterloo Rd. Akron, OH 44319	7712923-2-FY92	2	DIS	D	01/08/97	1
10	Gastown 3387 389 E. Waterloo Rd. Akron, OH 44319	7732094-2-FY93	2	CAS	D	01/15/97	1
11	Former Shell 449 E. Waterloo Rd. Akron, OH 44319	7700982-0-F900	2	CAP	D	03/28/95	1

Upper Tuscarawas River Watershed Leaking Underground Storage Tank (LUST) Report

Map Symbol	Facility Name and Address	Facility Identification #	Priority*	Status**	Class***	Last Update****	L.U.S.T. Trust Fund (LTF) Eligibility*****
12	BP 05559 471 E. Waterloo Rd. Akron, OH 44319	7732511-0-FY94	2	SAS	D	01/15/97	1
13	Waterloo Dental Assoc. Bldg. 475 E. Waterloo Rd. Akron, OH 44319	7732094-0-FY93	2	CAP	D	02/23/98	1
14	Forest Motors 1011 E. Waterloo Rd. Akron, OH 44306	7770681-0-FY97	2	SAS	D	08/14/97	1
15	Speedway 3308 3152 Manchester Rd. Akron, OH 44319	7770150-0-FY97	2	DIS	D	05/29/97	1
16	Unknown (National City Bank) 3379 Manchester Rd. Akron, OH 44319	7702708-0-FY91	1	CAP	D	03/11/94	1
17	Amoco State St. and Manchester Rd. Akron, OH 44319	778076-0-8007	2	ICR	D	07/11/95	1
18	Dennis Clay Residence 73 Portage Lakes Dr. Akron, OH 44319	7760415-0-FY96	1	RPT	A	04/15/96	1
19	Holland Oil #20 3130 S. Main St. Akron, OH 44319	7760415-1-FY96	2	SUS	D	03/24/98	1
20	Jones Transfer Co. 999 Swartz Rd. Akron, OH 44319	7702423-1-FY91	2	ICR	D	01/06/97	1
21	Kuality Kars, Inc. 2444 S. Arlington Rd. Akron, OH 44319	7750885-0-FY95	2	ICR	D	03/20/98	1
22	BP Oil Company 3171 S. Arlington and I-77 Akron, OH 44312	7770398-0-FY97	2	ICR	D	08/21/97	1

Upper Tuscarawas River Watershed Leaking Underground Storage Tank (LUST) Report

Map Symbol	Facility Name and Address	Facility Identification #	Priority*	Status**	Class***	Last Update****	L.U.S.T. Trust Fund (LTF) Eligibility*****
23	Sunoco 0001-5347 3155 S. Arlington Rd. Akron, OH 44312	7701017-0-F900	2	ICC	D	07/17/90	1
24	BP 05697 2536 S. Arlington Rd. Green, OH 44312	777043-2-8000	1	CAP	D	08/08/97	1
25	Gastown #3692 3540 S. Arlington Rd. Akron, OH 44312	777043-4-8000	2	DIS	D	01/03/97	1
26	Speedway #3692 3540 S. Arlington Rd. Akron, OH 44312	777043-5-FY97	2	DIS	D	08/20/97	1
27	Former Gulf 3557 S. Arlington Rd. Akron, OH 44312	777043-3-8000	1	DIS	A	04/14/95	1
28	Speedway #3672 5211 Manchester Rd. Akron, OH 44319	7732088-1-FY97	2	DIS	D	02/23/98	1
29	Speedway #3672 5211 Manchester Rd. Akron, OH 44319	7732088-1-FY98	2	DIS	D	02/03/98	1
30	Bank One 5638 Manchester Rd. Akron, OH 44319	7741773-0-FY95	1	SUS	A	10/17/94	1
31	Beverage Express Drive Thru 4900 South Main Akron, OH 44319	7771042-0-FY97	2	ICR	D	02/03/98	1
32	Bolin Oil 3634 Massillon Rd. Uniontown, OH 44685	7701952-1-F919	2	RPT	D	01/06/97	1
33	Dairy Mart #5089 3534 Massillon Rd. Green, OH 44232	7761505-0-FY97	2	DIS	D	01/03/97	1
34	Dairy Mart #5089 3534 Massillon Rd. Green, OH 44232	7761505-0-FY97	2	DIS	D	04/11/97	1

Upper Tuscarawas River Watershed Leaking Underground Storage Tank (LUST) Report

Map Symbol	Facility Name and Address	Facility Identification #	Priority*	Status**	Class***	Last Update****	L.U.S.T. Trust Fund (LTF) Eligibility*****
35	Dairy Mart #5089 3534 Massillon Rd. Green, OH 44232	7701592-2-FY97	2	DIS	D	08/19/97	1
36	Dairy Mart #5089 3534 Massillon Rd. Green, OH 44232	7701592-3-FY98	2	DIS	D	08/19/97	1
37	Dairy Mart #5089 3534 Massillon Rd. Green, OH 44232	7701592-4-FY97	2	DIS	D	09/08/97	1
38	Con Way Central Express 3733 Massillon Rd. Greensburg, OH 44232	7732009-0-FY94	2	CAP	D	12/17/97	1
39	Lake Township Garage 12360 Market Ave. Hartville, OH 44632	7610242-0-FY91	2	ICR	D	03/04/91	1
40	Edison Gas Station Near c/o Edison and Market Hartville, OH 44632	7623338-0-FY93	2	SUS	D	10/02/97	1
41	Hartville CITGO 125 W. Maple St. Hartville, OH 44632	7650850-1-FY97	2	ICR	D	11/25/97	1
42	Green Highway Dept. 1844 Greensburg Rd. Greensburg, OH 44232	7711471-2-FY91	2	ICR	D	01/08/97	1
43	Green Local School District 1900 Greensburg Rd. Greensburg, OH 44232	7702990-1-F900	2	ICR	D	01/07/97	1
44	Shipe Landscaping 4730 Massillon Rd. Greensburg, OH 44232	7700164-0-F900	2	ICA	D	06/26/91	1
45	Greensburg/Bills Amoco 4776 Massillon Rd. Greensburg, OH 44232	779548-1-9000	1	SAS	C	04/25/95	1
46	Diversified Industries 4781 Massillon Rd. Greensburg, OH 44232	779548-2-9000	1	RPT	A	04/01/91	

Upper Tuscarawas River Watershed Leaking Underground Storage Tank (LUST) Report						
Map Symbol	Facility Name and Address	Facility Identification #	Priority*	Status**	Class***	Last Update**** L.U.S.T. Trust Fund (LTF) Eligibility*****
47	Unknown (Residence) 4785 Massillon Rd. Greensburg, OH 44232	779548-0-9000	1	RPT	D	06/12/96 1
48	Adjutant General OMS #1 Akron Canton Regional Airport Greensburg, OH 44232	7660920-0-FY96	2	DIS	D	11/27/96 1
49	Firestone Flight Ops Akron Canton Regional Airport Greensburg, OH 44232	779986-0-F900	2	CAP	D	01/17/92 1
50	Rapid Air Freight Akron Canton Regional Airport Greensburg, OH 44232	7710199-0-FY91	2	SAS	D	01/07/97 1
51	Air Force and National Guard Akron Canton Regional Airport Greensburg, OH 44232	7710578-0-FY91	2	SAC	D	03/15/91 1

*Priority of LUST Incidents - The priorities used by BUSTR are 1 and 2, with one being the higher priority.

** Each status code is a three-letter abbreviation that corresponds with the corrective action status:

RPT - Reported

A release incident has been reported to BUSTR and the report has not been examined or investigated by BUSTR or another agency to determine if the incident is an eligible LTF site, or

A release incident has been reported to BUSTR, but the source of the release is not known. A follow-up investigation may identify one or more possible sources, and multiple facility tracking numbers are (or will likely be) used. For multiple facility reports, the "00" incident stays in the RPT status (there are not tanks at the "00" location). Because each facility later identified has its own incident number, they will also have their own status code.

SUS - Suspected

A release is suspected to have occurred from a LTF UST system (or a spill or overflow less than 25 gallons was reported). BUSTR or another response agency has verified that some BUSTR response is necessary, or the O/O has reported one of the required reporting triggers in the state or federal regulation.

A written report has been submitted by the RP indicating the status of progress at the incident. The report may be a 60-day progress report, or another first report from the RP (i.e., site check, etc.). BUSTR may not have reviewed the report for adequacy yet.

ICR - Initial Corrective Action Program Report

ICC - Initial Corrective Action Completed

The initial site check and free product removal report, if applicable, have been submitted and BUSTR has found the reports to be adequate. All initial corrective action requirements have been met, though some actions may still be in place (i.e. product recovery, soil venting, etc.)

DIS - Disproved

A suspected release investigation was conducted at this location and a release was disproved following the required confirmation procedure, or was disproved following a field investigation by BUSTR staff. No further corrective actions are required at this location.

SAC - Site Assessment Completed

The site assessment has been submitted and BUSTR has found it to be adequate. All site assessment requirements have been met.

SAS - Site Assessment Submitted

A site assessment has been submitted by the RP and BUSTR will review the assessment for adequacy. Additional information may be required and subsequent submissions may be required.

CAS - Corrective Action Plan Submitted

A long-term corrective action plan has been submitted by the RP and BUSTR is reviewing the plan for adequacy. An exposure assessment may be required. Prior to BUSTR approval, public participation requirements will be met to determine public comments. Subsequent submissions may be required.

CAP - Corrective Actions in Progress

Long-term corrective actions are in progress and progress reports are submitted as required in the corrective action plan.

*** Classification of LUST Incidents - There are four classes used to distinguish whether a source and RP are identified and the RP's willingness to proceed.

Class	Definition
A	Unknown source and/or responsible person.
B	Known suspected or confirmed source and either: 1) the responsible person in recalcitrant, or 2) no responsible person can be located, and BUSTR plans to or has obligated LTF funds to conduct corrective actions (beyond emergency work)
C	Known suspected or confirmed source and responsible person - RP is proceeding with investigation or corrective actions following a formal enforcement action.
D	Known suspected or confirmed source and responsible person is voluntarily, or under an informal enforcement action, proceeding with investigation or corrective actions.

****Last Update - The last time the incident was updated in the database.

LTF ELIGIBILITY

***** An incident is eligible for LUST Trust Fund oversight and/or spending when it is suspected or confirmed that a release has occurred from a RCRA subtitle I UST (a federally defined petroleum tank). This includes spills and overfills over 25 gallons and less than 25 gallons when not cleaned up.

The LTF code for eligible incidents is the value "1". All of the Leaking Underground Storage Tanks located in the Upper Tuscarawas River Watershed are eligible for the LTF.

Source: Bureau of Underground Storage Tank Regulations