

COMMUNITY DEVELOPMENT DEPARTMENT PHONE: 415-485-3085 FAX: 415-485-3184

Owner checklist for conditions that contribute to mold growth

- .. 1. Roof leaks
- 2. Leaking gutters or blocked gutters
- ... 3. Construction defects: Lack of vapor barrier; improper or missing flashing.
- .. 4. Inoperable sumps in the crawl space. Sump or storm water NOT directed away from the building.
- ... 5. Irrigation spray at the base of the building.
- ... 6. Storm water flow toward the building foundation—improper slope.

- .. 9. Inoperable heat in units
- .. 10. Waste plumbing leaks in units.
- " 11. Hot water heater leaks; laundry room leaks into habitable space.
- .. 12. Leaking windows.
- .. 13. Inoperable mechanical ventilation or improperly sized mechanical ventilation.
- ^{..} 14. Water damaged material and "paint-over" repairs.
- ... 15. Overhead staining in units.
- ... 16. Deteriorated tile and grout; moldy caulking; leaking sinks; water damaged cabinetry.
- .. 17. Landscape water waste.
- ... 18. Defective PRV (Pressure regulating Valve).
- .. 19. Recurrent backflow conditions due to defective sewer plumbing.