

<u>Pavement Condition Index (PCI)</u>	<u>Restoration Guidelines</u>
90+ <sup>(1)</sup>	Moratorium Street. Emergency encroachment only. Subject to special conditions and pavement restoration along entire property frontage.
70-90 <sup>(1)</sup>	<p>For roads less than 24 ft wide: Up to full width restoration (when applicable).            For roads over 24 ft wide: Restoration to centerline unless repair crosses the centerline then up to a full width restoration is required</p> <p>Restoration to extend up to 5 feet beyond each side of the trench excavation, including a structural pavement section extending 24 inches outside the limits of the trench excavation per DWG No. 330<sup>(2)</sup> and DWG No. 380<sup>(2)</sup>.</p>
50-70	Restoration to extend up to 5 feet beyond each side of the trench excavation, including a structural pavement section extending 24 inches outside the limits of the trench excavation per DWG No. 330 <sup>(2)</sup> and DWG No. 380 <sup>(2)</sup> .
0-50	Restoration to extend minimum 2 feet beyond each side of the trench excavation, per DWG No. 330, 360, and 370 <sup>(2)</sup> .

<sup>(1)</sup> ADA Curb Ramp upgrades on case by case basis

<sup>(2)</sup> Drawing can be found in the Uniform Construction Standards for All Cities and County of Marin, adopted July 2018.

<sup>(3)</sup> Compaction test results documenting the relative compaction of soil backfill will be required for projects involving significant excavation/trenching.