



**GENERAL NOTE:**

1. Remove all drop ceiling and replace with 2'x2'.
2. Clean all surfaces from smoke damage- estimate gyp. bd. and repaint.
3. Clean all surfaces from smoke damage- estimate gyp. bd. and repaint.
4. Remove any fire damaged wood framing and replace.
5. Remove any fire damaged wood framing and replace.

TREVISTON ELLIOTT ARCHITECT  
 1300 PINE STREET  
 SUITE 100  
 ALBUQUERQUE, NEW MEXICO 87102  
 (505) 241-1000  
 trevistonelliott.com

SUNDANCER  
 ALBUQUERQUE, NEW MEXICO

### PLUMBING FIXTURE CALCULATIONS

NOTE: NO CHANGE TO EXISTING PLAN

GROUP 1

SUNDANCER JEWELRY	
Total Number of occupants	= 62
NUMBER OF FIXTURES REQUIRED (Per 8 occupants)	
Water closets / urinal	1 per 8 occupants = 8
Lavatories	1 per 40 occupants = 2
Sinks	1 per 40 occupants = 2
Drinking fountains	1 provided

### OCCUPANCY LOAD

NOTE: NO CHANGE TO EXISTING PLAN

GROUP 1

AREA	USE	LOAD FACTOR
1,279	Office	15 net
300	Conference	15 net
1,279	Restroom	15 net
2,862	Kitchen	15 net
191	Accessory Storage	15 net
<b>TOTAL BUILDING</b>		<b>62</b>

**1** Floor Plan  
 SCALE: 3/8" = 1'-0"

Date: June 4, 2015  
 Sheet: Floor Plan