



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/BiA54MmJQeWXb9h2g/full_report_0068450_BiA54MmJQeWXb9h2g.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services.

Inspection Details	
Year	2017
Make	Caterpillar
Model	239D
Date of Inspection	03/19/2024
Location of Inspection	7421 Highway 5, Nauvoo, AL, 35578
Serial Number	CAT0239DLBL901671
Cylinders	See Notes
Engine Hours	1,620
EMS Warning Lights	No Active Warnings
Travel Control	No Damages Observed
Operator's Seat	No Damages Observed
Mirrors	No Damages Observed
Radio	No
A/C	No
Steering Wheel	N/A



Inspection Details Cont'd	
Pedals	No Damages Observed
Floorboard	No Damages Observed
Power Mirrors	No
Heated Mirrors	No
Switches and Controls	No Damages Observed
Steps	See Notes
Handrails	See Notes
Oil Dipstick	Good Level / Good Color
Engine Compartment	See Notes
Exhaust	Single - See Notes
Axles	N/A
Deluxe Instrumentation	No
Backup Camera	No
ROPS	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	No Damages Observed
Left Track Condition	No Damages Observed
Left Track Brand	Trek
Left Track Size	320X86BX49
Left Track Tread Depth Measurement	1"
Right Track Condition	See Notes
Right Track Brand	Trek
Right Track Size	320X86BX49
Right Track Tread Depth Measurement	1"
Attachments - Bucket	No Damages Observed
Cab Interior	See Notes
Comments	The rear door paint is scratched, and the door grille has dents in it. The exhaust tip is turned to the right. The upper top glass is faded. The bucket step is bent. The entry step is bent. The coolant level is low in the reservoir. The pins and bushings from the tilt cylinder rod ends to the coupler appear to be worn out and have gaps. The hydraulic hose on the bottom of the bucket has cracked rubber. The lift cylinders appear to be oily and possibly leaking. The front left grab handle is bent. The electrical plug on the left loader arm is missing its cover, and the retainer plate for the plug is bent. The front lower part of the cab has paint chipping. The headliner has some staining. The tilt cylinders have some paint chipping on them. The right track appears to have a cut in the tread lug.

Inspection Details Cont'd

Aspen Field Services



Front Left / ROPS / 03-19-2024



Front Right / ROPS / 03-19-2024

Aspen Field Services



Rear Left / 03-19-2024



Rear Right / 03-19-2024

Aspen Field Services



Left / 03-19-2024



Right / 03-19-2024

Aspen Field Services



Front / 03-19-2024



Rear / 03-19-2024

Aspen Field Services



Serial Number: CAT0239DLBL901671 / 03-19-2024



EMS Warning Lights / 03-19-2024

Aspen Field Services



Engine Hours: 1,620 / 03-19-2024



Cab Interior / 03-19-2024

Aspen Field Services



Operator's Seat / 03-19-2024



Floorboard / Pedals / 03-19-2024

Aspen Field Services



Switches and Controls / 03-19-2024



Switches and Controls / 03-19-2024

Aspen Field Services



Mirrors / 03-19-2024



Switches and Controls / Travel Control / 03-19-2024

Aspen Field Services



Switches and Controls / Travel Control / 03-19-2024



Steps / 03-19-2024

Aspen Field Services



Steps / 03-19-2024



Handrails / 03-19-2024

Aspen Field Services



Handrails / 03-19-2024



Exhaust Pipe / 03-19-2024

Aspen Field Services



Engine Compartment / 03-19-2024



Engine Compartment / 03-19-2024

Aspen Field Services



Oil Dipstick / 03-19-2024



Oil Dipstick / 03-19-2024

Aspen Field Services



Attachments / 03-19-2024



Cylinders / 03-19-2024

Aspen Field Services



Cylinders / 03-19-2024



Cylinders / 03-19-2024

Aspen Field Services



Cylinders / 03-19-2024



Front Lights / 03-19-2024

Aspen Field Services



Rear Lights / 03-19-2024



Rear Lights / 03-19-2024

Aspen Field Services



Rear Lights / 03-19-2024



Rear Lights / 03-19-2024

Aspen Field Services



Right Track Condition / 03-19-2024



Right Track Condition / 03-19-2024

Aspen Field Services



Right Track Condition / 03-19-2024



Right Track Condition / 03-19-2024

Aspen Field Services



Right Track Condition / 03-19-2024



Right Track Condition / 03-19-2024

Aspen Field Services



Right Track Brand / 03-19-2024



Right Track Size / 03-19-2024

Aspen Field Services



Right Track Tread Depth Measurement / 03-19-2024



Left Track Condition / 03-19-2024

Aspen Field Services



Left Track Condition / 03-19-2024



Left Track Condition / 03-19-2024

Aspen Field Services



Left Track Condition / 03-19-2024



Left Track Condition / 03-19-2024

Aspen Field Services



Left Track Condition / 03-19-2024



Left Track Brand / Left Track Size / 03-19-2024

Aspen Field Services



Left Track Tread Depth Measurement / 03-19-2024