

Release Notes

Software Version: V3R0.85.0, 2024-12-01

Unify Phone

Current release status can be verified via the Software Supply Server (SWS)

© Copyright, Unify Software and Solution GmbH & Co. KG All rights reserved.

This document provides general information about the release, generics, and other relevant notes for the corresponding product and its correction versions.

The information provided in this document contains merely general descriptions or characteristics of performance which in case of actual use do not always apply as described or which may change as a result of further development of the products. An obligation to provide the respective characteristics shall only exist if expressly agreed in the terms of contract. Availability and technical specifications are subject to change without notice.



Table of Contents

1	HISTORY OF CHANGE	. 2
1.1 1.2		
2	CHANGES	. 3
2.1 2.2 2.3	2 RESOLVED REPORTED PROBLEMS / SYMPTOMS	. 3
3	IMPORTANT ISSUES, WORKAROUNDS, HINTS AND RESTRICTIONS TO A SPECIFIC RELEASE	. 3
3.1 3.2		
	3.2.1 Troubleshooting issues 3.2.2 Xiaomi Devices - Granting additional app permissions	. 4
3.3 4	3 RESTRICTIONS HARDWARE AND SOFTWARE COMPATIBILITY	
4.1		
4.2 4.2 4.2	3 Loadware	. 4
	4.4.1 Software components included in this release	
4.5	5 OPERATING SYSTEMS	. 5
4.6	6 COMPLIANT PRODUCTS	
	4.6.2 Other products	. 6
	4.6.3 Third-Party products	. 6
_	ADDITIONAL INFORMATION	6

1 History of Change

1.1 Release notes content

Version	Date	Description of changes	
1.0	2024-11-21	Initial version for V3R0.85.0	



1.2 Product versions history

Software Version	Production Version	Date	Remarks
V3R0.76.0		2024-07-28	
V3R0.77.0		2024-08-11	
V3R0.78.0		2024-08-25	
V3R0.79.0		2024-09-08	
V3Ro.8o.o		2024-09-22	
V3Ro.81.0		2024-10-06	
V3Ro.82.0		2024-10-20	
V3Ro.83.0		2024-11-03	
V3Ro.84.0		2024-11-17	
V3Ro.85.0		2024-12-01	

2 Changes

2.1 Implemented Change Requests / New features

Not applicable for this release.

2.2 Resolved Reported Problems / Symptoms

Tracking Reference	Summary	Released in Version
PRB000078740	OSV: When a user clicks the voicemail button, the Voice Mail Access Number configured in the Mobile Client profile assigned on their OSMO DN, is called	V3Ro.85.0

2.3 Resolved Vulnerabilities

Tracking Reference	Summary	Released in Version
CVE-2024-21534	Versions of the package jsonpath-plus before 10.0.0 are vulnerable to Remote Code Execution (RCE) due to improper input sanitization. An attacker can execute aribitrary code on the system by exploiting the unsafe default usage of vm in Node.	V3Ro.85.0
CVE-2024-24790	The various Is methods (IsPrivate, IsLoopback, etc) of stdlib did not work as expected for IPv4-mapped IPv6 addresses, returning false for addresses which would return true in their traditional IPv4 forms.	V3Ro.85.0
CVE-2024-47764	cookie is a basic HTTP cookie parser and serializer for HTTP servers. The cookie name could be used to set other fields of the cookie, resulting in an unexpected cookie value. A similar escape can be used for path and domain, which could be abused to alter other fields of the cookie.	V3Ro.85.0

3 Important Issues, Workarounds, Hints and Restrictions to a specific release



This section provides the latest information at time of software release and is only pertaining to the time of release notes generation.

3.1 Important Issues

Tracking Reference	Internal Reference	Summary	Workaround / Actions
PRB000080199	NGTC-12480	requires to unlock the device to access the call control view	Samsung devices with Android 14: Press the "back" button on the lock screen

3.2 Workarounds, Hints

3.2.1 Troubleshooting issues

In the link below you may find the Troubleshooting Guide for Unify Phone https://nuxeo.unify.com/nuxeo/site/proxy/nxdoc/view/raw/59a4c308-57f9-46a6-b4c0-d05a44d99711

3.2.2 Xiaomi Devices - Granting additional app permissions

For Unify Phone to work properly on a Xiaomi device, you need to manually grant the app with a set of UI permissions.

- 1) To allow Unify Phone to use the background autostart service:
 - a) On your device **Settings**, navigate to **Apps > Permissions > Autostart**.
 - b) Switch the slider next to Unify Phone to **ON**.
- 2) To allow Unify Phone to show notifications on phone's lock screen:
 - a) On your device **Settings**, navigate to **Apps > Permissions > Other permissions**.
 - b) Tap **Permissions > Show** on Lock screen.
 - c) Enable the checkbox next to Unify Phone.

These steps may vary depending on the MIUI version.

3.3 Restrictions

Not applicable for this release.

4 Hardware and Software Compatibility

4.1 Hardware

Not applicable for this release.

4.2 Firmware

Not applicable for this release.

4.3 Loadware

Not applicable for this release.



4.4 Software / Applications

4.4.1 Software components included in this release

Released with	Component	Version
V3R0.85.0	Web Client	3.0.5901
V3R0.85.0	Android Client	3.0.85
V3R0.85.0	iOS Client	3.0.85

Mobile app availability is subject to Apple's and Google's release process for the respective app stores.

4.5 Operating systems

Below are the Operating System versions supported by Unify Phone mobile clients.

Component	Minimum Supported Version	Latest Supported Version	
Android Client	Android 10	Android 14	
iOS Client	iOS 16	iOS 18	

4.6 Compliant products

This section lists the versions associated with the communication platforms, other products and third-party products that have been tested for use with this version of the product and are known to work.

4.6.1 Communication platforms

	Product	Verified Software Versions		
Product Family		Version	Status	NUXEO Note
OpenScape Voice	OpenScape Voice	V10R3.31.2	GA	Check SWS
OpenScape 4000	OpenScape 4000	V11R0.22 CSTA HF2 RMX HF6 LW HF2	GA	Check SWS
SBC	SBC	V11 R1.01.00	GA	Check SWS
OpenScape Business	OSBiz X OSBiz S	V3R3.2.1.008 V3R3.2.1.008	HF	Check SWS
OpenScape Common Management Platform	OpenScape Common Management Platform	V10R5 FR15.0	GA	Check SWS

The current Common Compatibility Matrix can be found on the Mitel Unify Partner Portal https://www.mitel.com/login/unify-login.

Note: Use the "Search" option and Search Documents for "Common Compatibility Matrix" (select "Search on title only").



4.6.2 Other products

Not applicable for this release.

4.6.3 Third-Party products

Not applicable for this release.

5 Additional Information

Unify Phone Connector status and potential alerts can be found under: https://status.mitel.io/