












## Statické tesnenia a O- a X- krúžky

Pohyb	Profil	Typ	Materiál	Rýchlosť	Teplota	Tlak [bar]	Poznámky:
		STA 01	PU NBR EPDM	4 m/s	(-30; 105)°C (-25; 100)°C	400 250 250	
		STA 01 A	PU NBR EPDM	4 m/s	(-30; 105)°C (-25; 100)°C	400 250 250	
		STA 02	PU NBR FPM	-	(-30; 105)°C (-25; 100)°C (-20; 210)°C	600 160 160	
		STA 03	PTFE/ skrutkovitá pružina	0,1 m/s	(-60; 200)°C	800 400	
		STA 03 A	PTFE/ skrutkovitá pružina	0,1 m/s	(-60; 200)°C	800 400	
		O 01	PU NBR FPM	-	(-30; 105)°C (-20; 100)°C (-20; 210)°C	600 160 160	štand. tesnenie,
		OV 01	PU NBR FPM	-	(-30; 105)°C (-20; 100)°C (-20; 210)°C	600 160 160	
		OV 02	PU NBR FPM	-	(-30; 105)°C (-20; 100)°C (-20; 210)°C	600 160 160	
		X 01	PU NBR FPM	-	(-30; 105)°C (-20; 100)°C (-20; 210)°C	600 160 160	
		X 02	PU NBR FPM	-	(-30; 105)°C (-20; 100)°C (-20; 210)°C	600 160 160	