

SAMPLE PAGE, BOAT CARE EDITION

-- BOAT CARE EDITION --

**EDITOR'S PICK*

BOAT US Magazine, February-March 2018 Issue

- Technical advances for 2018 electronics, Pg. 36.
- New products to solve old problems: boat shoes, trailer mover, premixed gelcoat repair, pedal paddle-board, non-clogging multi-log, faux wood-grain plastic adhesive-backed wood cover, Pg. 40.
- Current improvements of marine outboard and inboard engines, Pg. 56.*
- Three outstanding boat rebuilds, Pg. 62.
- Do It Yourself: swim ladder-platform; dripless shaft seal replacement, repair leaking hatches, replace anode in water heater, Pg. 68.
- Exhaust manifold protection from saltwater, Pg. 86.

Boating Magazine, January 2018 Issue

- Fire safety issues, Pg. 8.
- Hybrid boating shorts, Pg. 12.
- Engine performance app for 2004 and later Mercury engines, Pg. 13.
- Magnetic compass compensation, Pg. 21.
- O-ring servicing, Pg. 21.
- Wiring through a fiberglass hardtop, Pg. 22.
- Fixing undrained accessory holders, Pg. 22.
- Fixing a leaky hatch, Pg. 22.
- Restraining fiddles for boat cabinet tops, Pg. 23.
- Boat beaching and bottom gel coat damage, Pg. 23.
- Protecting pontoons with MEGAWARE PONTOONGUARD, Pg. 23.
- Over-size storm anchor onboard storage, Pg. 23.
- Galley storage for 12 volt blender, Pg. 23.
- Use of "Turboswing" for improved water sports towing, Pg. 24.
- LED lights installation, Pg. 26.
- Marine LED lights, Pg. 28.
- Comparison of stainless steel vs aluminum boarding ladders, Pg. 30.
- Winter fuel storage additive, outboard engine oil, trailer LED light replacement kits, electrical circuit moisture protectant, PTFE one-step cleaner-wax, boat fabric guard, headlight lens and acrylic windshield/weather screen restoration, Pg. 34*.
- Review of new Volvo Penta 1000 hp+ diesel engine, Pg. 52.

SAMPLE PAGE, BOAT CARE EDITION

-- BOAT CARE EDITION --

**EDITOR'S PICK*

- Comments on newly updated Honda BF75, BF90 and BF100 outboards, Pg. 52.
- Inboards vs outboards, Pg. 56.
- Review Lowrance HOOK2 Sonar/Plotter series, Pg. 74.
- Review of Power Pole Vision multi-media tablet, Pg. 74.
- Comparison of radar and thermal imaging cameras, Pg. 74.

Boating Magazine, February 2018 Issue

- Winter storage outboard engine care, Pg. 22.
- Three brands of polarized sunglasses, Pg. 24.
- Four stroke engine oiln issues, Pg. 33.
- Cabin leak repair, Treating vinyl upholstery "pinking" stains, Pg. 34.
- Features of hull cleaning brush, Pg. 34.
- Thread seal tape recommendation, Pg. 34.
- Factors in gaining increased engine power, Pg. 34*.
- Debris removal from outboard cooling water intake system, Pg. 38.
- Improved deck shoes, Pg. 38.
- Installation of float-type bilge pump switch, Pg. 38.
- Recommendation for trailer loading-winch strap, Pg. 38.
- Transducer installation in a cored hull, Pg. 38.
- Repair a broken skeg, Pg. 40.
- Repainting of repaired skeg, Pg. 42.
- Improved deck tools, Pg. 50.
- Mercury inboard engine joystick piloting, Pg. 74.
- Report on Suzuki outboard DF9.9BEL, Pg. 74.
- Four onboard tests of the Yamaha new 90 HP F90B outboard, Pg. 79.
- Key features for boat insurance, Pg. 85.
- ICOM M605 VHF radio, Pg. 100.
- VHF ratchet-type antenna mounts, Pg. 100.
- How to access text and email service under way, Pg. 100.
- Features of the Garmin 4 display EchoMap depth finder, Pg. 102.

Chesapeake Bay Magazine, January-February 2018 Issue

- Content of this issue does not apply to Boat Care.

Cruising World, January 2018 Issue

- Exotic places boat repair, Pg. 1.
- Cabin lighting with LED's, Pg. 1.
- Spring sailboat hull refurbishing, Pg. 8*.
- Onboard emergency repair kit, Pg. 16.