


Always wear safety glasses, rubber gloves, and dust mask while handling, mixing and pouring. It is important to follow the directions in the Safety & User Guide to avoid potential of "Blow Outs" and ensure the best results. For larger scale projects, please contact your local dealer to determine suitability.

A "Blow Out" although highly unlikely, is when the product erupts from the filled hole at a high velocity and may cause injury. In order to avoid "Blow Out" take the following precautions:

1. Ensure drilled hole size **1.50" in diameter** (do not exceed 2.0" under any circumstances).
2. **Choose the correct Product Type** according to the rock or concrete's core temperature and ambient temperature, (use temperature chart to determine correct Product Type).



3. Use **cold** clean common water.
4. Fill holes within 10 minutes of mixing.
5. Mix the ratio of **1.5L of water per 5Kg (11Lb) of product**.
6. Keep product **out of direct sunlight** and cover with a tarp.
7. Contact your local dealer with any questions.

### PRECAUTIONS:

- \* Make sure everyone working with the product understands the possibility of blow-outs, and has read both the Safety and User Guide.
- \* Wear safety equipment.
- \* Do not look into filled holes or stand over them at any time.
- \* Do not leave excess product in the bucket.
- \* Cover holes with a tarp once filled.
- \* Stay out of the area where holes have been filled for 7 hours.
- \* When mixing, if product begins to steam in the bucket, add water to dilute it.
- \* Avoid contact with eyes or skin. If this happens, rinse off with cold water and consult your physician.

**Environmentally Friendly Non Explosive**  
**No Noise or Vibrations No Flying Rocks**