



The original PTO shaft for this model winch is no longer available. For details on replacement shaft, [click here](#).

#39 x (4)



Internally, these winches are essentially the same. The JL50 is shown to your right.

JL456 & JL50