PUBLIC WORKS DEPARTMENT, HARYANA (Buildings and Roads Branch)

To

The Executive Engineer, Provl. Division No. II, PWD B&R Br., Sirsa.

Memo No. 58

Dated 04-07-19

Şub:

Structural Safety Certificate of building St. Francis Xavier School situated at behind Beej Vikas Nigam, Village Khairpur, Hisar road in Sirsa Distt.

Ref:

Your office letter Ednst. No. 5049 dated 30.11.2018

In this connection it is intimated that the above building was inspected with incharge J.E. and on visual inspection the building seens to be safe.

This is for your kind information and necessary action please.

DA/Nil- as above

Sub Divisional Engineer, Provincial Sub Division No-1,

Hisa: Rchio, Sirsa-125055

PWD B&R Br., Sirsa.

Manager
St. Francis Xavier's
St. Francis (Hry.)
School, Sirsa (Hry.)

B.B. CERA.BE (CIVII ENGG), F.I.V.

Chartered Engineer & Approved Valuer, Fellow Of The Institution Of Valuers-India Surveyor & Loss Assessor, FIRE, ENGG & MOTOR, SLA-72876, Validity-Sep 26,2022.

Office Gali Masjid Wali, Near Chawla Attachi House, Sadar Bazar, Sirsa Mob.09996711450

REF NO SIRSA/BBG/C/2021

DATED: 28.06.2021

TO WHOM IT MAY CONCERN

IT IS CERTIFIED THAT THE BUILDING OF THE ST.FRANCIS XAVIER'S SECONDARY SCHOOL-SIRSA & DISTT. SIRSA (RUN BY THE ST. FRANCIS XAVIER'S EDUCATION SOCIETY SIRSA & DISTRICT SIRSA) SITUATED IN SIRSA & DISTRICT SIRSA HAS BEEN CONSTRUCTED WITH FIRST CLASS BRICKS AND CEMENT MORTAR THE ROOFS OF THE ROOMS ARE OF R.C.C. SLABS.THE FLOORS ARE OF PLAIN CEMENT CONCRETE & TILES & THE DOORS AND WINDOWS ARE OF HIGH CLASS SHISHAM WOOD .THE BUILDING PLAN IS AS PER ACTUAL AT SITE.

THE BUILDING IS WELL VENTILATED, AIRY, GOOD AND FIT FOR HUMAN LIVING. THE STRUCTURE OF THE BUILDING IS SAFE AND SOUND.

STRUCTURAL ENGINEER REGISTERED WITH HARYANA URBAN DEVELOPMENT AUTHORITY REGISTRATION NO 127 & THE INSTITUTION OF ENGINEERS (INDIA) REGISTRATION NO AM-075691/4 (LIFE MEMBER)

St. Francis Xavier's Secondary School Hisar Road, SIRSA-125055 (Hry.)

St. Francis Xavier's Secondary Schoo