40 Shattuck Road | Suite 110
Andover, Massachusetts 01810
www.woodardcurran.com

T 800.426.4262
T 978.557.8150
F 978.557.7948

MEMORANDUM

TO: Stephanie Carlisle, Stormwater Compliance Coordinator – Town of Medway
Pete Pelletier, Director of Public Works – Town of Medway
Nolan Lynch, Deputy Director – Town of Medway

FROM: Garrett Bergey, Project Manager – Woodard & Curran
Emily Nealon, Project Engineer – Woodard & Curran

DATE: March 14, 2025

RE: MS4 General Permit Compliance Illicit Discharge Detection and Elimination Program
Permit Year 7 Catchment Investigation Summary

EXECUTIVE SUMMARY

Between November 2024 and January 2025, drainage infrastructure within 16 catchments were inspected during dry weather conditions for evidence of non-stormwater discharges. Of the 16 catchments investigated, 12 catchments were completed, and four catchments were partially completed, requiring further investigation in future Municipal Separate Storm Sewer System (MS4) Permit Years.

No dry weather flow samples collected during this round of catchment investigations contained concentrations of all three criteria (ammonia, surfactants, and chlorine) above MS4 General Permit (Permit) potential illicit discharge threshold criteria. Drainage infrastructure within the 16 investigated catchments either contained no dry weather flow, or concentrations of illicit discharge parameters (ammonia, chlorine, and/or surfactants) detected in flow were below combined Permit threshold criteria. These detections do not require additional investigation under the current Permit requirements.

Catchment investigation prioritizations have been updated based on the information provided in this memorandum.

PURPOSE AND BACKGROUND

This memorandum describes the results of illicit discharge detection and elimination (IDDE) investigations performed in the Town of Medway, MA (Town) during Permit Year (PY) 7 within 16 catchments. This memorandum is intended to fulfill Permit Part 2.3.4.8.c.iii, which requires all data collected as part of catchment investigations to be recorded and reported annually.

Dry weather outfall screening and sampling results obtained for the Town's 507 outfalls screened during previous IDDE investigations were initially used to prioritize the order of catchment investigations. Catchments where potential illicit discharge indicators were detected above individual Permit threshold criteria in dry weather flow collected from outfalls were assigned an elevated prioritization for future investigation. Based on this method, 188 catchments were originally assigned as high priority for investigation. The remaining catchments were assigned a low priority for investigation due to no observed dry weather flow or no detections of potential

illicit discharge parameters in sampled flow. Eleven of the 188 original high priority catchments were completed in PY6, leaving 177 high priority catchments for investigation at the start of PY7.

Drainage infrastructure within the catchments that discharge to the following 16 outfalls was investigated during PY7:

- OF 12-9
- OF 12-12
- OF 16-2
- OF 22-15
- OF 23-1
- OF 23-3
- OF 30-1
- OF 35-5
- OF 44-6
- OF 45-7
- OF 48-10
- OF 50-1
- OF 50-3
- OF 55-4
- OF 6-7
- OF 67-9

IDDE INVESTIGATION METHODOLOGY

Between November 2024 and January 2025, Woodard & Curran's subcontractor, SDE, Inc. (SDE) conducted catchment investigations following the methodology in Permit Part 2.3.4.8.c.ii.1.c-d (Catchment Investigations) and the Town's IDDE Program Manual.

Drain manholes, and in some cases, catch basins were opened and visually inspected to determine the presence or absence of dry weather flow and visible and/or olfactory indicators of sewage. Where flow was observed, samples were collected and screened for potential illicit discharge indicators using field test kits. General observations related to the infrastructure condition were recorded when structures were accessed.

In general, drainage infrastructure was investigated throughout the drainage network starting upstream and working toward the outfall to determine the effect of upstream contamination on downstream water quality. There were no instances where field test kits detected concentrations of potential illicit discharge parameters above Permit threshold criteria in dry weather flow. Where concentrations of ammonia, chlorine, and/or surfactants were detected, the results did not meet likely sewer indicator parameter as defined by the current Permit, therefore the detections do not require additional investigations. The permit criteria and PY7 results are described in more detail in this document.

Information obtained during catchment investigation activities was recorded in ESRI's ArcGIS Field Maps application. This information is available in the Town's geographic information system (GIS).

DRY WEATHER SCREENING DATA EVALUATION CRITERIA

Permit Part 2.3.4.8.c.ii.1.c-d requires drainage infrastructure investigations during dry weather conditions. Where dry weather flow is present, it is typically sampled using field test kits for the presence of ammonia, surfactants, and chlorine. In some cases, dry weather flow is sampled for bacteria; however, this is not required during catchment investigations and no bacteria samples were collected during the catchment investigations described in this memorandum.

The Permit considers dry weather flow collected from MS4 screening locations that exceed the following threshold criteria as a potential indication of sewer contribution to drainage infrastructure:

- Olfactory or visual evidence of sewage; or
- Ammonia ≥0.5 milligrams per liter (mg/L), surfactants ≥0.25 mg/L, and bacteria ≥ water quality standards; or
- Ammonia ≥0.5 mg/L, surfactants ≥0.25 mg/L, and detectable chlorine.

Dry weather sample screening results obtained during catchment infrastructure investigations were compared against these criteria to determine the potential presence of illicit discharges.

In addition, test kit results where ammonia, surfactants and/or chlorine are detected above their individual Permit threshold criteria but below the combined Permit criteria for potential illicit discharges associated with likely sewer indicators can be potential indicators of other illicit discharges, such as swimming pool dewatering discharges, vehicle/equipment wash waters, incorrectly connected washing machine laterals, or diluted flow from sewer-related sources.

These types of potential illicit discharge indicators are not typically regulatory drivers for additional investigations, but investigations may be warranted depending on a variety of factors such as the proximity of the corresponding drainage pipe(s) to identified potential illicit discharges, the location of the catchment's outfall in relation to sensitive receptors, and other community-specific factors. This data and the infrastructure should be reviewed on a case-by-case basis to determine whether non-Permit drivers are present that would warrant further investigation.

CATCHMENT INVESTIGATION RESULTS

An evaluation of the dry weather flow screening did not identify any suspected sewer-related illicit discharges to drainage infrastructure based on the likely sewer indicator thresholds. However, sampled dry weather flow in 11 of the 16 investigated catchments had concentrations of one or more illicit discharge indicator parameters above individual Permit threshold criteria but below the combined Permit threshold criteria for potential illicit discharges. Because these catchments are below the combined Permit threshold criteria, they do not require further investigation. The figures in **Attachment A** show the investigation status for each investigated pipe. A summary of the drainage system infrastructure investigation findings is provided in **Table 1** below.

Note that "complete" drainage system infrastructure investigation statuses refer to investigation of the Town-owned drainage infrastructure located within the system and not the confirmation of location and removal of illicit discharges that may be present in sanitary sewer or private infrastructure discharging to the MS4.

TABLE 1: COMPLETED CATCHMENTS WITH NO POTENTIAL ILLICITS DETECTED

Substantially Investigated- No Potential Illicit Discharges Detected	
OF-12-9	OF-35-5
OF-23-1	OF-50-1
Substantially Investigated- Potential Illicit Discharge Parameter(s) Detected Below Permit Threshold Criteria	
OF-12-12	OF-44-6
OF-22-15	OF-50-3
OF-23-3	OF-55-4
OF-30-1	OF-6-7
Require Additional Investigation- No Potential Illicit Discharges Detected	
OF-16-2	
Require Additional Investigation- Potential Illicit Discharge Parameter(s) Detected Below Permit Threshold Criteria	
OF-45-7	OF-67-9
OF-48-10	

A table summarizing screening results obtained during catchment investigations is provided in **Attachment B**, and tables summarizing surficial drainage infrastructure and outfall condition observations noted during catchment investigations are provided in **Attachment C** and **Attachment D**, respectively.

CONCLUSIONS AND RECOMMENDATIONS

Catchments with No Potential Illicit Discharges Detected

As shown in **Table 1** above, drainage infrastructure has been substantially investigated in four catchments with no potential illicit discharges or positive test kit detections. No further investigation is necessary within these catchments.

Partial drainage infrastructure investigations have been conducted in one catchment (OF-16-2) with no potential illicit discharges identified. Further investigation will continue in this catchment during future field efforts.

Catchments with Potential Illicit Discharge Parameter(s) Detected Below Permit Threshold Criteria

Dry weather flow sampled from drainage infrastructure in 11 catchments listed in **Table 1** above contained concentrations of one or more illicit discharge indicator parameters above Permit threshold criteria, making them "potential" illicit discharge detections. However, none of the catchments investigated contained exceedances on all three Permit threshold criteria, therefore no entries are listed as "suspected" illicit discharges.

Eight of these 11 catchments have been substantially investigated and do not require any further investigations. Although these detections do not require additional catchment investigation under the Permit, the Town may consider investigating these locations in the future once

investigations are completed in higher priority catchments. In some cases, detection of individual illicit discharge criteria can indicate a diluted source of an illicit discharge in the vicinity.

Three of the 11 catchments with illicit discharge parameters detected below permit threshold criteria require further investigations before considering the catchment to be substantially completed. Further investigation will continue in these catchments during future field efforts.

Maintenance and Mapping Recommendations


Standing water was observed in pipe segments within a few catchments, as depicted on figures in **Attachment A** and the notes recorded in the summary tables in **Attachment C** and **Attachment D**. Locations where standing water has been identified should be maintained and/or evaluated to determine and abate the cause to promote adequate drainage through the catchment. After maintenance has been completed, these catchments should be revisited to attempt to complete catchment investigations.

There are 383 drainage features in the Town's GIS dataset with duplicate asset ID's. This includes 292 catch basins that share asset ID's representing a total of 584 unique catch basins and 91 manholes representing a total of 182 unique manholes. These locations are recorded in **Attachment E**. The Town's GIS should be updated so that each drainage feature has a unique ID.

There are also a number of pipes that are mapped as extending beyond a single manhole (or catch basin) to manhole run instead. These pipes appear to extend between three or more structures instead of having a discrete pipe for every pipe segment. Of the 54 pipes inspected during this round of investigations, 11 of the pipes had this situation. These 11 pipes are displayed in **Attachment B** and can be identified by the locations with duplicate Pipe ID's but distinct Infrastructure ID's. The pipe mapping should be updated so that each pipe segment (manhole to manhole, manhole to catch basin, catch basin to catch basin, etc.) has a unique pipe ID.

Additionally, drainage infrastructure within some catchments appears to be incompletely mapped, as noted in **Attachment C**. These catchments may require further investigation if new structures are identified that were not inspected during the investigations summarized in this memorandum.

ATTACHMENT A: CATCHMENT INVESTIGATION FIGURES



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-12-9

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

0 75 150 300 Feet


N

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA Stormwater\Medway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-12-12

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

0 75 150 300 Feet


N

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA Stormwater\Medway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-16-2

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

N


0 75 150 300 Feet

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA StormWater\Medway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-22-15

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

0 75 150 300 Feet


N

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA StormwaterMedway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-23-1

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

N


0 75 150 300 Feet

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA Stormwater\Medway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-23-3

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

N


0 75 150 300 Feet

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA StormwaterMedway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4
IDDE INVESTIGATIONS
CATCHMENT OF-30-1
Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

N


0 75 150 300 Feet

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA StormWaterMedway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-35-5

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

0 75 150 300 Feet


N

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA StormwaterMedway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-44-6

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

N


0 75 150 300 Feet

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA StormwaterMedway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-45-7

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

0 75 150 300 Feet


N

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA StormwaterMedway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-48-10

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

0 75 150 300 Feet


N

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA StormWaterMedway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-50-1

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

0 75 150 300 Feet


N

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA StormwaterMedway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-50-3

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

N

0 75 150 300 Feet


Woodard & Curran

Project #: 0234166.08

Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA StormwaterMedway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-55-4

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

N


0 75 150 300 Feet

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA StormwaterMedway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-6-7

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

0 75 150 300 Feet


N

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA StormwaterMedway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**



FY25 MS4 IDDE INVESTIGATIONS

CATCHMENT OF-67-9

Town of Medway, MA

Legend

Pipes by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Partial Inspection
- Standing Water
- Not Yet Inspected

Outfalls by Illicit Discharge Status
- Visual/Olfactory Evidence of Illicit Discharge
- Suspected Illicit Discharge
- Positive Detection
- Cleared
- Standing Water/Submerged
- Partial Inspection
- Not Inspected

Catch Basins by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

Manholes by Inspection Status
- Yes, Completed
- Not Completed, Could Not Locate
- Not Completed, Unsafe Conditions
- Not Completed, Inaccessible
- Not Yet Inspected

N

0 75 150 300 Feet

Woodard & Curran

Project #: 0234166.08
Map Created: February 2025

Figure Exported: 3/4/2025 By: poregan Using: \\woodardcurran.net\shared\Projects\0234166.12 Medway MA FY25 MS4 Support\wip\GIS\Project\Medway, MA StormwaterMedway, MA Stormwater.aprx Layout: Standard_8.5x11_P_Bottom

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**

ATTACHMENT B: CATCHMENT INVESTIGATION SCREENING RESULTS

Attachment B: Catchment Investigation Screening Results

MS4 General Permit IDDE Program

Permit Year 7 Catchment Investigation Summaries

Medway, MA

Infrastructure ID	Inspection Date	Pipe ID	Flow	Flow Color	Velocity	Ammonia	Surfactants	Chlorine	Comments
OF-12-9									
MH-1092	1/9/2025	SWP-707	No Flow Visible	N/A	--	--	--	--	This includes OF-12-12 & OF-12-9
OF-12-9	1/9/2025	SWP-706	No Flow Visible	N/A	--	--	--	--	
MH-236	1/9/2025	SWP-705	No Flow Visible	N/A	--	--	--	--	This catchment includes OF-12-12 and OF-12-9.
MH-1092	1/9/2025	SWP-706	No Flow Visible	N/A	--	--	--	--	
MH-236	1/9/2025	SWP-705	No Flow Visible	N/A	--	--	--	--	This catchment includes OF-12-12 and OF-12-9.
OF-16-2									
MH-609	1/9/2025	SWP-303	No Flow Visible	N/A	--	--	--	--	
MH-609	1/9/2025	SWP-303	No Flow Visible	N/A	--	--	--	--	
OF-22-15									
OF-22-15	1/7/2025	SWP-1733	Flow Visible	Colorless	Medium 0.5-1.75 ft/sec	0	0	**0.20**	
OF-23-1									
OF-23-1	1/9/2025	SWP-185	No Flow Visible	N/A	--	--	--	--	
OF-23-3									
OF-23-3	1/14/2025	SWP-183	Flow Visible	Colorless	Medium 0.5-1.75 ft/sec	0.10	**0.25**	**0.10**	
MH-882	1/14/2025	SWP-597	Flow Visible	Colorless	Medium 0.5-1.75 ft/sec	0	**0.5**	**0.43**	
MH-882	1/16/2025	SWP-862	No Flow Visible	N/A	--	--	--	--	
MH-882	1/16/2025	SWP-598	No Flow Visible	N/A	--	--	--	--	
MH-629	1/14/2025	SWP-178	Flow Visible	Colorless	Slow 0-0.5 ft/sec	0	**0.25**	**0.20**	
OF-30-1									
MH-718	1/9/2025	SWP-916	No Flow Visible	N/A	--	--	--	--	
OF-30-1	11/25/2024	SWP-916	Flow Visible	Colorless	Slow 0-0.5 ft/sec	0	**0.25**	**0.28**	
MH-718	11/25/2024	SWP-918	Flow Visible	Colorless	Slow 0-0.5 ft/sec	0	**0.25**	**0.28**	
MH-718	1/9/2025	SWP-917	No Flow Visible	N/A	--	--	--	--	
OF-35-5									
OF-35-5	1/9/2025	SWP-1032	No Flow Visible	N/A	--	--	--	--	
MH-68	1/9/2025	SWP-1032	No Flow Visible	N/A	--	--	--	--	
MH-68	1/9/2025	SWP-1033	No Flow Visible	N/A	--	--	--	--	
MH-68	1/7/2025	SDE_CB_1:MH-68	No Flow Visible	N/A	--	--	--	--	
OF-44-6									
OF-44-6	1/9/2025	SWP-1133	No Flow Visible	N/A	--	--	--	--	
OF-45-7									
OF-45-7	1/7/2025	SWP-1038	Standing Water	N/A	--	--	--	--	
OF-45-7	1/7/2025	SWP-1038	Standing Water	N/A	--	--	--	--	

Attachment B: Catchment Investigation Screening Results
MS4 General Permit IDDE Program
Permit Year 7 Catchment Investigation Summaries
Medway, MA

Infrastructure ID	Inspection Date	Pipe ID	Flow	Flow Color	Velocity	Ammonia	Surfactants	Chlorine	Comments
MH-1208	1/9/2025	SWP-1038	No Flow Visible	N/A	--	--	--	--	Re investigated Outfall per W&C request, Outfall was partially submerged. Investigated upstream manhole, line that was previous flowing was observed dry and sandbag was placed. Investigation continued
OF-48-10									
OF-48-10	1/14/2025	SWP-431	Flow Visible	Colorless	Slow 0-0.5 ft/sec	--	--	--	Insufficient flow to collect a test kit. Recommend to return to warmer weather to sandbag. Sandbag would like freeze in current temperatures.
MH-298	1/14/2025	SWP-431	Flow Visible	Colorless	Slow 0-0.5 ft/sec	0	**0.25**	0	
OF-50-1									
MH-529	1/16/2025	SWP-1364	No Flow Visible	N/A	--	--	--	--	
MH-563	1/16/2025	SWP-1361	No Flow Visible	N/A	--	--	--	--	
MH-563	1/16/2025	SWP-1359	No Flow Visible	N/A	--	--	--	--	
MH-571	1/16/2025	SWP-1358	No Flow Visible	N/A	--	--	--	--	
MH-571	1/16/2025	SWP-544	No Flow Visible	N/A	--	--	--	--	
MH-575	1/16/2025	SWP-1355	No Flow Visible	N/A	--	--	--	--	
OF-50-1	1/16/2025	SWP-1221	No Flow Visible	N/A	--	--	--	--	
OF-50-3									
CB-901	1/14/2025	SWP-2176	Standing Water	N/A	--	--	--	--	
CB-901	1/16/2025	SWP_2147	No Flow Visible	N/A	--	--	--	--	
MH-1468	1/16/2025	SWP-1660	No Flow Visible	N/A	--	--	--	--	
MH-1468	1/16/2025	SWP-1660	No Flow Visible	N/A	--	--	--	--	
MH-1468	1/16/2025	SDE_UNK:MH1468	No Flow Visible	N/A	--	--	--	--	
SMH-1711	1/16/2025	SWP-2174	No Flow Visible	N/A	--	--	--	--	
SMH-1711	1/16/2025	SWP-2174	No Flow Visible	N/A	--	--	--	--	
CB-885	1/16/2025	SWP-2282	No Flow Visible	N/A	--	--	--	--	Confirmed with DPW that this pipe connects to CB-3730 via CCTV footage.
OF-55-4									
MH-73	1/9/2025	SWP-1248	No Flow Visible	N/A	--	--	--	--	
OF-55-4	11/25/2024	SWP-1248	Flow Visible	Colorless	Slow 0-0.5 ft/sec	0	**0.50**	**0.23**	

Attachment B: Catchment Investigation Screening Results

MS4 General Permit IDDE Program

Permit Year 7 Catchment Investigation Summaries

Medway, MA

Infrastructure ID	Inspection Date	Pipe ID	Flow	Flow Color	Velocity	Ammonia	Surfactants	Chlorine	Comments
OF-6-7									
OF-6-7	11/25/2024	SWP-659	Flow Visible	Colorless	Medium 0.5-1.75 ft/sec	0	**1**	**0.30**	
OF-67-9									
MH-1008	1/16/2025	SWP-464	Unknown	Unknown	Unknown	--	--	--	Unable to complete inspection due to manhole not being located. Ground is frozen.
MH-1008	1/16/2025	SWP-462	Unknown	Unknown	Unknown	--	--	--	Unable to complete inspection due to manhole not being located. Ground is frozen.
MH-1009	1/16/2025	SWP-462	No Flow Visible	N/A	--	--	--	--	Investigated during last day of catchment investigations. Pipe was observed dry and will need to be returned to be bagged
MH-1010	1/16/2025	SWP-466	Flow Visible	Colorless	Medium 0.5-1.75 ft/sec	0	0	**0.14**	
MH-310	1/16/2025	SWP-468	Flow Visible	Colorless	Medium 0.5-1.75 ft/sec	0.10	0	**0.03**	
OF-67-9	1/16/2025	SWP-462	Flow Visible	Colorless	Medium 0.5-1.75 ft/sec	0	**0.25**	0	
MH-1008	1/16/2025	SWP-463	Unknown	Unknown	Unknown	--	--	--	Could not locate manhole.

ATTACHMENT C: SURFICIAL DRAINAGE INFRASTRUCTURE CONDITIONS – CATCH BASINS AND MANHOLES

Attachment C: Surficial Drainage Infrastructure Conditions - Catch Basins and Manholes

MS4 General Permit IDDE Program

Permit Year 7 Catchment Investigation Summaries

Medway, MA

Infrastructure ID	Inspection Date	Street	Asset Type	Cover Condition	Frame Condition	Pavement Condition	Corbel Condition	Corbel Material	Wall Material	Floor Condition	Comments
OF-12-9											
MH-236	1/7/2025	Stable Way	Drainage Manhole	Good	Good	N/A	Good	Concrete Precast	Concrete Precast	Good	Manhole is part of catchments for both OF-129 and OF-12-12.
MH-1092	1/7/2025	Stable Way	Drainage Manhole	Good	Good	N/A	Good	Concrete Precast	Concrete Precast	Good	
OF-12-12											
MH-1092	11/25/2024	Stable Way	Drainage Manhole	Good	Good	N/A	Good	Concrete Precast	Concrete Precast	Good	Confirmed both outlets in manhole leading to OF-12-12 and OF-12-9 respectively.
OF-16-2											
MH-609	1/7/2025	Broken Tree Rd	Drainage Manhole	Good	Good	N/A	Good	Brick	Brick	Good	Potential infiltration coming from under main pipe. Test kit is A: 0 C:0.12 S:0.25 PH: 7.09 T:4.4 Con:261 Sal:0.1
MH-608	1/9/2025	Broken Tree Rd	Drainage Manhole	Unknown	Unknown	Unknown	Unknown	Unknown	Unknown	Unknown	Could not locate. Might be buried. Ground was frozen.
OF-23-3											
MH-629	1/14/2025	Greenvalley Rd	Drainage Manhole	Good	Good	N/A	Fair	Stone	Concrete Block	Not Visible	
MH-882	1/14/2025	Greenvalley Rd	Drainage Manhole	Good	Good	N/A	Good	Brick	Concrete Block	Good	
OF-30-1											
MH-718	11/25/2024	Delmar Rd	Drainage Manhole	Good	Good	Good	Good	Concrete Block	Concrete Block	Good	
OF-35-5											
MH-68	1/7/2025	Deerfield Rd	Drainage Manhole	Good	Good	Good	Good	Concrete Block	Brick	Not Visible	
OF-45-7											
MH-1208	1/7/2025	Fisher St	Drainage Manhole	Good	Good	Good	Good	Brick	Concrete Block	Not Visible	Returned to reinvestigate submerged outfall. Outfall is still partially submerged. N and NW pipes still have slow flow but NE line is dry.
OF-48-10											
MH-298	1/14/2025	Evergreen St	Drainage Manhole	Good	Good	Good	Good	Brick	Brick	Not Visible	
OF-50-1											
MH-529	1/14/2025	Cassidy Ln	Drainage Manhole	Good	Good	Good	Good	Brick	Brick	Good	
MH-563	1/14/2025	Holliston St	Drainage Manhole	Good	Good	Good	Good	Brick	Concrete Block	Not Visible	
MH-571	1/14/2025	North St	Drainage Manhole	Good	Good	Good	Good	Concrete Block	Concrete Block	Good	
MH-575	1/14/2025	Broad St	Drainage Manhole	Good	Fair	Good	Good	Brick	Concrete Block	Good	
OF-50-3											
MH-1468	1/14/2025	Mustang Dr	Drainage Manhole	Good	Good	N/A	Good	Brick	Concrete Cast in Place	Not Visible	
MH-1711	1/14/2025	Holliston St	Drainage Manhole	Good	Good	N/A	Good	Brick	Brick	Good	Manhole located further down than GIS has mapped.
CB-901	1/14/2025	Mustang Dr	Catch Basin	Good	Good	Good	Good	Brick	Brick	Not Visible	
CB-712	1/14/2025	Kelley St	Catch Basin	Good	Good	Good	Good	Brick	Brick	Not Visible	No unmapped inlets.
CB-885	1/14/2025	Holliston St	Catch Basin	Good	Good	Good	Good	Brick	Brick	Not Visible	
OF-55-4											
MH-73	1/7/2025	Holbrook St	Drainage Manhole	Good	Good	Good	N/A	N/A	Concrete Precast	Good	
OF-67-9											
MH-1008	1/16/2025	Waterview Dr	Drainage Manhole	Unknown	Unknown	Unknown	Unknown	Unknown	Unknown	Unknown	Could not locate manhole. Possibly burried. Ground is froze. Return to key junction when warmer. Continued investigations upstream for now.
MH-1010	1/16/2025	Waterview Dr	Drainage Manhole	Good	Good	N/A	Good	Brick	Concrete Precast	Good	
MH-310	1/16/2025	Waterview Dr	Drainage Manhole	Good	Good	N/A	Good	Brick	Concrete Precast	Good	

Attachment C: Surficial Drainage Infrastructure Conditions - Catch Basins and Manholes

MS4 General Permit IDDE Program

Permit Year 7 Catchment Investigation Summaries

Medway, MA

Infrastructure ID	Inspection Date	Street	Asset Type	Cover Condition	Frame Condition	Pavement Condition	Corbel Condition	Corbel Material	Wall Material	Floor Condition	Comments
MH-1009	1/16/2025	Waterview Dr	Drainage Manhole	Good	Good	N/A	Good	Brick	Concrete Precast	Good	Investigated during last day of catchment investigations. Pipe was observed dry and will need to be returned to be bagged.

ATTACHMENT D: SURFICIAL DRAINAGE INFRASTRUCTURE CONDITIONS – OUTFALLS

Attachment D: Surficial Drainage Infrastructure Conditions - Outfalls

MS4 General Permit IDDE Program

Permit Year 7 Catchment Investigation Summaries

Medway, MA

Infrastructure ID	Inspection Date	Street	Structure Diameter (in)	Structure Material	Structure Shape	Structure Condition	Condition Details	Contamination Status	Comments
OF-12-9	1/9/2025	Stable Way	12	Reinforced Concrete	Circular	Good	--	Cleared No Evidence	Returned to confirm mapping and outfall was observed dry during reinvestigation.
OF-22-15	1/7/2025	Holliston St	12	Reinforced Concrete	Circular	Good	--	Positive Test Kit Chlorine Only	Multiple outfalls in location. The one sampled sound tested to MH-784 confirming connectivity.
OF-23-1	1/9/2025	Greenvalley Rd	12	Polyvinvyl Chloride	Circular	Good	--	Cleared No Evidence	
OF-23-3	1/14/2025	Greenvalley Rd	24	Reinforced Concrete	Circular	Good	--	Positive Test Kit During Inspection	
OF-30-1	11/25/2024	Delmar Rd	12	Concrete	Circular	Good	--	Positive Test Kit During Inspection	
OF-35-5	1/9/2025	Deerfield Rd	12	Reinforced Concrete	Circular	Good	--	Cleared No Evidence	
OF-44-6	1/9/2025	Milford St	12	Reinforced Concrete	Circular	Good	--	Cleared No Evidence	
OF-48-10	1/14/2025	Evergreen St	12	Reinforced Concrete	Parabolic	Good	--	Partial Inspection	Outfall had insufficient flow. Unable to sandbag due to freezing temps likely going to cause flow and bags to freeze. Should return to outfall during warmer temps. Continued upstream.
OF-50-1	1/16/2025	Broad St	12	Reinforced Concrete	Circular	Poor	Cracking or Chipping	Cleared No Evidence	Two outfall located in area and only one mapped. Sandbagged the one that sound tested as connected to MH-578. Outfall was broken in half.
OF-55-4	11/25/2024	Holbrook St	12	Concrete	Circular	Good	--	Positive Test Kit During Inspection	
OF-6-7	11/25/2024	Whitney Rd	24	Reinforced Concrete	Circular	Good	--	Positive Test Kit During Inspection	
OF-67-9	1/16/2025	Waterview Dr	12	Reinforced Concrete	Circular	Good	--	Positive Test Kit During Inspection	

ATTACHMENT E: DRAINAGE FEATURES WITH DUPLICATE ASSET ID'S

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
1160	CB-923	Burke Elementary 6	42.14084	-71.40905		8-Jun-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2864	CB-923	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/19/2023	MedwayMA
1159	CB-922	Burke Elementary 16	42.14085	-71.4093		8-Jun-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2863	CB-922	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/19/2023	MedwayMA
1158	CB-921	Burke Elementary 15	42.1407	-71.4094		8-Jun-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2866	CB-921	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/19/2023	MedwayMA
1157	CB-920	Burke Elementary 14	42.14076	-71.40942		8-Jun-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2865	CB-920	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/19/2023	MedwayMA
1155	CB-919	Burke Elementary 13	42.14135	-71.4094		8-Jun-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2862	CB-919	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/19/2023	MedwayMA
1154	CB-918	Burke Elementary 12	42.14135	-71.40705		8-Jun-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2715	CB-918	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
1153	CB-917	Burke Elementary 11	42.14134	-71.40719		8-Jun-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2714	CB-917	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
1150	CB-913	Burke Elementary 7	42.14164	-71.40724		8-Jun-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2713	CB-913	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
1149	CB-912	Cassidy 9	42.14174	-71.40678		8-Jun-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2711	CB-912	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
1148	CB-911	Cassidy 8	42.1418	-71.40677		8-Jun-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2710	CB-911	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
1145	CB-909	Burke Elementary 3	42.14288	-71.40709		8-Jun-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2722	CB-909	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
1144	CB-908	Burke Elementary 2	42.14292	-71.40681		8-Jun-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2721	CB-908	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
1142	CB-906	MMS 8	42.14672	-71.40688		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2826	CB-906	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
1141	CB-905	MMS 7	42.14647	-71.40846		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2790	CB-905	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
1140	CB-902	MMS 4	42.14596	-71.4083		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2787	CB-902	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
1139	CB-901	MMS 3	42.14601	-71.40604		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2724	CB-901	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
1138	CB-900	MMS 2	42.14594	-71.40596		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2723	CB-900	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
1121	CB-886	Holliston 19	42.14915	-71.40845		8-Jun-17	Aerial Photo	Student	Town	Holliston	40-8	8/20/2021	UtilityCloud1
2815	CB-886	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
1120	CB-885	Holliston 18	42.14819	-71.40817		8-Jun-17	Aerial Photo	Student	Town	Holliston	40-8	8/20/2021	UtilityCloud1
2791	CB-885	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
1119	CB-884	Holliston 17	42.14709	-71.40719		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2824	CB-884	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
1118	CB-883	Holliston 16	42.14695	-71.40703		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2825	CB-883	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
1117	CB-882	Holliston 15	42.14678	-71.40686		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2827	CB-882	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
1116	CB-881	Holliston 14	42.14596	-71.40585		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-1	8/20/2021	UtilityCloud1
2725	CB-881	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
1115	CB-880	Holliston 13	42.14592	-71.40566		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-1	8/20/2021	UtilityCloud1
2830	CB-880	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1113	CB-879	Holliston 12	42.14489	-71.40459		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2835	CB-879	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1112	CB-878	Holliston 11	42.14454	-71.40403		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2837	CB-878	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1111	CB-877	Holliston 10	42.14449	-71.4041		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2836	CB-877	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1110	CB-876	Holliston 9	42.14428	-71.40387		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2694	CB-876	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
1109	CB-875	Holliston 8	42.14416	-71.40369		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2695	CB-875	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
1108	CB-874	Holliston 7	42.14375	-71.4032		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2839	CB-874	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1107	CB-873	Holliston 6	42.1438	-71.40312		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2838	CB-873	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1106	CB-872	Holliston 5	42.14278	-71.40197		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2840	CB-872	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1105	CB-871	Holliston 4	42.14274	-71.4019		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2841	CB-871	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1104	CB-870	Holliston 3	42.14277	-71.40182		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-4	8/20/2021	UtilityCloud1
2842	CB-870	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1102	CB-869	Holliston 2	42.1418	-71.40058		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-1	8/20/2021	UtilityCloud1
2846	CB-869	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1101	CB-868	Holliston 1	42.14173	-71.40067		8-Jun-17	Aerial Photo	Student	Town	Holliston	50-1	8/20/2021	UtilityCloud1
2845	CB-868	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1083	CB-851	Village 39	42.14026	-71.4239		8-Jun-17	Aerial Photo	Student	Town	Village	58-10	8/20/2021	UtilityCloud1
2930	CB-851	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1082	CB-850	Village 38	42.14034	-71.42388		8-Jun-17	Aerial Photo	Student	Town	Village	58-10	8/20/2021	UtilityCloud1
2929	CB-850	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1080	CB-849	Village 37	42.14016	-71.423		7-Jun-17	Aerial Photo	Student	Town	Village	58-7	8/20/2021	UtilityCloud1
2928	CB-849	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1079	CB-848	Village 36	42.14024	-71.42309		7-Jun-17	Aerial Photo	Student	Town	Village	58-7	8/20/2021	UtilityCloud1
2927	CB-848	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1078	CB-847	Village 35	42.14037	-71.42058		7-Jun-17	Aerial Photo	Student	Town	Village	58-4	8/20/2021	UtilityCloud1
2926	CB-847	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1077	CB-846	Village 34	42.14026	-71.42015		7-Jun-17	Aerial Photo	Student	Town	Village	58-4	8/20/2021	UtilityCloud1
2925	CB-846	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
1076	CB-845	Village 33	42.14033	-71.42015		7-Jun-17	Aerial Photo	Student	Town	Village	58-4	8/20/2021	UtilityCloud1
2924	CB-845	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1075	CB-844	Village 32	42.14027	-71.41961		7-Jun-17	Aerial Photo	Student	Town	Village	58-4	8/20/2021	UtilityCloud1
2923	CB-844	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1074	CB-843	Village 31	42.14022	-71.41925		7-Jun-17	Aerial Photo	Student	Town	Village	68-1	8/20/2021	UtilityCloud1
2922	CB-843	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1073	CB-842	Village 30	42.14019	-71.41906		7-Jun-17	Aerial Photo	Student	Town	Village	68-1	8/20/2021	UtilityCloud1
2921	CB-842	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1072	CB-841	Village 29	42.14015	-71.41884		7-Jun-17	Aerial Photo	Student	Town	Village	68-1	8/20/2021	UtilityCloud1
2920	CB-841	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1071	CB-840	Village 28	42.14001	-71.41796		7-Jun-17	Aerial Photo	Student	Town	Village	68-1	8/20/2021	UtilityCloud1
2919	CB-840	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1069	CB-839	Village 27	42.13998	-71.4178		7-Jun-17	Aerial Photo	Student	Town	Village	68-1	8/20/2021	UtilityCloud1
2918	CB-839	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1068	CB-838	Village 26	42.13935	-71.41495		7-Jun-17	Aerial Photo	Student	Town	Village	59-5	8/20/2021	UtilityCloud1
2916	CB-838	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1067	CB-837	Village 25	42.13932	-71.41206		7-Jun-17	Aerial Photo	Student	Town	Village	59-4	8/20/2021	UtilityCloud1
2914	CB-837	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1066	CB-836	Village 24	42.13943	-71.41152		7-Jun-17	Aerial Photo	Student	Town	Village	59-4	8/20/2021	UtilityCloud1
2913	CB-836	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1065	CB-835	Village 23	42.13944	-71.41066		7-Jun-17	Aerial Photo	Student	Town	Village	59-4	8/20/2021	UtilityCloud1
2912	CB-835	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1064	CB-834	Village 22	42.13937	-71.41001		7-Jun-17	Aerial Photo	Student	Town	Village	59-4	8/20/2021	UtilityCloud1
2911	CB-834	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
1060	CB-830	Village 18	42.14072	-71.40243		7-Jun-17	Aerial Photo	Student	Town	Village	60-2	8/20/2021	UtilityCloud1
2850	CB-830	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1058	CB-829	Village 17	42.14067	-71.4023		7-Jun-17	Aerial Photo	Student	Town	Village	60-2	8/20/2021	UtilityCloud1
2851	CB-829	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1057	CB-828	Village 16	42.14092	-71.4014		7-Jun-17	Aerial Photo	Student	Town	Village	60-3	8/20/2021	UtilityCloud1
2849	CB-828	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1055	CB-826	Village 14	42.14074	-71.39988		7-Jun-17	Aerial Photo	Student	Town	Village	DW 60-3	8/20/2021	UtilityCloud1
2848	CB-826	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
990	CB-767	Queens 3	42.14623	-71.41412		7-Jun-17	Aerial Photo	Student	Town	Queens	49-9	8/20/2021	UtilityCloud1
2758	CB-767	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
989	CB-766	Queens 2	42.14645	-71.41522		7-Jun-17	Aerial Photo	Student	Town	Queens	59-6	8/20/2021	UtilityCloud1
2756	CB-766	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
988	CB-765	Queens 1	42.14651	-71.41521		7-Jun-17	Aerial Photo	Student	Town	Queens	59-6	8/20/2021	UtilityCloud1
2757	CB-765	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
987	CB-764	Villa 8	42.14732	-71.41548		7-Jun-17	Aerial Photo	Student	Town	Villa	59-6	8/20/2021	UtilityCloud1
2761	CB-764	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
986	CB-763	Villa 7	42.14663	-71.41544		7-Jun-17	Aerial Photo	Student	Town	Villa	59-6	8/20/2021	UtilityCloud1
2760	CB-763	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
985	CB-762	Villa 6	42.14663	-71.41536		7-Jun-17	Aerial Photo	Student	Town	Villa	59-6	8/20/2021	UtilityCloud1
2759	CB-762	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
984	CB-761	Villa 5	42.14581	-71.41547		7-Jun-17	Aerial Photo	Student	Town	Villa	59-6	8/20/2021	UtilityCloud1
2755	CB-761	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
983	CB-760	Villa 4	42.1458	-71.41537		7-Jun-17	Aerial Photo	Student	Town	Villa	59-6	8/20/2021	UtilityCloud1
2754	CB-760	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
982	CB-76	Stallbrook 1	42.13774	-71.46821		6-Jun-17	Aerial Photo	Student	Town	Stallbrook	64-6	8/20/2021	UtilityCloud1
981	CB-759	Villa 3	42.14498	-71.41548		7-Jun-17	Aerial Photo	Student	Town	Villa	59-6	8/20/2021	UtilityCloud1
2763	CB-759	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
980	CB-758	Villa 2	42.14498	-71.41539		7-Jun-17	Aerial Photo	Student	Town	Villa	59-6	8/20/2021	UtilityCloud1
2762	CB-758	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
979	CB-757	Villa 1	42.1442	-71.451569		7-Jun-17	Aerial Photo	Student	Town	Villa	55-7	8/20/2021	UtilityCloud1
978	CB-756	Gable 12	42.14549	-71.41523		7-Jun-17	Aerial Photo	Student	Town	Gable	59-6	8/20/2021	UtilityCloud1
2753	CB-756	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
977	CB-755	Gable 11	42.14556	-71.41523		7-Jun-17	Aerial Photo	Student	Town	Gable	59-6	8/20/2021	UtilityCloud1
2752	CB-755	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
976	CB-754	Gable 10	42.14541	-71.41386		7-Jun-17	Aerial Photo	Student	Town	Gable	<Null>	8/20/2021	UtilityCloud1
2749	CB-754	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
975	CB-753	Gable 9	42.14541	-71.41382		7-Jun-17	Aerial Photo	Student	Town	Gable	49-9	8/20/2021	UtilityCloud1
2748	CB-753	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
974	CB-752	Gable 8	42.14547	-71.41387		7-Jun-17	Aerial Photo	Student	Town	Gable	49-9	8/20/2021	UtilityCloud1
2750	CB-752	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
973	CB-751	Gable 7	42.14547	-71.41384		7-Jun-17	Aerial Photo	Student	Town	Gable	49-9	8/20/2021	UtilityCloud1
2751	CB-751	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
972	CB-750	Gable 6	42.14545	-71.41296		7-Jun-17	Aerial Photo	Student	Town	Gable	59-2	8/20/2021	UtilityCloud1
2740	CB-750	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
971	CB-75	Lost Hill 2	42.13868	-71.47037		6-Jun-17	Aerial Photo	Student	Town	Lost Hill	64-14	8/20/2021	UtilityCloud1
970	CB-749	Gable 5	42.14536	-71.41288		7-Jun-17	Aerial Photo	Student	Town	Gable	59-2	8/20/2021	UtilityCloud1
2739	CB-749	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
969	CB-748	Gable 4	42.14537	-71.41267		7-Jun-17	Aerial Photo	Student	Town	Gable	59-2	8/20/2021	UtilityCloud1
2743	CB-748	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
968	CB-747	Gable 3	42.14494	-71.412		7-Jun-17	Aerial Photo	Student	Town	Gable	49-15	8/20/2021	UtilityCloud1
2738	CB-747	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
967	CB-746	Gable 2	42.14498	-71.41189		7-Jun-17	Aerial Photo	Student	Town	Gable	49-15	8/20/2021	UtilityCloud1
2737	CB-746	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
966	CB-745	Gable 1	42.14479	-71.41107		7-Jun-17	Aerial Photo	Student	Town	Gable	49-13	8/20/2021	UtilityCloud1
2775	CB-745	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
965	CB-744	Dean 9	42.1442	-71.41045		7-Jun-17	Aerial Photo	Student	Town	Dean	59-3	8/20/2021	UtilityCloud1
2776	CB-744	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
964	CB-743	Dean 8	42.14485	-71.41038		7-Jun-17	Aerial Photo	Student	Town	Dean	49-11	8/20/2021	UtilityCloud1
2779	CB-743	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
963	CB-742	Dean 7	42.14491	-71.41046		7-Jun-17	Aerial Photo	Student	Town	Dean	49-11	8/20/2021	UtilityCloud1

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
2780	CB-742	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
962	CB-74	Lost Hill 1	42.13874	-71.47037		6-Jun-17	Aerial Photo	Student	Town	Lost Hill	64-14	8/20/2021	UtilityCloud1
961	CB-739	Dean 4	42.14588	-71.4101		7-Jun-17	Aerial Photo	Student	Town	Dean	49-11	8/20/2021	UtilityCloud1
2782	CB-739	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
960	CB-738	Dean 3	42.14587	-71.41003		7-Jun-17	Aerial Photo	Student	Town	Dean	49-11	8/20/2021	UtilityCloud1
2781	CB-738	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
959	CB-737	Dean 2	42.14658	-71.4099		7-Jun-17	Aerial Photo	Student	Town	Dean	49-11	8/20/2021	UtilityCloud1
2783	CB-737	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
958	CB-736	Dean 1	42.14663	-71.40998		7-Jun-17	Aerial Photo	Student	Town	Dean	49-11	8/20/2021	UtilityCloud1
2784	CB-736	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
957	CB-735	King 11	42.14642	-71.41296		7-Jun-17	Aerial Photo	Student	Town	King	50-2	8/20/2021	UtilityCloud1
2746	CB-735	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
956	CB-734	King 10	42.14641	-71.41286		7-Jun-17	Aerial Photo	Student	Town	King	50-2	8/20/2021	UtilityCloud1
2747	CB-734	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
955	CB-733	King 9	42.14563	-71.41286		7-Jun-17	Aerial Photo	Student	Town	King	50-2	8/20/2021	UtilityCloud1
2745	CB-733	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
954	CB-732	King 8	42.14563	-71.41275		7-Jun-17	Aerial Photo	Student	Town	King	50-2	8/20/2021	UtilityCloud1
2744	CB-732	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
953	CB-731	King 7	42.14516	-71.41264		7-Jun-17	Aerial Photo	Student	Town	King	59-2	8/20/2021	UtilityCloud1
2742	CB-731	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
952	CB-730	King 6	42.14524	-71.41277		7-Jun-17	Aerial Photo	Student	Town	King	59-2	8/20/2021	UtilityCloud1
2741	CB-730	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
951	CB-73	Fox Run 12	42.13717	-71.46888		6-Jun-17	Aerial Photo	Student	Town	Fox Run	64-3	8/20/2021	UtilityCloud1
950	CB-729	King 5	42.14449	-71.41278		7-Jun-17	Aerial Photo	Student	Town	King	50-2	8/20/2021	UtilityCloud1
2765	CB-729	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
949	CB-728	King 4	42.14448	-71.41268		7-Jun-17	Aerial Photo	Student	Town	King	50-2	8/20/2021	UtilityCloud1
2766	CB-728	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
948	CB-727	King 3	42.14392	-71.41289		7-Jun-17	Aerial Photo	Student	Town	King	59-2	8/20/2021	UtilityCloud1
2767	CB-727	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
947	CB-726	King 2	42.14393	-71.41279		7-Jun-17	Aerial Photo	Student	Town	King	59-2	8/20/2021	UtilityCloud1
2768	CB-726	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
946	CB-725	King 1	42.14313	-71.41283		7-Jun-17	Aerial Photo	Student	Town	King	59-1	8/20/2021	UtilityCloud1
2769	CB-725	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
945	CB-724	Crestview 10	42.14377	-71.41266		7-Jun-17	Aerial Photo	Student	Town	Crestview	59-2	8/20/2021	UtilityCloud1
2771	CB-724	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
944	CB-723	Crestview 9	42.14384	-71.41265		7-Jun-17	Aerial Photo	Student	Town	Crestview	59-2	8/20/2021	UtilityCloud1
2772	CB-723	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
943	CB-722	Crestview 8	42.14418	-71.41147		7-Jun-17	Aerial Photo	Student	Town	Crestview	49-15	8/20/2021	UtilityCloud1
2774	CB-722	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
942	CB-721	Crestview 7	42.14414	-71.41139		7-Jun-17	Aerial Photo	Student	Town	Crestview	49-15	8/20/2021	UtilityCloud1
2773	CB-721	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
941	CB-720	Crestview 6	42.14488	-71.41116		7-Jun-17	Aerial Photo	Student	Town	Crestview	49-13	8/20/2021	UtilityCloud1

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
2736	CB-720	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
940	CB-72	Fox Run 11	42.13715	-71.469		6-Jun-17	Aerial Photo	Student	Town	Fox Run	64-3	8/20/2021	UtilityCloud1
939	CB-719	Crestview 5	42.14491	-71.41134		7-Jun-17	Aerial Photo	Student	Town	Crestview	49-13	8/20/2021	UtilityCloud1
2735	CB-719	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
938	CB-718	Crestview 4	42.14565	-71.41158		7-Jun-17	Aerial Photo	Student	Town	Crestview	49-14	8/20/2021	UtilityCloud1
2734	CB-718	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
937	CB-717	Crestview 3	42.14564	-71.41166		7-Jun-17	Aerial Photo	Student	Town	Crestview	49-14	8/20/2021	UtilityCloud1
2733	CB-717	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
936	CB-716	Crestview 2	42.14647	-71.4115		7-Jun-17	Aerial Photo	Student	Town	Crestview	49-14	8/20/2021	UtilityCloud1
2732	CB-716	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
935	CB-715	Crestview 1	42.14649	-71.41159		7-Jun-17	Aerial Photo	Student	Town	Crestview	49-14	8/20/2021	UtilityCloud1
2731	CB-715	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
934	CB-714	Kelley 3	42.14753	-71.41087		7-Jun-17	Aerial Photo	Student	Town	Kelley	40-8	8/20/2021	UtilityCloud1
2730	CB-714	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
933	CB-713	Kelley 2	42.14754	-71.41008		7-Jun-17	Aerial Photo	Student	Town	Kelley	40-8	8/20/2021	UtilityCloud1
2729	CB-713	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
932	CB-712	Kelley 1	42.14762	-71.40781		7-Jun-17	Aerial Photo	Student	Town	Kelley	40-8	8/20/2021	UtilityCloud1
2728	CB-712	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
931	CB-711	Orchard 3	42.14891	-71.41419		7-Jun-17	Aerial Photo	Student	Town	Orchard	49-1	8/20/2021	UtilityCloud1
2805	CB-711	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
930	CB-710	Orchard 2	42.14895	-71.41334		7-Jun-17	Aerial Photo	Student	Town	Orchard	49-2	8/20/2021	UtilityCloud1
2804	CB-710	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
929	CB-71	Fox Run 10	42.13796	-71.46803		6-Jun-17	Aerial Photo	Student	Town	Fox Run	64-4	8/20/2021	UtilityCloud1
928	CB-709	Orchard 1	42.14886	-71.41329		7-Jun-17	Aerial Photo	Student	Town	Orchard	49-2	8/20/2021	UtilityCloud1
2802	CB-709	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
927	CB-708	Henry 10	42.14848	-71.40835		7-Jun-17	Aerial Photo	Student	Town	Henry	40-8	8/20/2021	UtilityCloud1
2792	CB-708	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
926	CB-707	Henry 9	42.14853	-71.40837		7-Jun-17	Aerial Photo	Student	Town	Henry	40-8	8/20/2021	UtilityCloud1
2793	CB-707	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
925	CB-706	Henry 8	42.14845	-71.40911		7-Jun-17	Aerial Photo	Student	Town	Henry	40-8	8/20/2021	UtilityCloud1
2795	CB-706	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
924	CB-705	Henry 7	42.1485	-71.40912		7-Jun-17	Aerial Photo	Student	Town	Henry	40-8	8/20/2021	UtilityCloud1
2794	CB-705	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
923	CB-704	Henry 6	42.14842	-71.40983		7-Jun-17	Aerial Photo	Student	Town	Henry	40-8	8/20/2021	UtilityCloud1
2796	CB-704	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
922	CB-703	Henry 5	42.14849	-71.40984		7-Jun-17	Aerial Photo	Student	Town	Henry	40-8	8/20/2021	UtilityCloud1
2797	CB-703	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
921	CB-702	Henry 4	42.14838	-71.41113		7-Jun-17	Aerial Photo	Student	Town	Henry	49-4	8/20/2021	UtilityCloud1
2799	CB-702	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
920	CB-701	Henry 3	42.14845	-71.41114		7-Jun-17	Aerial Photo	Student	Town	Henry	49-4	8/20/2021	UtilityCloud1
2798	CB-701	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
919	CB-700	Henry 2	42.14833	-71.41285		7-Jun-17	Aerial Photo	Student	Town	Henry	49-3	8/20/2021	UtilityCloud1

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
2800	CB-700	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
918	CB-70	Fox Run 9	42.13803	-71.46807		6-Jun-17	Aerial Photo	Student	Town	Fox Run	64-4	8/20/2021	UtilityCloud1
917	CB-7	Alder 7	42.13939	-71.47546		6-Jun-17	Aerial Photo	Student	Town	Alder	53-1	8/20/2021	UtilityCloud1
916	CB-699	Henry 1	42.14839	-71.41284		7-Jun-17	Aerial Photo	Student	Town	Henry	49-3	8/20/2021	UtilityCloud1
2801	CB-699	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
915	CB-698	Malloy 9	42.14892	-71.41316		7-Jun-17	Aerial Photo	Student	Town	Malloy	49-2	8/20/2021	UtilityCloud1
2803	CB-698	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
914	CB-697	Malloy 8	42.14938	-71.41159		7-Jun-17	Aerial Photo	Student	Town	Malloy	40-8	8/20/2021	UtilityCloud1
2806	CB-697	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
913	CB-696	Malloy 7	42.14946	-71.41159		7-Jun-17	Aerial Photo	Student	Town	Malloy	40-8	8/20/2021	UtilityCloud1
2807	CB-696	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
912	CB-695	Malloy 6	42.14907	-71.41081		7-Jun-17	Aerial Photo	Student	Town	Malloy	40-8	8/20/2021	UtilityCloud1
2808	CB-695	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
911	CB-694	Malloy 5	42.14914	-71.41079		7-Jun-17	Aerial Photo	Student	Town	Malloy	40-8	8/20/2021	UtilityCloud1
2809	CB-694	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
910	CB-693	Malloy 4	42.14908	-71.40969		7-Jun-17	Aerial Photo	Student	Town	Malloy	40-8	8/20/2021	UtilityCloud1
2810	CB-693	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
909	CB-692	Malloy 3	42.14915	-71.4097		7-Jun-17	Aerial Photo	Student	Town	Malloy	40-8	8/20/2021	UtilityCloud1
2811	CB-692	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
908	CB-691	Malloy 2	42.14912	-71.40857		7-Jun-17	Aerial Photo	Student	Town	Malloy	40-8	8/20/2021	UtilityCloud1
2812	CB-691	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
907	CB-690	Malloy 1	42.14919	-71.40858		7-Jun-17	Aerial Photo	Student	Town	Malloy	40-8	8/20/2021	UtilityCloud1
2813	CB-690	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
906	CB-69	Fox Run 8	42.13864	-71.46735		6-Jun-17	Aerial Photo	Student	Town	Fox Run	64-2	8/20/2021	UtilityCloud1
905	CB-689	Appleton 6	42.15049	-71.41003		7-Jun-17	Aerial Photo	Student	Town	Appleton	40-1	8/20/2021	UtilityCloud1
2823	CB-689	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
904	CB-688	Appleton 5	42.15057	-71.41001		7-Jun-17	Aerial Photo	Student	Town	Appleton	40-1	8/20/2021	UtilityCloud1
2822	CB-688	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
903	CB-687	Appleton 4	42.15043	-71.40928		7-Jun-17	Aerial Photo	Student	Town	Appleton	40-1	8/20/2021	UtilityCloud1
2821	CB-687	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
902	CB-686	Appleton 3	42.15051	-71.40928		7-Jun-17	Aerial Photo	Student	Town	Appleton	40-1	8/20/2021	UtilityCloud1
2820	CB-686	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
901	CB-685	Appleton 2	42.15044	-71.40874		7-Jun-17	Aerial Photo	Student	Town	Appleton	40-3	8/20/2021	UtilityCloud1
2818	CB-685	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
900	CB-684	Appleton 1	42.15054	-71.40876		7-Jun-17	Aerial Photo	Student	Town	Appleton	40-3	8/20/2021	UtilityCloud1
2819	CB-684	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
899	CB-683	Koyview 1	42.14597	-71.40449		7-Jun-17	Aerial Photo	Student	Town	Koyview	50-2	8/20/2021	UtilityCloud1
2831	CB-683	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
887	CB-671	Oakland 11	42.15548	-71.39053		7-Jun-17	Aerial Photo	Student	Town	Oakland	DW 33-1	8/20/2021	UtilityCloud1
2691	CB-671	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
886	CB-670	Oakland 10	42.1528	-71.39179		7-Jun-17	Aerial Photo	Student	Town	Oakland	42-3	8/20/2021	UtilityCloud1
2688	CB-670	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
884	CB-67	Fox Run 6	42.14025	-71.46743		6-Jun-17	Aerial Photo	Student	Town	Fox Run	54-6	8/20/2021	UtilityCloud1
883	CB-669	Oakland 9	42.15277	-71.3917		7-Jun-17	Aerial Photo	Student	Town	Oakland	42-3	8/20/2021	UtilityCloud1
2689	CB-669	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
882	CB-668	Oakland 8	42.15014	-71.39219		7-Jun-17	Aerial Photo	Student	Town	Oakland	42-7	8/20/2021	UtilityCloud1
881	CB-667	Oakland 7	42.14986	-71.39216		7-Jun-17	Aerial Photo	Student	Town	Oakland	42-7	8/20/2021	UtilityCloud1
2685	CB-667	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
880	CB-666	Oakland 6	42.1466	-71.39104		7-Jun-17	Aerial Photo	Student	Town	Oakland	51-2	8/20/2021	UtilityCloud1
2682	CB-666	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
879	CB-665	Oakland 5	42.14382	-71.39194		7-Jun-17	Aerial Photo	Student	Town	Oakland	61-4	8/20/2021	UtilityCloud1
2693	CB-665	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
878	CB-664	Oakland 4	42.14382	-71.39202		7-Jun-17	Aerial Photo	Student	Town	Oakland	61-4	8/20/2021	UtilityCloud1
2692	CB-664	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
877	CB-663	Oakland 3	42.14183	-71.39353		7-Jun-17	Aerial Photo	Student	Town	Oakland	61-4	8/20/2021	UtilityCloud1
2679	CB-663	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
876	CB-662	Oakland 2	42.14183	-71.39362		7-Jun-17	Aerial Photo	Student	Town	Oakland	61-4	8/20/2021	UtilityCloud1
2678	CB-662	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
875	CB-661	Oakland 1	42.14052	-71.39379		7-Jun-17	Aerial Photo	Student	Town	Oakland	61-1	8/20/2021	UtilityCloud1
874	CB-660	Grapevine 2	42.14302	-71.39119		7-Jun-17	Aerial Photo	Student	Town	Grapevine	61-5	8/20/2021	UtilityCloud1
873	CB-66	Fox Run 5	42.14025	-71.46752		6-Jun-17	Aerial Photo	Student	Town	Fox Run	54-6	8/20/2021	UtilityCloud1
872	CB-659	Grapevine 1	42.14309	-71.39119		7-Jun-17	Aerial Photo	Student	Town	Grapevine	61-5	8/20/2021	UtilityCloud1
871	CB-658	Crook 2	42.14344	-71.39452		7-Jun-17	Aerial Photo	Student	Town	Crook	DW 60-1	8/20/2021	UtilityCloud1
2671	CB-658	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
870	CB-657	Crook 1	42.14358	-71.39446		7-Jun-17	Aerial Photo	Student	Town	Crook	DW 60-1	8/20/2021	UtilityCloud1
869	CB-656	School 3	42.14255	-71.39553		7-Jun-17	Aerial Photo	Student	Town	School	61-4	8/20/2021	UtilityCloud1
868	CB-655	School 2	42.14028	-71.39536		7-Jun-17	Aerial Photo	Student	Town	School	61-1	8/20/2021	UtilityCloud1
867	CB-654	School 1	42.1403	-71.39525		7-Jun-17	Aerial Photo	Student	Town	School	61-1	8/20/2021	UtilityCloud1
866	CB-653	Barber 4	42.14353	-71.39711		7-Jun-17	Aerial Photo	Student	Town	Barber	50-1	8/20/2021	UtilityCloud1
2666	CB-653	<Null>	<Null>	<Null>	<Null>	12-Jun	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
865	CB-652	Barber 3	42.14097	-71.39661		7-Jun-17	Aerial Photo	Student	Town	Barber	61-1	8/20/2021	UtilityCloud1
2663	CB-652	<Null>	<Null>	<Null>	<Null>	12-Jun	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
864	CB-651	Barber 2	42.1404	-71.39656		7-Jun-17	Aerial Photo	Student	Town	Barber	61-1	8/20/2021	UtilityCloud1
863	CB-650	Barber 1	42.14024	-71.39645		7-Jun-17	Aerial Photo	Student	Town	Barber	61-1	8/20/2021	UtilityCloud1
2664	CB-650	<Null>	<Null>	<Null>	<Null>	12-Jun	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
862	CB-65	Fox Run 4	42.14087	-71.46745		6-Jun-17	Aerial Photo	Student	Town	Fox Run	54-6	8/20/2021	UtilityCloud1
861	CB-649	Broad 6	42.14384	-71.39802		7-Jun-17	Aerial Photo	Student	Town	Broad	50-1	8/20/2021	UtilityCloud1
2675	CB-649	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
860	CB-648	Broad 5	42.14516	-71.39831		7-Jun-17	Aerial Photo	Student	Town	Broad	<Null>	8/20/2021	UtilityCloud1
2673	CB-648	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
859	CB-647	Broad 4	42.14512	-71.39822		7-Jun-17	Aerial Photo	Student	Town	Broad	50-1	8/20/2021	UtilityCloud1
2674	CB-647	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
858	CB-646	Broad 3	42.14386	-71.39811		7-Jun-17	Aerial Photo	Student	Town	Broad	50-1	8/20/2021	UtilityCloud1
2676	CB-646	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
857	CB-645	Broad 2	42.14241	-71.39808		7-Jun-17	Aerial Photo	Student	Town	Broad	50-1	8/20/2021	UtilityCloud1
2677	CB-645	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
856	CB-644	Broad 1	42.14237	-71.39799		7-Jun-17	Aerial Photo	Student	Town	Broad	50-1	8/20/2021	UtilityCloud1
2659	CB-644	<Null>	<Null>	<Null>	<Null>	12-Jun	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
855	CB-643	Pine 1	42.14165	-71.39977		7-Jun-17	Aerial Photo	Student	Town	Pine	50-1	8/20/2021	UtilityCloud1
2847	CB-643	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
854	CB-642	North 4	42.14281	-71.39348		7-Jun-17	Aerial Photo	Student	Town	North	61-4	8/20/2021	UtilityCloud1
853	CB-641	North 3	42.14274	-71.39457		7-Jun-17	Aerial Photo	Student	Town	North	61-4	8/20/2021	UtilityCloud1
2662	CB-641	<Null>	<Null>	<Null>	<Null>	12-Jun	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
852	CB-640	North 2	42.14258	-71.39565		7-Jun-17	Aerial Photo	Student	Town	North	61-4	8/20/2021	UtilityCloud1
2657	CB-640	<Null>	<Null>	<Null>	<Null>	12-Jun	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
851	CB-64	Fox Run 3	42.14087	-71.46754		6-Jun-17	Aerial Photo	Student	Town	Fox Run	54-6	8/20/2021	UtilityCloud1
850	CB-639	North 1	42.14222	-71.40065		7-Jun-17	Aerial Photo	Student	Town	North	50-1	8/20/2021	UtilityCloud1
2661	CB-639	<Null>	<Null>	<Null>	<Null>	12-Jun	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
849	CB-638	Sanderson 2	42.14308	-71.40073		7-Jun-17	Aerial Photo	Student	Town	Sanderson	60-1	8/20/2021	UtilityCloud1
2843	CB-638	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
848	CB-637	Sanderson 1	42.14314	-71.40075		7-Jun-17	Aerial Photo	Student	Town	Sanderson	60-1	8/20/2021	UtilityCloud1
2844	CB-637	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
847	CB-636	Sanford 4	42.13889	-71.39776		7-Jun-17	Aerial Photo	Student	Town	Sanford	70-2	8/20/2021	UtilityCloud1
2937	CB-636	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	8/3/2023	scarlisle_TownofMedway
846	CB-634	Sanford 2	42.13928	-71.39737		7-Jun-17	Aerial Photo	Student	Town	Sanford	70-2	8/20/2021	UtilityCloud1
2936	CB-634	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	8/3/2023	scarlisle_TownofMedway
845	CB-633	Sanford 1	42.13936	-71.39719		7-Jun-17	Aerial Photo	Student	Town	Sanford	70-2	8/20/2021	UtilityCloud1
844	CB-632	Cassidy 6	42.14227	-71.40144		7-Jun-17	Aerial Photo	Student	Town	Cassidy	50-1	8/20/2021	UtilityCloud1
2703	CB-632	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
843	CB-631	Cassidy 5	42.14233	-71.40152		7-Jun-17	Aerial Photo	Student	Town	Cassidy	50-1	8/20/2021	UtilityCloud1
2704	CB-631	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
842	CB-630	Cassidy 4	42.14203	-71.40231		7-Jun-17	Aerial Photo	Student	Town	Cassidy	50-1	8/20/2021	UtilityCloud1
2701	CB-630	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
841	CB-63	Fox Run 2	42.14169	-71.46749		6-Jun-17	Aerial Photo	Student	Town	Fox Run	54-6	8/20/2021	UtilityCloud1
840	CB-629	Cassidy 3	42.1421	-71.4023		7-Jun-17	Aerial Photo	Student	Town	Cassidy	50-1	8/20/2021	UtilityCloud1
2702	CB-629	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
839	CB-628	Cassidy 2	42.14199	-71.40451		7-Jun-17	Aerial Photo	Student	Town	Cassidy	50-1	8/20/2021	UtilityCloud1
2705	CB-628	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
838	CB-627	Cassidy 1	42.14187	-71.40567		7-Jun-17	Aerial Photo	Student	Town	Cassidy	59-12	8/20/2021	UtilityCloud1
2708	CB-627	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
837	CB-626	Lovers 4	42.14327	-71.40266		7-Jun-17	Aerial Photo	Student	Town	Lovers	50-4	8/20/2021	UtilityCloud1
2697	CB-626	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
836	CB-625	Lovers 3	42.14331	-71.40278		7-Jun-17	Aerial Photo	Student	Town	Lovers	50-4	8/20/2021	UtilityCloud1
2696	CB-625	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
835	CB-624	Lovers 2	42.1431	-71.40325		7-Jun-17	Aerial Photo	Student	Town	Lovers	60-4	8/20/2021	UtilityCloud1
2698	CB-624	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
834	CB-623	Lovers 1	42.143	-71.40335		7-Jun-17	Aerial Photo	Student	Town	Lovers	60-4	8/20/2021	UtilityCloud1
2699	CB-623	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
833	CB-622	Prospect 2	42.1419	-71.40441		7-Jun-17	Aerial Photo	Student	Town	Prospect	50-1	8/20/2021	UtilityCloud1
2707	CB-622	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
832	CB-621	Prospect 1	42.1419	-71.40452		7-Jun-17	Aerial Photo	Student	Town	Prospect	50-1	8/20/2021	UtilityCloud1
2706	CB-621	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
831	CB-620	Legion 2	42.14187	-71.40581		7-Jun-17	Aerial Photo	Student	Town	Legion	59-12	8/20/2021	UtilityCloud1
2709	CB-620	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
830	CB-62	Fox Run 1	42.14168	-71.46759		6-Jun-17	Aerial Photo	Student	Town	Fox Run	54-6	8/20/2021	UtilityCloud1
829	CB-619	Legion 1	42.14121	-71.40561		7-Jun-17	Aerial Photo	Student	Town	Legion	59-12	8/20/2021	UtilityCloud1
2718	CB-619	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
828	CB-617	Riverview 1	42.13561	-71.40802		7-Jun-17	Aerial Photo	Student	Town	Riverview	69-5	8/20/2021	UtilityCloud1
2882	CB-617	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/21/2023	MedwayMA
827	CB-616	Charles River 5	42.13472	-71.40852		7-Jun-17	Aerial Photo	Student	Town	Charles River	69-6	8/20/2021	UtilityCloud1
2881	CB-616	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/21/2023	MedwayMA
826	CB-615	Charles River 4	42.13539	-71.40859		7-Jun-17	Aerial Photo	Student	Town	Charles River	69-6	8/20/2021	UtilityCloud1
2880	CB-615	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/21/2023	MedwayMA
825	CB-614	Charles River 3	42.13648	-71.40873		7-Jun-17	Aerial Photo	Student	Town	Charles River	69-6	8/20/2021	UtilityCloud1
2877	CB-614	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/21/2023	MedwayMA
824	CB-613	Charles River 2	42.13738	-71.40877		7-Jun-17	Aerial Photo	Student	Town	Charles River	69-6	8/20/2021	UtilityCloud1
2876	CB-613	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/21/2023	MedwayMA
823	CB-612	Charles River 1	42.1392	-71.40887		7-Jun-17	Aerial Photo	Student	Town	Charles River	69-3	8/20/2021	UtilityCloud1
2872	CB-612	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/21/2023	MedwayMA
822	CB-611	Center 4	42.14074	-71.40951		7-Jun-17	Aerial Photo	Student	Town	Center	59-11	8/20/2021	UtilityCloud1
2867	CB-611	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/19/2023	MedwayMA
820	CB-609	Center 2	42.13948	-71.40954		7-Jun-17	Aerial Photo	Student	Town	Center	59-4	8/20/2021	UtilityCloud1
2869	CB-609	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/19/2023	MedwayMA
819	CB-608	Center 1	42.13948	-71.40945		7-Jun-17	Aerial Photo	Student	Town	Center	59-4	8/20/2021	UtilityCloud1
2870	CB-608	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/19/2023	MedwayMA
800	CB-591	Cottage 3	42.14072	-71.42338		7-Jun-17	Aerial Photo	Student	Town	Cottage	58-5	8/20/2021	UtilityCloud1
2933	CB-591	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
799	CB-590	Cottage 2	42.14066	-71.42337		7-Jun-17	Aerial Photo	Student	Town	Cottage	58-5	8/20/2021	UtilityCloud1
2932	CB-590	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
402	CB-589	Cottage 1	42.14047	-71.42365		7-Jun-17	Aerial Photo	Student	Town	Cottage	58-5	8/20/2021	UtilityCloud1
2931	CB-589	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
2619	CB-2731	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	1/26/2023	scarlisle_TownofMedway
2834	CB-2731	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
2588	CB-2700	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	11/15/2021	scarlisle_TownofMedway
2858	CB-2700	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/6/2023	MedwayMA
2153	CB-2663	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	8/20/2021	UtilityCloud1
2828	CB-2663	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
2072	CB-2582	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	8/20/2021	UtilityCloud1

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
2902	CB-2582	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
2071	CB-2581	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	8/20/2021	UtilityCloud1
2901	CB-2581	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
2070	CB-2580	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	8/20/2021	UtilityCloud1
2900	CB-2580	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
2064	CB-2574	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	8/20/2021	UtilityCloud1
2906	CB-2574	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
2015	CB-2525	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	41-1	8/20/2021	UtilityCloud1
2789	CB-2525	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
767	CB-2471	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	31-12	8/20/2021	UtilityCloud1
2854	CB-2471	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/6/2023	MedwayMA
2225	CB-246	Olde Surrey 2	42.16803	-71.44882		6-Jun-17	Aerial Photo	Student	Town	Olde Surrey	5-Dec	8/20/2021	UtilityCloud1
2717	CB-246	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
743	CB-2446	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	70-6	8/20/2021	UtilityCloud1
2905	CB-2446	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
739	CB-2442	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	70-5	8/20/2021	UtilityCloud1
2907	CB-2442	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
738	CB-2441	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	70-4	8/20/2021	UtilityCloud1
2908	CB-2441	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
737	CB-2440	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	CUL 56-3	8/20/2021	UtilityCloud1
2909	CB-2440	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
2223	CB-244	Claybrook Farm 18	42.16745	-71.44497		6-Jun-17	Aerial Photo	Student	Town	Claybrook Farm	16-Dec	8/20/2021	UtilityCloud1
736	CB-2439	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	46-9	8/20/2021	UtilityCloud1
2910	CB-2439	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
724	CB-2427	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	21-2	8/20/2021	UtilityCloud1
2903	CB-2427	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
723	CB-2426	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-12	8/20/2021	UtilityCloud1
722	CB-2425	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-12	8/20/2021	UtilityCloud1
2898	CB-2425	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
721	CB-2424	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-12	8/20/2021	UtilityCloud1
2899	CB-2424	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
720	CB-2423	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-12	8/20/2021	UtilityCloud1
2897	CB-2423	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
719	CB-2422	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-12	8/20/2021	UtilityCloud1
2896	CB-2422	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
718	CB-2421	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-8	8/20/2021	UtilityCloud1
2894	CB-2421	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
717	CB-2420	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-8	8/20/2021	UtilityCloud1
2895	CB-2420	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
2221	CB-242	Claybrook Farm 16	42.16736	-71.44605		6-Jun-17	Aerial Photo	Student	Town	Claybrook Farm	16-Dec	8/20/2021	UtilityCloud1
716	CB-2419	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-8	8/20/2021	UtilityCloud1
715	CB-2418	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-8	8/20/2021	UtilityCloud1

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
714	CB-2417	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-8	8/20/2021	UtilityCloud1
2891	CB-2417	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
713	CB-2416	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-8	8/20/2021	UtilityCloud1
712	CB-2415	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-8	8/20/2021	UtilityCloud1
2889	CB-2415	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
711	CB-2414	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-8	8/20/2021	UtilityCloud1
2893	CB-2414	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
710	CB-2413	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-8	8/20/2021	UtilityCloud1
2892	CB-2413	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
709	CB-2412	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-8	8/20/2021	UtilityCloud1
708	CB-2411	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-8	8/20/2021	UtilityCloud1
2888	CB-2411	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
707	CB-2410	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-8	8/20/2021	UtilityCloud1
2220	CB-241	Claybrook Farm 15	42.16742	-71.44607		6-Jun-17	Aerial Photo	Student	Town	Claybrook Farm	16-Dec	8/20/2021	UtilityCloud1
706	CB-2409	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	40-8	8/20/2021	UtilityCloud1
2886	CB-2409	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
705	CB-2408	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	48-16	8/20/2021	UtilityCloud1
2887	CB-2408	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
704	CB-2407	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	48-16	8/20/2021	UtilityCloud1
2884	CB-2407	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
703	CB-2406	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	48-16	8/20/2021	UtilityCloud1
2885	CB-2406	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/25/2023	MedwayMA
676	CB-2379	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	48-16	8/20/2021	UtilityCloud1
2720	CB-2379	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
664	CB-2367	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	Cul-1	8/20/2021	UtilityCloud1
2945	CB-2367	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	8/3/2023	scarlisle_TownofMedway
663	CB-2366	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	Cul-1	8/20/2021	UtilityCloud1
2944	CB-2366	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	8/3/2023	scarlisle_TownofMedway
662	CB-2365	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	Cul-1	8/20/2021	UtilityCloud1
2942	CB-2365	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	8/3/2023	scarlisle_TownofMedway
661	CB-2364	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	Cul-1	8/20/2021	UtilityCloud1
2943	CB-2364	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	8/3/2023	scarlisle_TownofMedway
659	CB-2362	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	Cul-1	8/20/2021	UtilityCloud1
2941	CB-2362	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	8/3/2023	scarlisle_TownofMedway
647	CB-2350	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	61-6	8/20/2021	UtilityCloud1
2860	CB-2350	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/19/2023	MedwayMA
587	CB-2290	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	21-12	8/20/2021	UtilityCloud1
2883	CB-2290	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/21/2023	MedwayMA
586	CB-2289	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	Cul-2	8/20/2021	UtilityCloud1
2879	CB-2289	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/21/2023	MedwayMA
585	CB-2288	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	28-11	8/20/2021	UtilityCloud1
2878	CB-2288	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/21/2023	MedwayMA

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
584	CB-2287	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	28-4	8/20/2021	UtilityCloud1
2875	CB-2287	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/21/2023	MedwayMA
583	CB-2286	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	28-1	8/20/2021	UtilityCloud1
2915	CB-2286	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/27/2023	MedwayMA
571	CB-2274	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	21-1	8/20/2021	UtilityCloud1
2670	CB-2274	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
570	CB-2273	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	CUL 19-2	8/20/2021	UtilityCloud1
2668	CB-2273	<Null>	<Null>	<Null>	<Null>	12-Jun	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
569	CB-2272	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	19-9	8/20/2021	UtilityCloud1
2669	CB-2272	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
568	CB-2271	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	27-1	8/20/2021	UtilityCloud1
2934	CB-2271	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	8/3/2023	scarlisle_TownofMedway
567	CB-2270	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	16-5	8/20/2021	UtilityCloud1
2652	CB-2270	<Null>	<Null>	<Null>	<Null>	12-Jun	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
565	CB-2268	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	21-4	8/20/2021	UtilityCloud1
2655	CB-2268	<Null>	<Null>	<Null>	<Null>	12-Jun	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
564	CB-2267	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	21-1	8/20/2021	UtilityCloud1
2654	CB-2267	<Null>	<Null>	<Null>	<Null>	12-Jun	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
562	CB-2265	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	21-1	8/20/2021	UtilityCloud1
2868	CB-2265	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/19/2023	MedwayMA
551	CB-2253	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	19-3	8/20/2021	UtilityCloud1
2764	CB-2253	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
466	CB-2168	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	20-6	8/20/2021	UtilityCloud1
2856	CB-2168	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/6/2023	MedwayMA
465	CB-2167	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	20-6	8/20/2021	UtilityCloud1
2855	CB-2167	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/6/2023	MedwayMA
464	CB-2166	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	20-6	8/20/2021	UtilityCloud1
2853	CB-2166	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/6/2023	MedwayMA
453	CB-2156	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	20-2	8/20/2021	UtilityCloud1
2874	CB-2156	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/21/2023	MedwayMA
452	CB-2155	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	20-3	8/20/2021	UtilityCloud1
2777	CB-2155	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
451	CB-2154	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	20-3	8/20/2021	UtilityCloud1
2778	CB-2154	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
2192	CB-2144	Lovers 5	42.14197	-71.40334		23-Aug-17	Aerial Photo	Student	Town	Lovers	50-1	8/20/2021	UtilityCloud1
2700	CB-2144	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
2719	CB-2144	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
1619	CB-2135	Center 7	42.1422	-71.40929		21-Aug-17	Aerial Photo	Student	Town	Center	59-11	8/20/2021	UtilityCloud1
2861	CB-2135	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/19/2023	MedwayMA
1611	CB-2125	Village 60	42.14012	-71.39724		2-Aug-17	Aerial Photo	Student	Town	Village	61-1	8/20/2021	UtilityCloud1
2935	CB-2125	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	8/3/2023	scarlisle_TownofMedway
1583	CB-21	Holbrook 5	42.1398	-71.4565		6-Jun-17	Aerial Photo	Student	Town	Holbrook	<Null>	8/20/2021	UtilityCloud1

OBJECTID *	Asset ID *	Town CB ID	xy_loc_x_c	xy_loc_y_c	Elevation	map_date	map_method	mapped_by	Owner	Street	Associated_DischargePoint	CreationDate	Creator
2788	CB-21	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
1525	CB-2038	River 3	42.13847	-71.39636		25-Jul-17	Aerial Photo	Student	Town	River	70-1	8/20/2021	UtilityCloud1
2940	CB-2038	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	8/3/2023	scarlisle_TownofMedway
1524	CB-2037	River 2	42.13873	-71.39759		25-Jul-17	Aerial Photo	Student	Town	River	70-2	8/20/2021	UtilityCloud1
2938	CB-2037	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>	8/3/2023	scarlisle_TownofMedway
1494	CB-2003	Oakland 17	42.14199	-71.39356		25-Jul-17	Aerial Photo	Student	Town	Oakland	61-4	8/20/2021	UtilityCloud1
2681	CB-2003	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
1493	CB-2002	Oakland 16	42.14198	-71.39346		25-Jul-17	Aerial Photo	Student	Town	Oakland	61-4	8/20/2021	UtilityCloud1
2680	CB-2002	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
1492	CB-2001	Oakland 15	42.14812	-71.39113		25-Jul-17	Aerial Photo	Student	Town	Oakland	51-1	8/20/2021	UtilityCloud1
2684	CB-2001	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
1491	CB-2000	Oakland 14	42.15002	-71.39213		25-Jul-17	Aerial Photo	Student	Town	Oakland	42-7	8/20/2021	UtilityCloud1
2687	CB-2000	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
1487	CB-1999	Oakland	42.14814	-71.391		25-Jul-17	Aerial Photo		Town	Oakland	51-1	8/20/2021	UtilityCloud1
2683	CB-1999	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/12/2023	UtilityCloud1
1394	CB-1905	King 12	42.14313	-71.4129		24-Jul-17	Aerial Photo	Student	Town	King	59-1	8/20/2021	UtilityCloud1
2770	CB-1905	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
1393	CB-1904	Kenney 2	42.14681	-71.40486		24-Jul-17	Aerial Photo	Student	Town	Kenney	50-3	8/20/2021	UtilityCloud1
2727	CB-1904	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
1392	CB-1903	Kenney 1	42.14676	-71.40479		24-Jul-17	Aerial Photo	Student	Town	Kenney	50-3	8/20/2021	UtilityCloud1
2726	CB-1903	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/27/2023	scarlisle_TownofMedway
1391	CB-1902	Koyview 2	42.14597	-71.40439		24-Jul-17	Aerial Photo	Student	Town	Koyview	50-2	8/20/2021	UtilityCloud1
2832	CB-1902	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
2833	CB-1902	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/29/2023	scarlisle_TownofMedway
1275	CB-1796	Charles River 6	42.13848	-71.40879		18-Jul-17	Aerial Photo	Student	Town	Charles River	69-3	8/20/2021	UtilityCloud1
2873	CB-1796	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/21/2023	MedwayMA
1273	CB-1794	Center 6	42.14116	-71.40946		18-Jul-17	Aerial Photo	Student	Town	Center	59-11	8/20/2021	UtilityCloud1
2859	CB-1794	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	7/19/2023	MedwayMA
1269	CB-1788	Cassidy 10	42.14173	-71.40714		17-Jul-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2712	CB-1788	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
1268	CB-1787	Burke Elementary 5	42.14137	-71.40688		17-Jul-17	Aerial Photo	Student	Town	Cassidy	59-11	8/20/2021	UtilityCloud1
2716	CB-1787	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/13/2023	UtilityCloud1
1983	CB-1727	Holliston 22	42.15007	-71.40869		12-Jun-17	Aerial Photo	Student	Town	Holliston	40-8	8/20/2021	UtilityCloud1
2817	CB-1727	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
1982	CB-1726	Holliston 21	42.14983	-71.40864		12-Jun-17	Aerial Photo	Student	Town	Holliston	40-8	8/20/2021	UtilityCloud1
2816	CB-1726	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway
1981	CB-1725	Holliston 20	42.14926	-71.40854		12-Jun-17	Aerial Photo	Student	Town	Holliston	40-8	8/20/2021	UtilityCloud1
2814	CB-1725	<Null>	<Null>	<Null>	<Null>	<Null>	1	<Null>	<Null>	<Null>	<Null>	6/28/2023	scarlisle_TownofMedway

map_date	map_method	mapped_by	st_name	struct_id	town_cb_id	UC_struct_id	xy_loc_x_c	xy_loc_y_c	ObjectId	Shape *
30-May-18	Aerial Photo	Student	Trotter	MH-10	Trotter 6	SWM-10	42.14042	-71.47173	8	Point
30-May-18	Aerial Photo	Student	Trotter	MH-11	Trotter 7	SWM-11	42.13891	-71.47104	9	Point
30-May-18	Aerial Photo	Student	Hawthorne	MH-22	Hawthorne 1	SWM-22	42.14015	-71.4663	19	Point
1-Jun-18	Aerial Photo	Student	Village	MH-500	Village 14	SWM-500	42.14035	-71.42013	342	Point
1-Jun-18	Aerial Photo	Student	Village	MH-501	Village 15	SWM-501	42.13934	-71.41215	343	Point
1-Jun-18	Aerial Photo	Student	Village	MH-502	Village 16	SWM-502	42.13944	-71.40948	344	Point
1-Jun-18	Aerial Photo	Student	Sunset	MH-529	Sunset 3	SWM-529	42.1555	-71.41451	362	Point
1-Jun-18	Aerial Photo	Student	Center	MH-548	Center 1	SWM-548	42.14035	-71.4095	375	Point
1-Jun-18	Aerial Photo	Student	Center	MH-549	Center 2	SWM-549	42.14036	-71.40945	376	Point
1-Jun-18	Aerial Photo	Student	Charles River	MH-550	Charles River 1	SWM-550	42.13817	-71.40878	377	Point
1-Jun-18	Aerial Photo	Student	Charles River	MH-551	Charles River 2	SWM-551	42.1374	-71.40874	378	Point
1-Jun-18	Aerial Photo	Student	Charles River	MH-552	Charles River 3	SWM-552	42.13534	-71.40856	379	Point
1-Jun-18	Aerial Photo	Student	Holliston	MH-560	Holliston 6	SWM-560	42.14923	-71.40854	384	Point
1-Jun-18	Aerial Photo	Student	Holliston	MH-561	Holliston 7	SWM-561	42.14853	-71.40832	385	Point
1-Jun-18	Aerial Photo	Student	Holliston	MH-563	Holliston 9	SWM-563	42.14208	-71.40104	386	Point
1-Jun-18	Aerial Photo	Student	Legion	MH-564	Legion 1	SWM-564	42.14121	-71.40558	387	Point
1-Jun-18	Aerial Photo	Student	Legion	MH-566	Legion 3	SWM-566	42.14125	-71.40561	388	Point
1-Jun-18	Aerial Photo	Student	Cassidy	MH-567	Cassidy 1	SWM-567	42.14135	-71.4071	389	Point
1-Jun-18	Aerial Photo	Student	Cassidy	MH-568	Cassidy 2	SWM-568	42.14172	-71.40708	390	Point
4-Jun-18	Aerial Photo	Student	Malloy	MH-648	Malloy 1	SWM-648	42.14914	-71.40857	465	Point
4-Jun-18	Aerial Photo	Student	Mallory	MH-649	Mallory 2	SWM-649	42.14908	-71.40965	466	Point
4-Jun-18	Aerial Photo	Student	Malloy	MH-650	Malloy 3	SWM-650	42.14916	-71.41076	467	Point
4-Jun-18	Aerial Photo	Student	Malloy	MH-651	Malloy 4	SWM-651	42.1491	-71.41102	468	Point
4-Jun-18	Aerial Photo	Student	Malloy	MH-652	Malloy 5	SWM-652	42.14935	-71.41144	469	Point
4-Jun-18	Aerial Photo	Student	Henry	MH-654	Henry 1	SWM-654	42.14842	-71.41108	470	Point
4-Jun-18	Aerial Photo	Student	Villa	MH-656	Villa 1	SWM-656	42.14725	-71.41549	472	Point
4-Jun-18	Aerial Photo	Student	Villa	MH-659	Villa 4	SWM-659	42.14603	-71.41541	475	Point
4-Jun-18	Aerial Photo	Student	Villa	MH-661	Villa 6	SWM-661	42.14492	-71.41547	477	Point
4-Jun-18	Aerial Photo	Student	Villa	MH-662	Villa 7	SWM-662	42.14428	-71.41557	478	Point
4-Jun-18	Aerial Photo	Student	Gable	MH-665	Gable 3	SWM-665	42.14532	-71.4127	481	Point
4-Jun-18	Aerial Photo	Student	Gable	MH-666	Gable 4	SWM-666	42.14492	-71.41146	482	Point
4-Jun-18	Aerial Photo	Student	Dean	MH-667	Dean 1	SWM-667	42.14483	-71.4104	483	Point
4-Jun-18	Aerial Photo	Student	Dean	MH-668	Dean 2	SWM-668	42.14535	-71.41018	484	Point
4-Jun-18	Aerial Photo	Student	Kings	MH-671	Kings 2	SWM-671	42.14641	-71.41287	486	Point
4-Jun-18	Aerial Photo	Student	Kings	MH-674	Kings 5	SWM-674	42.14446	-71.41274	488	Point
4-Jun-18	Aerial Photo	Student	Crestview	MH-676	Crestview 1	SWM-676	42.14638	-71.41165	490	Point
<Null>	<Null>	<Null>	<Null>	MH-936	<Null>	SWM-936	<Null>	<Null>	729	Point

map_date	map_method	mapped_by	st_name	struct_id	town_cb_id	UC_struct_id	xy_loc_x_c	xy_loc_y_c	ObjectId	Shape *
<Null>	<Null>	<Null>	<Null>	MH-937	<Null>	SWM-937	<Null>	<Null>	730	Point
<Null>	<Null>	<Null>	<Null>	MH-938	<Null>	SWM-938	<Null>	<Null>	731	Point
<Null>	<Null>	<Null>	<Null>	MH-939	<Null>	SWM-939	<Null>	<Null>	732	Point
<Null>	<Null>	<Null>	<Null>	MH-940	<Null>	SWM-940	<Null>	<Null>	733	Point
<Null>	<Null>	<Null>	<Null>	MH-941	<Null>	SWM-941	<Null>	<Null>	734	Point
<Null>	<Null>	<Null>	<Null>	MH-1230	<Null>	SWM-1230	<Null>	<Null>	1023	Point
<Null>	<Null>	<Null>	<Null>	MH-1234	<Null>	SWM-1234	<Null>	<Null>	1028	Point
<Null>	<Null>	<Null>	<Null>	MH-1252	<Null>	SWM-1252	<Null>	<Null>	1047	Point
<Null>	<Null>	<Null>	<Null>	MH-1256	<Null>	SWM-1256	<Null>	<Null>	1051	Point
<Null>	<Null>	<Null>	<Null>	MH-1264	<Null>	SWM-1264	<Null>	<Null>	1059	Point
<Null>	<Null>	<Null>	<Null>	MH-1266	<Null>	SWM-1266	<Null>	<Null>	1061	Point
<Null>	<Null>	<Null>	<Null>	MH-1272	<Null>	SWM-1272	<Null>	<Null>	1067	Point
<Null>	<Null>	<Null>	<Null>	MH-1306	<Null>	SWM-1306	<Null>	<Null>	1101	Point
<Null>	<Null>	<Null>	<Null>	MH-1383	<Null>	SWM-1383	<Null>	<Null>	1179	Point
<Null>	<Null>	<Null>	<Null>	MH-1384	<Null>	SWM-1384	<Null>	<Null>	1180	Point
<Null>	<Null>	<Null>	<Null>	MH-1385	<Null>	SWM-1385	<Null>	<Null>	1181	Point
<Null>	<Null>	<Null>	<Null>	MH-1396	<Null>	SWM-1396	<Null>	<Null>	1192	Point
<Null>	<Null>	<Null>	<Null>	MH-1410	<Null>	SWM-1410	<Null>	<Null>	1206	Point
<Null>	<Null>	<Null>	<Null>	MH-1411	<Null>	SWM-1411	<Null>	<Null>	1207	Point
<Null>	<Null>	<Null>	<Null>	MH-1412	<Null>	SWM-1412	<Null>	<Null>	1208	Point
<Null>	<Null>	<Null>	<Null>	MH-1414	<Null>	SWM-1414	<Null>	<Null>	1210	Point
<Null>	<Null>	<Null>	<Null>	MH-1415	<Null>	SWM-1415	<Null>	<Null>	1211	Point
<Null>	<Null>	<Null>	<Null>	MH-1417	<Null>	SWM-1417	<Null>	<Null>	1213	Point
<Null>	<Null>	<Null>	<Null>	MH-1418	<Null>	SWM-1418	<Null>	<Null>	1214	Point
<Null>	<Null>	<Null>	<Null>	MH-1420	<Null>	SWM-1420	<Null>	<Null>	1216	Point
<Null>	<Null>	<Null>	<Null>	MH-1421	<Null>	SWM-1421	<Null>	<Null>	1217	Point
<Null>	<Null>	<Null>	<Null>	MH-1422	<Null>	SWM-1422	<Null>	<Null>	1218	Point
<Null>	<Null>	<Null>	<Null>	MH-1423	<Null>	SWM-1423	<Null>	<Null>	1219	Point
<Null>	<Null>	<Null>	<Null>	MH-1424	<Null>	SWM-1424	<Null>	<Null>	1220	Point
<Null>	<Null>	<Null>	<Null>	MH-1425	<Null>	SWM-1425	<Null>	<Null>	1221	Point
<Null>	<Null>	<Null>	<Null>	MH-1433	<Null>	SWM-1433	<Null>	<Null>	1229	Point
<Null>	<Null>	<Null>	<Null>	MH-1434	<Null>	SWM-1434	<Null>	<Null>	1230	Point
<Null>	<Null>	<Null>	<Null>	MH-1435	<Null>	SWM-1435	<Null>	<Null>	1231	Point
<Null>	<Null>	<Null>	<Null>	MH-1436	<Null>	SWM-1436	<Null>	<Null>	1232	Point
<Null>	<Null>	<Null>	<Null>	MH-1437	<Null>	SWM-1437	<Null>	<Null>	1233	Point
<Null>	<Null>	<Null>	<Null>	MH-1459	<Null>	SWM-1459	<Null>	<Null>	1255	Point
<Null>	<Null>	<Null>	<Null>	MH-1461	<Null>	SWM-1461	<Null>	<Null>	1257	Point

map_date	map_method	mapped_by	st_name	struct_id	town_cb_id	UC_struct_id	xy_loc_x_c	xy_loc_y_c	ObjectId	Shape *
<Null>	<Null>	<Null>	<Null>	MH-1462	<Null>	SWM-1462	<Null>	<Null>	1258	Point
<Null>	<Null>	<Null>	<Null>	MH-1465	<Null>	SWM-1465	<Null>	<Null>	1261	Point
<Null>	<Null>	<Null>	<Null>	MH-1466	<Null>	SWM-1466	<Null>	<Null>	1262	Point
<Null>	<Null>	<Null>	<Null>	MH-1468	<Null>	SWM-1468	<Null>	<Null>	1264	Point
<Null>	<Null>	<Null>	<Null>	MH-1471	<Null>	SWM-1471	<Null>	<Null>	1267	Point
<Null>	<Null>	<Null>	<Null>	MH-1472	<Null>	SWM-1472	<Null>	<Null>	1268	Point
<Null>	<Null>	<Null>	<Null>	MH-1473	<Null>	SWM-1473	<Null>	<Null>	1269	Point
<Null>	<Null>	<Null>	<Null>	MH-1474	<Null>	SWM-1474	<Null>	<Null>	1270	Point
<Null>	<Null>	<Null>	<Null>	MH-1478	<Null>	SWM-1478	<Null>	<Null>	1274	Point
<Null>	<Null>	<Null>	<Null>	MH-1479	<Null>	SWM-1479	<Null>	<Null>	1275	Point
<Null>	<Null>	<Null>	<Null>	MH-1537	<Null>	SWM-1537	<Null>	<Null>	1333	Point
<Null>	<Null>	<Null>	<Null>	MH-1548	<Null>	SWM-1548	<Null>	<Null>	1344	Point
<Null>	<Null>	<Null>	<Null>	MH-1566	<Null>	SWM-1566	<Null>	<Null>	1362	Point
<Null>	<Null>	<Null>	<Null>	MH-1567	<Null>	SWM-1567	<Null>	<Null>	1363	Point
<Null>	<Null>	<Null>	<Null>	MH-1656	<Null>	SWM-1656	<Null>	<Null>	1452	Point
<Null>	<Null>	<Null>	<Null>	MH-1684	<Null>	SWM-1684	<Null>	<Null>	1480	Point
<Null>	<Null>	<Null>	<Null>	MH-1684	<Null>	SMH-1684	<Null>	<Null>	1481	Point
<Null>	1	<Null>	<Null>	MH-529	<Null>	<Null>	<Null>	<Null>	1547	Point
<Null>	1	<Null>	<Null>	MH-568	<Null>	<Null>	<Null>	<Null>	1548	Point
<Null>	1	<Null>	<Null>	MH-1465	<Null>	<Null>	<Null>	<Null>	1549	Point
<Null>	1	<Null>	<Null>	MH-567	<Null>	<Null>	<Null>	<Null>	1550	Point
<Null>	1	<Null>	<Null>	MH-566	<Null>	<Null>	<Null>	<Null>	1551	Point
<Null>	1	<Null>	<Null>	MH-564	<Null>	<Null>	<Null>	<Null>	1552	Point
<Null>	1	<Null>	<Null>	MH-1459	<Null>	<Null>	<Null>	<Null>	1554	Point
<Null>	1	<Null>	<Null>	MH-1466	<Null>	<Null>	<Null>	<Null>	1556	Point
<Null>	1	<Null>	<Null>	MH-1461	<Null>	<Null>	<Null>	<Null>	1557	Point
<Null>	1	<Null>	<Null>	MH-1462	<Null>	<Null>	<Null>	<Null>	1558	Point
<Null>	1	<Null>	<Null>	MH-678	<Null>	<Null>	<Null>	<Null>	1559	Point
<Null>	1	<Null>	<Null>	MH-676	<Null>	<Null>	<Null>	<Null>	1560	Point
<Null>	1	<Null>	<Null>	MH-666	<Null>	<Null>	<Null>	<Null>	1561	Point
<Null>	1	<Null>	<Null>	MH-1264	<Null>	<Null>	<Null>	<Null>	1562	Point
<Null>	1	<Null>	<Null>	MH-936	<Null>	<Null>	<Null>	<Null>	1563	Point
<Null>	1	<Null>	<Null>	MH-665	<Null>	<Null>	<Null>	<Null>	1564	Point
<Null>	1	<Null>	<Null>	MH-671	<Null>	<Null>	<Null>	<Null>	1565	Point
<Null>	1	<Null>	<Null>	MH-659	<Null>	<Null>	<Null>	<Null>	1566	Point
<Null>	1	<Null>	<Null>	MH-1266	<Null>	<Null>	<Null>	<Null>	1567	Point
<Null>	1	<Null>	<Null>	MH-656	<Null>	<Null>	<Null>	<Null>	1568	Point

map_date	map_method	mapped_by	st_name	struct_id	town_cb_id	UC_struct_id	xy_loc_x_c	xy_loc_y_c	ObjectId	Shape *
<Null>	1	<Null>	<Null>	MH-661	<Null>	<Null>	<Null>	<Null>	1569	Point
<Null>	1	<Null>	<Null>	MH-662	<Null>	<Null>	<Null>	<Null>	1570	Point
<Null>	1	<Null>	<Null>	MH-674	<Null>	<Null>	<Null>	<Null>	1571	Point
<Null>	1	<Null>	<Null>	MH-937	<Null>	<Null>	<Null>	<Null>	1572	Point
<Null>	1	<Null>	<Null>	MH-938	<Null>	<Null>	<Null>	<Null>	1573	Point
<Null>	1	<Null>	<Null>	MH-667	<Null>	<Null>	<Null>	<Null>	1574	Point
<Null>	1	<Null>	<Null>	MH-939	<Null>	<Null>	<Null>	<Null>	1575	Point
<Null>	1	<Null>	<Null>	MH-668	<Null>	<Null>	<Null>	<Null>	1576	Point
<Null>	1	<Null>	<Null>	MH-940	<Null>	<Null>	<Null>	<Null>	1577	Point
<Null>	1	<Null>	<Null>	MH-1468	<Null>	<Null>	<Null>	<Null>	1578	Point
<Null>	1	<Null>	<Null>	MH-10	<Null>	<Null>	<Null>	<Null>	1579	Point
<Null>	1	<Null>	<Null>	MH-11	<Null>	<Null>	<Null>	<Null>	1580	Point
<Null>	1	<Null>	<Null>	MH-1471	<Null>	<Null>	<Null>	<Null>	1581	Point
<Null>	1	<Null>	<Null>	MH-1474	<Null>	<Null>	<Null>	<Null>	1582	Point
<Null>	1	<Null>	<Null>	MH-561	<Null>	<Null>	<Null>	<Null>	1583	Point
<Null>	1	<Null>	<Null>	MH-654	<Null>	<Null>	<Null>	<Null>	1584	Point
<Null>	1	<Null>	<Null>	MH-1548	<Null>	<Null>	<Null>	<Null>	1585	Point
<Null>	1	<Null>	<Null>	MH-652	<Null>	<Null>	<Null>	<Null>	1586	Point
<Null>	1	<Null>	<Null>	MH-651	<Null>	<Null>	<Null>	<Null>	1587	Point
<Null>	1	<Null>	<Null>	MH-650	<Null>	<Null>	<Null>	<Null>	1588	Point
<Null>	1	<Null>	<Null>	MH-22	<Null>	<Null>	<Null>	<Null>	1589	Point
<Null>	1	<Null>	<Null>	MH-649	<Null>	<Null>	<Null>	<Null>	1590	Point
<Null>	1	<Null>	<Null>	MH-560	<Null>	<Null>	<Null>	<Null>	1591	Point
<Null>	1	<Null>	<Null>	MH-648	<Null>	<Null>	<Null>	<Null>	1592	Point
<Null>	1	<Null>	<Null>	MH-1252	<Null>	<Null>	<Null>	<Null>	1593	Point
<Null>	1	<Null>	<Null>	MH-1230	<Null>	<Null>	<Null>	<Null>	1594	Point
<Null>	1	<Null>	<Null>	MH-941	<Null>	<Null>	<Null>	<Null>	1595	Point
<Null>	1	<Null>	<Null>	MH-1537	<Null>	<Null>	<Null>	<Null>	1596	Point
<Null>	1	<Null>	<Null>	MH-1256	<Null>	<Null>	<Null>	<Null>	1597	Point
<Null>	1	<Null>	<Null>	MH-1473	<Null>	<Null>	<Null>	<Null>	1598	Point
<Null>	1	<Null>	<Null>	MH-1472	<Null>	<Null>	<Null>	<Null>	1599	Point
<Null>	1	<Null>	<Null>	MH-1272	<Null>	<Null>	<Null>	<Null>	1600	Point
<Null>	1	<Null>	<Null>	MH-1306	<Null>	<Null>	<Null>	<Null>	1601	Point
<Null>	1	<Null>	<Null>	MH-563	<Null>	<Null>	<Null>	<Null>	1602	Point
<Null>	1	<Null>	<Null>	MH-1478	<Null>	<Null>	<Null>	<Null>	1603	Point
<Null>	1	<Null>	<Null>	MH-1479	<Null>	<Null>	<Null>	<Null>	1604	Point
<Null>	1	<Null>	<Null>	MH-1383	<Null>	<Null>	<Null>	<Null>	1605	Point

map_date	map_method	mapped_by	st_name	struct_id	town_cb_id	UC_struct_id	xy_loc_x_c	xy_loc_y_c	ObjectId	Shape *
<Null>	1	<Null>	<Null>	MH-1385	<Null>	<Null>	<Null>	<Null>	1606	Point
<Null>	1	<Null>	<Null>	MH-1384	<Null>	<Null>	<Null>	<Null>	1607	Point
<Null>	1	<Null>	<Null>	MH-548	<Null>	<Null>	<Null>	<Null>	1608	Point
<Null>	1	<Null>	<Null>	MH-549	<Null>	<Null>	<Null>	<Null>	1609	Point
<Null>	1	<Null>	<Null>	MH-502	<Null>	<Null>	<Null>	<Null>	1610	Point
<Null>	1	<Null>	<Null>	MH-550	<Null>	<Null>	<Null>	<Null>	1611	Point
<Null>	1	<Null>	<Null>	MH-551	<Null>	<Null>	<Null>	<Null>	1612	Point
<Null>	1	<Null>	<Null>	MH-552	<Null>	<Null>	<Null>	<Null>	1613	Point
<Null>	<Null>	<Null>	<Null>	MH-1410	<Null>	<Null>	<Null>	<Null>	1614	Point
<Null>	1	<Null>	<Null>	MH-1411	<Null>	<Null>	<Null>	<Null>	1615	Point
<Null>	1	<Null>	<Null>	MH-1412	<Null>	<Null>	<Null>	<Null>	1616	Point
<Null>	1	<Null>	<Null>	MH-1234	<Null>	<Null>	<Null>	<Null>	1617	Point
<Null>	1	<Null>	<Null>	MH-1417	<Null>	<Null>	<Null>	<Null>	1618	Point
<Null>	1	<Null>	<Null>	MH-1418	<Null>	<Null>	<Null>	<Null>	1619	Point
<Null>	1	<Null>	<Null>	MH-1414	<Null>	<Null>	<Null>	<Null>	1620	Point
<Null>	1	<Null>	<Null>	MH-1415	<Null>	<Null>	<Null>	<Null>	1621	Point
<Null>	1	<Null>	<Null>	MH-1421	<Null>	<Null>	<Null>	<Null>	1622	Point
<Null>	1	<Null>	<Null>	MH-1420	<Null>	<Null>	<Null>	<Null>	1624	Point
<Null>	1	<Null>	<Null>	MH-1422	<Null>	<Null>	<Null>	<Null>	1625	Point
<Null>	1	<Null>	<Null>	MH-1423	<Null>	<Null>	<Null>	<Null>	1626	Point
<Null>	1	<Null>	<Null>	MH-1566	<Null>	<Null>	<Null>	<Null>	1627	Point
<Null>	1	<Null>	<Null>	MH-1567	<Null>	<Null>	<Null>	<Null>	1628	Point
<Null>	1	<Null>	<Null>	MH-1425	<Null>	<Null>	<Null>	<Null>	1629	Point
<Null>	1	<Null>	<Null>	MH-1424	<Null>	<Null>	<Null>	<Null>	1630	Point
<Null>	1	<Null>	<Null>	MH-1437	<Null>	<Null>	<Null>	<Null>	1632	Point
<Null>	1	<Null>	<Null>	MH-1436	<Null>	<Null>	<Null>	<Null>	1633	Point
<Null>	1	<Null>	<Null>	MH-1435	<Null>	<Null>	<Null>	<Null>	1634	Point
<Null>	1	<Null>	<Null>	MH-1434	<Null>	<Null>	<Null>	<Null>	1635	Point
<Null>	1	<Null>	<Null>	MH-1433	<Null>	<Null>	<Null>	<Null>	1636	Point
<Null>	1	<Null>	<Null>	MH-501	<Null>	<Null>	<Null>	<Null>	1638	Point
<Null>	1	<Null>	<Null>	MH-1656	<Null>	<Null>	<Null>	<Null>	1642	Point
<Null>	1	<Null>	<Null>	MH-500	<Null>	<Null>	<Null>	<Null>	1643	Point
<Null>	1	<Null>	<Null>	MH-1396	<Null>	<Null>	<Null>	<Null>	1646	Point
4-Jun-18	Aerial Photo	Student	Kelley	MH-678	Kelley 2	SWM-678	42.14759	-71.40779	492	Point