

## RESPONSIBILITY

**794 STRIKE DETAIL** 

(2 Places)

DOOR AND FRAME MANUFACTURERS ARE RESPONSIBLE FOR PROVIDING ADEQUATE CONSTRUCTION OR REINFORCEMENTS FOR PROPER INSTALLATION OF HARDWARE SHOWN. ALL ARCHITECTURAL BUILDERS HARDWARE MUST BE INSTALLED ON PROPERLY REINFORCED DOORS AND FRAMES, REGARDLESS OF TYPE, MATERIAL, OR METHOD OF CONSTRUCTION.

## 6210, 6215, 7210 & 7215 Narrow Stile Surface Vertical Rod Panic Devices

1/2

(13)

11/16

(17.5)

© Rods, Deadbolt and Floor Strike

Application for Pairs of Aluminum Doors and Blade Stop Frame with 1/2" Threshold and Optional 794 Floor Strike; 791 Top Strike 1-855-557-5078 Ext. 2

www.accentra-assaabloy.com

ACCENTRA ASSA ABLOY

Experience a safer and more open world

Copyright © 2015, 2023, 2024, ASSA ABLOY ACCENTRA $^{\sim}$  Access and Egress Hardware Group, Inc. All rights reserved. Reproduction in whole or in part without the express written permission of ASSA ABLOY Access and Egress Hardware Group, Inc. is prohibited.

 SUPERSEDES
 11/15
 DO NOT SCALE DRAWING

 TEMPLATE NUMBER
 SHEET
 DATE

 7472-0011
 1 of 1
 04/24