




D1 mm	L1 mm	B mm	L mm	D mm	K mm
5	50	30	72	11	4
6	60	35	87	14	5
8	80	50	115	18	6
10	100	60	144	22	8