























№		PCS	 mm	 mm	 mm
1		2	19	52	2200
2		65	19	92	2200
3		42	19	92	484
5		1	38	38	1842
6		1	48	84	1290
7		1	38	38	1842
8		2		305	2200
9		1	40	60	2200
10		4	15	35	1800
11G		1		585	1760
11D		1		585	1760
12		6	OSB	733	1200
13A		2		1000	2200
13B		1		500	2200
14		8	15	35	1200
15		4	13	92	1225
17		2	15	75	145
18		6			
19		3			
19.1		1			
20		2	15	35	855
21		4	OSB	35	1100
22		1	15	69	1180
24		4	15	35	1100

1





Int.

2 21 pieces
1 1 pieces

2 22 pieces

6
5

8
7

2 22 pieces

3 21 pieces
1 1 pieces

3



22

C x5


B x12

Int.


Ext.




$$a=b$$




4




5









6







8










17



B x4