














LUX






PUSH



1,5h





OPCJA A




E88




x...(2)

OPCJA B





L11



x...(2)






PUSH




A6 $\varnothing 7 \times 40$ x...(8)	G50 6×13 x...(12)	F15 x...(8)		
H3 280mm x...(4)	I1 x...(6)	W1 x...(1)	W10 300mm x...(1)	
K1 $\varnothing 15 \times 12$ x...(8)	G8 4×30 x...(4)	N1 $M4 \times 9$ x...(4)	G56 4×16 x...(32)	
K10 x...(8)	B1 $\varnothing 8 \times 35$ x...(8)	W2 x...(1)	P4 x...(6)	

I


OPCJA A



W1




0,5h






II


OPCJA B











PUSH




W1




III




IV





1.






2.





V





VI




VII





VIII




IX




$$a = b$$



X




XI




XII

OPCJA B




PUSH




G50

L11




L11

L11



L11



XIII

