


STYLE NO: **T181**

DESCRIPTION: PW3 Hi-Vis Cotton Comfort T-Shirt S/S



	Measurements	XS	S	M	L	XL	XXL	3XL	4XL	5XL	Tolerance (+)
A	Chest	100	104	108	116	124	136	144	152	160	1
B	Across Back, from 15cm below neck	44	46	48	50	53	55	57	59	61	0.5
D	Outside sleeve length, including cuff	20	20	20.25	20.5	20.75	21	21.25	21.5	21.75	0.5
J	Hem circumference	100	104	108	116	124	136	144	152	160	0.5
K	Center back length	76	76	76	76	77	78	79	80	81	1