



Uwaga:


1. W przypadku jakichkolwiek niejasności prosimy skonsultować się z wykwalifikowanym elektrykiem.
2. Instalacja powinna być wykonana zgodnie z krajowymi regulacjami w zakresie montażu urządzeń elektrycznych. Instalacja doprowadzająca prąd do urządzenia powinna także spełniać krajowe wymagania bezpieczeństwa.
3. Przed montażem upewnij się, że napięcie zostało wyłączone. Wyłącz także napięcie na bezpieczniku i upewnij się, że nie ma możliwości przypadkowego załączenia napięcia podczas montażu.
4. Oprawę należy użytkować w zastosowaniach adekwatnych do jej stopnia ochrony IP oraz IK.
5. Sprawdź położenie przewodów doprowadzających prąd (a także ew. innych przewodów) w celu uniknięcia ich uszkodzenia podczas montażu oprawy.
6. Zastosuj właściwą metodę montażu oprawy w zależności od konstrukcji powierzchni montażowej.
7. Przewody doprowadzające napięcie nie powinny stykać się z nagrzewającymi się elementami oprawy.
8. Instalując przewody należy zwrócić uwagę, aby nie były one odkształcane ani naprężane.
9. Przed zakończeniem instalacji sprawdź poprawność wszystkich połączeń i upewnij się, że żaden przewód ani śrubka nie wypadła z kostki montażowej.
10. Nie należy montować oprawy na wilgotnych powierzchniach (świeżo tynkowanych lub malowanych) gdyż może to doprowadzić do odbarwienia kolorów.
11. Upewnij się, że przewody których używasz do instalacji mają odpowiednią odporność na podwyższoną temperaturę.




MODEL: AG-LG-210W




MODEL: AG-LG-310W



MODEL: AG-LG-450W



MODEL: AG-LG-750W



MODEL: AG-LG-520W




Importer:


BERGE Wojciech Mincgerger, ul. Piłsudskiego 11, 32-050 Skawina POLAND,
T.: +48 538 891 929 MAIL: kontakt@berge.pl PL944-212-47-03

Attention:


1. In case of any ambiguity, please consult a qualified electrician.
2. The installation should be carried out in accordance with national regulations for the installation of electrical equipment. The installation supplying electricity to the appliance should also meet national safety requirements.
3. Make sure the voltage is turned off before installation. Also turn off the voltage at the fuse and make sure that there is no possibility of accidental switching on of voltage during installation.
4. The luminaire should be used in applications adequate to its IP and IK rating.
5. Check the location of the power supply wires (and possibly other wires) to avoid their damage during installation of the luminaire.
6. Use the correct method of mounting the luminaire depending on the design of the mounting surface.
7. The voltage supply wires should not come into contact with the heating elements of the luminaire.
8. When installing the wires, make sure that they are not deformed or stressed.
9. Before completing the installation, check the correctness of all connections and make sure that no wire or screw has fallen out of the mounting block.
10. Do not install the luminaire on damp surfaces (freshly plastered or painted) as this may lead to color discoloration.
11. Make sure that the wires you use for installation have adequate resistance to elevated temperatures.




MODEL: AG-LG-210W




MODEL: AG-LG-450W



MODEL: AG-LG-310W



MODEL: AG-LG-750W



MODEL: AG-LG-520W



Importer:

BERGE Wojciech Mincgerger, ul. Piłsudskiego 11, 32-050 Skawina POLAND,
T.: +48 538 891 929 MAIL: kontakt@berge.pl PL944-212-47-03