





















№		PCS			
			mm	mm	mm
1		6		980	1900
2		2		980	1900
3		1		89	1234
4D		1		363	1900
4K		1		363	1900
5		1		582	1754
6		1		582	1754
7		2		300	1517
8		2		300	1517
9		9	38	38	1324
9.1		2	38	38	672
9.2		7	38	38	1636
9.3		7	12	35	300
9.4		35	19	92	1324
9.5		35	19	92	672
10		2		363	1470
11		2	40	60	1700
12		1	40	60	1700
13		2	40	60	470
14		1	40	60	470
15		4	17	47	1085
15.1		4	17	47	1470

16		1	30	60	1234
17		50	19	92	1660
18		4	15	35	1085
19		1	58	70	1810
20		1	58	70	1810
21		4	13	92	1700
22		2		547	1363
23		2	15	35	1835
23.1		3	15	35	1848
24		4	17	47	1900
25		2	15	35	234
26		1	58	70	1324
27		2	15	75	145
28		48	10	10	390
29		48	10	10	190
30		2			
30.1		4			
31		8			
32		6			
33		5			
34		10			
35		10			
36		1			
37		2			
38		1			
39		24	4	187	388



1



F x16




I x280




A x28

9.3




$\sim 2\text{mm}$


2




3




4






5




6




7






8




9












A x2





A x4






14






16




B_{x4}

37


Ø12mm



37




B_{x4}





37

B_{x2}



37

17



18

14-16mm


14-16mm

35




34

22

22




19





Ø3

30






Ø3




30

B x2

30





21

A x12

15.1

!!!

15

15.1




25

23.1

23

B x104

24



22

18

D_{x16}

A_{x150}

17

2mm

