

# CERTIFICATE OF COMPLIANCE

Certificate Number MH16651  
Report Reference MH16651-19910703  
Issue Date 2020-MARCH-25

Issued to: KOREA BATTERY CO LTD  
134, 1gongdan-ro 6-gil  
Gumi-si Gyeongsangbuk-do 39373 KOREA

This certificate confirms that  
representative samples of COMPONENT - BATTERIES, STANDBY  
SEE ADDENDUM PAGE FOR MODELS


Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: UL 1989 Standard for Safety For Standby Batteries  
Additional Information: See the UL Online Certifications Directory at  
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



*B. Mahlen*

Bruce Mahlenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

Certificate Number MH16651  
Report Reference MH16651-19910703  
Issue Date 2020-MARCH-25

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

## Models/Product

Component - Sealed cell, lead-acid secondary batteries Models FNC 610, FNC 612, FNC 640, FNC 645, FNC 650, FNC 660, FNC 670, FNC 695, FNC 6100, FNC 6120, FNC 1212, FNC 1219, FNC 1220, FNC 1230, FNC 1240, FNC 1245, FNC 1265, FNC 1270, FNC 1272, FNC 12120, FNC 12150, FNC 12170, FNC 12210, FNC 12190, FNC 12240, FNC 12260, FNC 12310, FNC 12340, FNC 12350, FNC 12400, FNC 12420, FNC 12650, FNC 12800, FNC 121000, FNC 121200, FNC 121500, and FNC 122000; PNB 610, PNB 612, PNB 640, PNB 645, PNB 650, PNB 660, PNB 670, PNB 695, PNB 6100, PNB 6120, PNB 1212, PNB 1219, PNB 1220, PNB 1230, PNB 1240, PNB 1245, PNB 1265, PNB 1270, PNB 1272, PNB 12120, PNB 12150, PNB 12170, PNB 12210, PNB 12190, PNB 12180, PNB 12240, PNB 12260, PNB 12310, PNB 12300, PNB 12340, PNB 12350, PNB 12400, PNB 12420, PNB 12650, PNB 12650S, PNB 12800, PNB 12700, PNB 121000, PNB 121000H, PNB 121000S, PNB 121200, PNB121200H, PNB121200S, PNB 121500, and PNB 122000; PNGB 12800, PNGB 121000, PNGB 121200, PNGB 121500, PNGB 122000, PNC 610, PNC 612, PNC 640, PNC 645, PNC 650, PNC 660, PNC 670, PNC 695, PNC 6100, PNC 6120, PNC 1212, PNC 1219, PNC 1220, PNC 1230, PNC 1240, PNC 1245, PNC 1265, PNC 1270, PNC 1272, PNC 12120, PNC 12150, PNC 12170, PNC 12210, PNC 12190, PNC 12240, PNC 12260, PNC 12310, PNC 12340, PNC 12350, PNC 12400, PNC 12420, PNC 12650, PNC 12800, PNC 121000, PNC 121200, PNC 121500, and PNC 122000; SG 800H, SG 1000H, SG 1200H, SG 1500H and SG 2000H.

원 본 대 조 필



*B. Mahlen*

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

