



# Fișă tehnică | Număr articol: 221-505/000-004

Mounting carrier; for 5-conductor terminal blocks; 221 Series - 4 mm<sup>2</sup>; for screw mounting; black



[www.wago.com/221-505/000-004](http://www.wago.com/221-505/000-004)



RoHS  Compliant

[BOMcheck.net](https://www.bomcheck.net)

Culoare: ■

## Date

### Geometrical Data

Width	35 mm / 1.378 inch
Height from the surface	16,9 mm / 0.665 inch
Depth	52,8 mm / 2.079 inch

### Material Data

Color	black
Insulation material	Polyamide 66 (PA 66)
Flammability class per UL94	V0
Weight	4,9 g

Supus modificărilor.

WAGO Kontakttechnik GmbH & Co. KG  
/Representative Office Romania  
Sos. Pipera-Tunari nr. 1/1  
building 1, 2nd floor | 077190 Voluntari, Ilfov  
Tel.: +40-(0)31 421 85 68 | Email: info-RO@wago.com

Aveți întrebări despre produsele noastre?  
Vă stăm la dispoziție pentru preluarea apelului la +40 (0) 31 421 85 68.

## Commercial data

Packaging type	BOX
Country of origin	CN
GTIN	4055143640848
Customs tariff number	39269097900

## Counterpart

## Descărcări

### Documentation

#### Additional Information


Technical explanations	Apr 3, 2019	pdf 2,1 MB	Descărcare
------------------------	-------------	---------------	------------

## CAD/CAE-Data


### CAD data

2D/3D Models 221-505/000-004	URL	Descărcare
------------------------------	-----	------------

## Installation Notes




Inserting a connector into the mounting carrier.




Removing a connector from the mounting carrier.

### Inserting a conductor

Supus modificărilor.




Inserting a conductor.




Horizontal screw mounting



Vertical screw mounting



Horizontal mounting via snap-in foot



Vertical mounting via snap-in foot

### Strain Relief

Supus modificărilor.




Use a cable tie to secure the conductors to the strain relief plate.



The strain relief plate can be removed.

### Testing



Testing a connector mounted on the carrier via test slot.


### Application



Connecting a light to the mains.

### Marking

Supus modificărilor.



Labeling

Supus modificărilor.