

Water Committee Report to BEM Board December 2021

Nothing new to report except that the committee continues to be concerned that the following projects need to be push ahead:

Lower flume – needs to be shored up so water is not bypassing flume

Steel Tank – need to have piping repaired so that it can be used to store water so concrete tank can be used and then upper storage tank by sand shed can be serviced

Sunset Lake Outlet Works – needs to have gate valve repaired so that it can store water

Roy McCutchen