



## SERVICE TROLLEY

### PART LIST




### ASSEMBLY PROCEDURE



1

Make sure holes of castors, shelves and frames face the same direction before screwing.

3



3

Completion of Assembly



**CABLEMATIC**

Max.Loading:50Kgs for each shelf and 100Kgs for 2 shelves.