Calipers



FEATURES

- Digital caliper and mechanical micrometer measuring set
- Made of stainless steel
- Maximum caliper measurement of 150mm/6"
- Maximum micrometer measurement of 25mm

RS PRO Digital Measuring Set

RS Stock No.: 2436622, 2436841, 2436842, 2436843, 2436844, 2436845



RS Professionally Approved Products bring to you professional quality parts across all product categories. Our product range has been tested by engineers and provides a comparable quality to the leading brands without paying a premium price.



Product Description



Hardened stainless steel frame and measuring jaws

Thumb roll adjustment Knurled locking screw

Depth rod

Clear LCD Display Large 11mm digits Inch/Metric conversion

Origin setting


Resolution: 0.01mm / 0.0005" Repeatability: 0.01mm / 0.0005"

4 Way measurement: Individual serial numbers

Power: 1 x Silver oxide battery SR44 - 1.55v

Operating temperature: 5 - 40°C Relative humidity: Maximum 80%

Warranty: 1 year



1 Metric / Inch Conversion Button 2 Knurled Locking Screw

3 LCD Display

4 Depth Measuring Blade

5 Caliper Beam

6 Thumbroll Fine Adjustment

7 Battery Cover

8 Zero Set Button

9 Power Button ON/OFF

10 External Measuring Jaws

11 Step Measuring Faces

12 Internal Measuring Jaws

Manufacturers code 2436622

Electronic Caliper 0-150mm/0-6" Description


General Specifications

Range	150mm/6"	
Resolution	0.01mm/0.0005"	
Repeatability	0.01mm/0.0005"	
Accuracy	±0.02mm (≤ 100mm) ±0.03mm (≥ 100mm – 150mm)	
External Jaw Length	40mm	
Internal Jaw Length	18mm	

Calipers



4 Way Measurement Feature



OPERATING INSTRUCTIONS

When using the Caliper for the first time or after a period of non-use, wipe the beam scale with a dry clean cloth to remove any condensation or oil deposits.

Prior to setting the caliper for measuring, first clean the measuring faces with a soft clean cloth or paper.

Switch Caliper ON


Move Caliper jaws together.

Select required measuring mode Inch / Metric.

Zero display, caliper is now ready for direct measurement.

Caliper can be zeroed at any position within its range, to provide relative measurements.

Caliper provides 4 way measurements, External, Internal, Step and Depth.



Calipers



General Specifications

Resolution	0.01mm
Repeatability	0.01mm
Accuracy	0.004mm/±0.002mm

OPERATING CARE

Clean measuring faces with dry soft cloth Keep away from strong magnetic fields Prevent ingress of oil / liquids into electronics

Remove battery if instrument is not used for a long period of time

Do not disassemble or drop the instrument

Do not mark instrument by engraving, etching or any other permanent marking method, as this will invalidate the warranty

FAULT FINDING

Fault	Cause	Action
Display flashes	Battery voltage below 1.45volts	Replace battery
Display frozen	Circuit overload	Remove battery and replace after 4 minutes
Accuracy below specification but within +/- 0.1mm	Dirt in sensor	Remove slider cover assembly, clean face of sensor with dry clean compressed air (5kg/cm²)
No display	Poor battery contact Dead battery	Remove battery and carefully adjust battery contacts, replace battery. Replace battery.