Report: 141/

100 Football pitch Project



Football Ground: R. Rasgetheemu Site visit report – supporting information

9th April 2023	9th April 2023			
R. Rasgetheemu (Is	R. Rasgetheemu (Island)			
Hot dry and sunny	Hot dry and sunny			
Council President: 0	Council President: Council representatives and former Council President			
Island:	R. Rasgetheem			
Contact name:	Mr. Ibrahim Mohamed			
Designation	Council president			
Address:				
Tel:				
e-mail				
Fax:				
	R. Rasgetheemu (Is Hot dry and sunny Council President: 0 Island: Contact name: Designation Address: Tel: e-mail			

Scope of the Project	Design and construction of full-size football Artificial turf pitch (Subbase)					
	Category of pitch requirement Level of competition and activities & requirement		FIFA Recommended			
			National Level			
Proposed usage	Level of play		National Level			
	Intensity of paly per week / year		+/- 36 hrs. /week			
Field orientation	North / South					
Proposed filed dimensions			1			
		Length		Width 68m		
	Field size	105m				
	Run – off area	North	South	West	East	
		3m	3m	2.5m	2.5m	
	Total Green area (synthetic)	111m x 73m				
Spectator Area	No spectator	<u> </u>				
Fencing	No build boundary wall, no fe	No build boundary wall, no fence				

Ground Conditions: Proposed site is in the Northwest side of the island; 1 trail holes were made. Proposed site is the existing football ground, Noticed the ground level is in the same but slightly higher on West side of the plot, mostly covered with grass around the existing ground, in the middle area partly cleared, near the perimeter heavily grown grass small trees on the part if new ground to be extended West, West side is covered with trees and bush. must be removed, level and compact to create subbase ready for installation

Groundwater evidence	Location is in the Northwest of the island, according to the representatives on site water is likely more than 3 feet deep, no water found in any trial holes
Topography	Existing football ground, surface with mostly covered with heavily grown grass, generally a football pitch size area is flat
Drain Outlet	Drainage is designed with enough soak pits due to the size of the area.
Existing Service & sports lighting	No Existing building, Futsal pitch located north of the plot with some lights.
Disposal of Spoil	All removed spoil sand disposal must be finalized with a consent from local council.









distance not far from the harbor to the Proposed site, but existing old structures may cause some degree of difficulty, but the road is accessible,				
It's located Northwest of the island, existing football pitch with heavy grown grass on the				
sides, no infrastructure on site				
No significant time of the year				
No				
base on design and drawings provided,				
Plot of land allocated is without boundary wall, orientation of the pitch and footprint must be laid in a way space is best utilized.				
ТВС				
ТВС				

Other	Consideration
-	Possible work restriction on transportation of heavy vehicles
-	Orientation must be changed to best utilize the space for further development of the facility, size of the plot is not very large.
-	Easy access to the facility for vehicles (Ambulance)
-	Potential outlet for field drainage connecting to local sewerage system
-	Possible shift to west to create space may cause site clearance.

PPROPOSED INDICATIVE LAYOUT

Due North existing futsal pitch Due south an existing building (not very large) Site clearance including removal of trees Not to large.