



S.S Mooring point

All measurements are in millimeter
Diagram Are not to scale




S.S Mooring Bolt & Nut

All measurements are in millimeter
Diagram Are not to scale




S.S Ring

All measurements are in millimeter
Diagram Are not to scale




S.S Swivel

All measurements are in millimeter
Diagram Are not to scale




Thimble Bush(Nylon)

All measurements are in millimeter
Diagram Are not to scale




Cross section




Side view

Thimble washer(Nylon)




Cross section



Side view


Swivel Pin

All measurements are in millimeter
Diagram Are not to scale



S.S Swivel

All measurements are in millimeter
Diagram Are not to scale



Details on Page 8.
Diagram 01 to 05

Front view




Diagram : 01




Diagram : 02




Diagram : 03




Diagram : 05




Diagram : 04