LIST OF EQUIPMENT REQUIRED

LIST OF EQUIPMENT REQUIRED		
	Equipment	Drawing or sample
	Welding Table: Work Surface Width 57 In., Work Surface Depth 27 In., Work Surface Thickness 0.375 In., Load Capacity 1000 lb., Overall Height 90 In., Overall Width 60 In., Overall Depth 30 In., Work Surface Pattern X-Pattern 3/16 In. Steel Top, Adjustable Height No, Construction Steel, Finish Painted	
2	Welding Magnets: 4Pcs 4" 50 lbs Arrow Welding Magnets Metal Working Mig Tools and Equipment Arrow Workshop Welder Soldering, 45, 90, 135 Degree Angle Magnet	a same o
3	Chipping Hammer	Constant of the Constant of th
4	Inverter based welder 200 Amps	STÅRO STÅRO STÅRO Abouths Worrenty on Registration
5		

5	Gas Welding Goggle (Colour)	and the same of th
6	Welding Electrode Holder 300AMP	
7	Safety Helmet with welding helmet	
8	Welders Leather Apron	
	SON SON	

Tig Welding Plant	
Mig Welding Plant	Might be a second and a second
Plasma Welding Machine	
	Mig Welding Plant