## **TECHNICAL DATASHEET**





## CONTAIN



5		1/2"	x1	8mm
	$\bigcirc$	3/8"	x1	8mm
		1/4"	x1	6mm
		1/2"	x2	16, 21mm
		3/8"	x1	18mm
2		1/2"	x12	8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19mm
		1/2"	x7	1.27, 1.5, 2, 2.5, 3, 4, 5mm
		1/4"	x1	
		1/4"	x1	
		1/4"	x1	
		1/2"	x1	T70
		1/2"	x1	14mm
A	4	1/4"	хЗ	PHO, PH1, PH2
	*		хЗ	PZO, PZ1, PZ2
	$\bigcirc$		х4	3, 4, 5, 6mm
			x4	SL4, SL5.5, SL6.5, SL7
			x8	T8, T9, T10, T15, T20, T25, T27, T30
			x8	T8, T9, T10, T15, T20, T25, T27, T30

$\Box$	$\bigcirc$	8mm	x4	7, 8, 10, 12mm
Η.	$\langle \bigcirc \rangle$	6mm	х6	2, 2.5, 3, 4, 5, 6mm
	$\ominus$	8mm	x3	SL8, SL10, SL12
	4	8mm	x3	PH2, PH3, PH4
	*	8mm	хЗ	PZ2, PZ3, PZ4
_	$\Diamond$	8mm	х5	T40, T45, T50, T55, T60
		6mm	x3	T5, T6, T7
-	$\Diamond$	8mm	x5	T40, T45, T50, T55, T60
		6mm	x1	T7
	$\Diamond$	8mm	х4	M10, M11, M12, M13
		6mm	х5	M5, M6, M7, M8, M9
		8mm	x2	M10, M12
		6mm	x3	M5, M6, M8
	$\bowtie$	8mm	x1	TS50
	\(\frac{\psi}{2}\)	6mm	x8	TS10, TS15, TS20, TS25, TS27, TS30, TS40, TS45
	$\Diamond$	6mm	x4	0, 1, 2, 3mm
	8		хЗ	6, 8, 10mm
	3		х4	4, 6, 8, 10mm
	$\langle \rangle \rangle$		x3	1, 2, 3mm
			х4	1, 2, 3, 4mm
		6mm	x1	1/4"