TECHNICAL DATASHEET





CONTAIN

	1/2"	x17	10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 24, 27, 30, 32mm
	3/8"	x10	10, 11, 12, 13, 14, 15, 16, 17, 18, 19mm
	1/4"	x13	4, 4.5, 5, 5.5, 6, 7, 8, 9, 10, 11, 12, 13, 14mm
	1/2"	x5	16, 17, 18, 19, 22mm
	3/8"	х6	10, 11, 12, 13, 14, 15mm
	1/4"	x7	4, 5, 6, 7, 8, 9, 10mm
	1/2"	x2	E20, E24
	3/8"	х6	E10, E11, E12, E14, E16, E18
	1/4"	x5	E4, E5, E6, E7, E8
	12	хЗ	1/2" - 3/8" - 1/4"
	1/2"	x1	125mm
	3/8"	x1	125mm
	1/4"	x2	50, 100mm
	1/2"	x1	250mm

	\neg		
		x3	1/2" - 3/8" - 1/4"
	1/2"	x2	16, 21mm
	3/8"	x1	18mm
5	1/2"	x1	8mm
	3/8"	x1	8mm
	1/4"	x1	6mm
		x7	1.27, 1.5, 2, 2.5, 3, 4, 5mm
		x1	1/4"
	—	x1	1/4"
A	+	хЗ	PH1, PH2, PH3
	*	хЗ	PZ1, PZ2, PZ3
	1/4"	x5	2, 3, 4, 5, 6mm
		x3	SL4, SL5.5, SL7
_	$\overline{\Box}$	x8	T8, T9, T10, T15, T20, T25, T27, T30
	\$	x8	T8, T9, T10, T15, T20, T25, T27, T30

	\bigcirc		x11	T5, T6, T7, T8, T9, T10, T15, T20, T25, T27, T30
H	\Diamond	6mm	x9	T7, T10, T15, T20, T25, T27, T30, T40, T45
			x5	M5, M6, M7, M8, M9
	\Diamond		x3	M5, M6, M8
	\oplus	8mm	x2	PH3, PH4
H	*		x2	PZ3, PZ4
	\bigcirc		x8	7, 8, 10, 12, 14mm
	\ominus		x3	SL8, SL10, SL12
	\Box		х6	T40, T45, T50, T55, T60, T70
	Ó		х6	T40, T45, T50, T55, T60, T70