
## FIȘA DE DATE TEHNICE





## INCLUDE



	3		x3	1/2" - 3/8" - 1/4"
	1/	2"	x2	16, 21mm
	3/	/8"	x1	18mm
5	1/	2"	x1	8mm
	3/	/8"	x1	8mm
	1/	<b>4</b> "	x1	6mm
			x7	1.27, 1.5, 2, 2.5, 3, 4, 5mm
ė.		)	x1	1/4"
	-		x1	1/4"
A	$\oplus$	- 1/ <b>4"</b>	хЗ	PH1, PH2, PH3
	*		х3	PZ1, PZ2, PZ3
U			х5	2, 3, 4, 5, 6mm
			x3	SL4, SL5.5, SL7
_	$\Box$		x8	T8, T9, T10, T15, T20, T25, T27, T30
_	ξĝζ		x8	T8, T9, T10, T15, T20,

	$\Diamond$		x11	T5, T6, T7, T8, T9, T10, T15, T20, T25, T27, T30
H	$\Diamond$	6mm	x9	T7, T10, T15, T20, T25, T27, T30, T40, T45
			x5	M5, M6, M7, M8, M9
	$\Diamond$		x3	M5, M6, M8
	$\oplus$	8mm	x2	PH3, PH4
-	*		x2	PZ3, PZ4
	$\bigcirc$		x8	7, 8, 10, 12, 14mm
	$\bigcirc$		x3	SL8, SL10, SL12
	$\bigcirc$		х6	T40, T45, T50, T55, T60, T70
	Ó		x6	T40, T45, T50, T55, T60, T70