



*Scott Municipal Utility*

**Water Service Line**  
**Material List**



*Scott Municipal Utility*

## WATER SERVICE LINE MATERIAL GLOSSARY

<b>L:</b>	Lead
<b>Unk:</b>	Unknown
<b>C:</b>	Copper
<b>P:</b>	Plastic
<b>Galv:</b>	Galvanized
<b>Y:</b>	Yes
<b>N:</b>	No
<b>SF:</b>	Single Family
<b>MF:</b>	Multi Family
<b>NonRes:</b>	Non Residential



## SERVICE LINE MATERIALS LIST

1. Algoma Rd, DePrey St., Judy Ln., & Debra Anne Dr . . . . . pg. 1 - 2
2. Champeau Rd . . . . . pg. 3 - 4
3. Edmund Rd, Charlotte Ct, Metzler Ct, Royal Bay Ridge Rd . . . . pg. 5 - 6
4. Rebecca Ann Dr, Jody Dr, Jake Dr, Settlement Heights Dr . . . . pg. 7
5. Hackberry Ct, Redbud Ct, Buckeye Way, Sussex Rd, . . . . . pg. 8
6. Rose Garden Way, Sandra Rose Ln . . . . . pg. 9
7. Norrie Dr, Scott Tower Dr, DeBauche Dr, Church Rd . . . . . pg. 10
8. Bay Settlement Rd . . . . . pg. 11 - 15
9. VanLanen Rd . . . . . pg. 16
10. Bay Heights Dr, Sandpiper Way, Heron Ln . . . . . pg. 17 - 18
11. Loon Ln, Egret Dr, Osprey Ln, Sparrow Ln . . . . . pg. 19
12. Nicolet Dr . . . . . pg. 20 - 21
13. Shore Crest, Scotchman . . . . . pg. 22 - 23
14. Meunier Ln, Fischer Rd, Point Ln, Web Rd, Grove Rd . . . . . pg. 24 - 25
15. Lloyd St, Agamaite Rd . . . . . pg. 26



Water mains in the Town are one of three types-

1. Ductile Iron
2. PVC (Plastic)
3. HDPE (Plastic)

Algoma Rd, DePrey St, Judy Ln, and Debra Anne Dr  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously Lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side Classification
	3524 Algoma Rd	N	C	N	1 inch	7/14/1992	P	1 inch	9/27/2002	SF	Plastic	Install after lead ban
	3530 Algoma Rd	N	C	N	1 inch	7/14/1992	Empty Lot		Empty Lot			Install after lead ban
	3538 Algoma Rd	N	C	N	1 inch	7/14/1992	P	1 inch	3/26/2018	SF	Plastic	Install after lead ban
	3560 Algoma Rd	N	C	N	1 inch	7/13/1992	P	1 inch	6/21/2007	SF	Plastic	Install after lead ban
	3574 Algoma Rd	N	C	N	1 inch	5/12/1981	C	1 inch	2/24/1982	SF	Copper	1980 Material Manual
	3579 Algoma Rd	N	C	N	1 inch	5/12/1981	C	1 inch	5/4/1982	SF	Copper	1980 Material Manual
	3596 Algoma Rd	N	C	N	1 inch	5/13/1981	C	1 inch	4/9/1982	SF	Copper	1980 Material Manual
	3650 Algoma Rd	N	P	N	1 inch	12/7/2020	Empty Lot		Empty Lot			Install after lead ban
	3656 Algoma Rd	N	P	N	1 inch	12/7/2020	P	1 inch	11/19/2024	NONRES	Plastic	Install after lead ban
	3660 Algoma Rd	N	C	N	1 inch	5/13/1981	C	1 inch	12/11/1981	SF	Copper	1980 Material Manual
	3665 Algoma Rd	N	P	N	2 inch	11/13/2023	P	2 inch	11/13/2023	NONRES	Copper + Plastic	Install after lead ban
	3675 Algoma Rd	N	P	N	2 inch	6/14/2020	P	2 inch	7/22/2020	NONRES	Plastic	Install after lead ban
	3680 Algoma Rd	N	C	N	1 inch	5/11/1981	C	1 inch	12/7/1981	SF	Copper	1980 Material Manual
	3686 Algoma Rd	N	C	N	1 inch	5/11/1981	C	1 inch	5/10/1983	SF	Copper	1980 Material Manual
	3696 Algoma Rd	N	C	N	1 inch	5/6/1981	C	1 inch	7/23/1982	SF	Copper	1980 Material Manual
	3697 Algoma Rd	N	C	N	1 inch	5/5/1981	Empty Lot		Empty Lot			1980 Material Manual
	3706 Algoma Rd	N	C	N	1 inch	6/12/1993	C	1 inch	5/30/1995	MF	Copper	Install after lead ban
	3728 Algoma Rd	N	C	N	1 inch	6/12/1993	C	1 inch	10/10/1996	SF	Copper	Install after lead ban
	3729 Algoma Rd	N	C	N	1 inch	3/17/1981	C	1 inch	3/29/1982	SF	Copper	1980 Material Manual
	3738 Algoma Rd	N	C	N	1 inch	5/4/1981	C	1 inch	10/21/1982	SF	Copper	1980 Material Manual
	3744 Algoma Rd	N	C	N	1 inch	5/4/1981	C	1 inch	10/20/1982	SF	Copper	1980 Material Manual
	3745 Algoma Rd	N	C	N	1 inch	5/27/1994	C	1 inch	3/16/1995	MF	Copper	Install after lead ban
	3753 Algoma Rd	N	C	N	1 inch	3/20/1981	C	1 inch	12/4/1981	SF	Copper	1980 Material Manual
LC12	3754 Algoma Rd	N	C	N	1 inch	4/30/1981	C	1 inch	11/2/1982	SF	Copper	1980 Material Manual
	3760 Algoma Rd	N	C	N	1 inch	5/4/1981	C	1 inch	10/27/1982	SF	Copper	1980 Material Manual
	3762 Algoma Rd	N	C	N	1 inch	4/30/1981	C	1 inch	12/9/1981	SF	Copper	1980 Material Manual
LC2	3763 Algoma Rd	N	C	N	1 inch	3/24/1981	C	1 inch	11/25/1981	SF	Copper	1980 Material Manual
	3769 Algoma Rd	N	C	N	1 inch	3/24/1981	C	1 inch	12/19/1981	SF	Copper	1980 Material Manual
	3770 Algoma Rd	N	C	N	1 inch	3/18/1981	C	1 inch	11/25/1981	SF	Copper	1980 Material Manual
	3775 Algoma Rd	N	C	N	1 inch	3/25/1981	C	1 inch	10/7/1982	SF	Copper	1980 Material Manual
	3781 Algoma Rd	N	C	N	1 inch	3/26/1981	C and G	1 inch	11/11/1982	SF	Galvanized	1980 Material Manual
D1	3789 Algoma Rd	N	C	N	1 inch	3/26/1981	C and G	1 inch	10/16/1982	SF	Galvanized	1980 Material Manual
	3797 Algoma Rd	N	C	N	1 inch	3/28/1981	C	1 inch	9/30/1982	SF	Copper	1980 Material Manual
							P					
	3817 Algoma Rd	N	P	N	2 inch	11/16/2023	(Not Connected)	2 inch	11/14/2023	NONRES	Plastic	Install after lead ban
							Not in use					
	3821 Algoma Rd	N	P	N	2 inch	6/5/2021	(undersized)					Install after lead ban
							P					
	3827 Algoma Rd	N	P	N	2 inch	11/16/2023	(Not Connected)	2 inch	11/14/2023			Install after lead ban
	3851 Algoma Rd	N	P	N	2 inch	11/16/2023	P	2 inch	11/14/2023	NONRES	Plastic	Install after lead ban
							Not in use					
	3859 Algoma Rd	N	P	N	2 inch	6/5/2021	(undersized)					Install after lead ban

Algoma Rd, DePrey St, Judy Ln, and Debra Anne Dr  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously Lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side Classification
	3861 Algoma Rd	N	P	N	2 inch	11/16/2023	P	2 inch	11/14/2023	NONRES	Plastic	Install after lead ban
	3866 Algoma Rd	N	C	N	1 inch	4/2/1981	C	1 inch	8/1/1982	SF	Copper	1980 Material Manual
	3874 Algoma Rd	N	C	N	1 inch	4/5/1986	C	1 inch	7/14/1986	SF	Copper	Install after lead ban
	3875 Algoma Rd	N	C	N	1 inch	4/6/1981	Disconnected					1980 Material Manual
	3888 Algoma Rd	N	C	N	1 inch	6/30/1990	C	1 inch	7/27/1990	SF	Copper	Install after lead ban
	3889 Algoma Rd	N	C	N	1 inch	4/7/1981	C	1 inch	12/22/1982	SF	Copper	1980 Material Manual
	3910 Algoma Rd	N	C	N	1 inch	6/26/1990	P	1 inch	8/12/1993	SF	Copper	Install after lead ban
	3913 Algoma Rd	N	C	N	1.5 inch	4/10/1981	C	1.5 inch	12/2/1981	NONRES	Copper	1980 Material Manual
	3920 Algoma Rd	N	C	N	1 inch	6/26/1990	C	1 inch	5/25/1994	SF	Copper	Install after lead ban
	3921 Algoma Rd	N	C	N	2 inch	5/20/2016	C	2 inch	6/1/2016	NONRES	Copper	Install after lead ban
	3967 Algoma Rd	N	C	N	2 inch	3/13/1998	C	2 inch	2/12/1999	NONRES	Copper	Install after lead ban
	3968 Algoma Rd	N	C	N	1.5 inch	6/2/1981	Empty Lot		Empty Lot			1980 Material Manual
D2	3987 Algoma Rd	N	C	N	2 inch	3/13/1998	C	1.5 inch	6/21/2002	NONRES	Copper	Install after lead ban
	SC-491-5	N	C	N	1 inch	2/16/2000	Empty Lot					Install after lead ban
	2404 DePrey St	N	C	N	1 inch	12/9/1980	C	1 inch	11/27/1981	SF	Copper	1980 Material Manual
	2408 DePrey St	N	C	N	1 inch	12/9/1980	C and P	1 inch	3/20/1982	SF	Plastic	1980 Material Manual
LC18	2413 DePrey St	N	C	N	1 inch	10/7/1980	C	1 inch	3/17/1982	SF	Copper	1980 Material Manual
	2417 DePrey St	N	C	N	1 inch	10/7/1980	C	1 inch	12/1/1981	SF	Copper	1980 Material Manual
	2423 DePrey St	N	C	N	1 inch	5/20/1981	C	1 inch	12/9/1981	SF	Copper	1980 Material Manual
	2426 DePrey St	N	C	N	1 inch	12/3/1980	C	1 inch	11/20/1981	SF	Copper	1980 Material Manual
	2434 DePrey St	N	C	N	1 inch	11/19/1980	C	1 inch	12/14/1981	SF	Copper	1980 Material Manual
	2445 DePrey St	N	C	N	1 inch	10/16/1980	C	1 inch	12/4/1981	SF	Copper	1980 Material Manual
LC19	2447 DePrey St	N	C	N	1 inch	10/20/1980	C	1 inch	3/27/1982	SF	Copper	1980 Material Manual
	3567 Judy Lane	N	C	N	1 inch	10/1/1980	C and G	1 inch	12/23/1981	SF	Galvanized	1980 Material Manual
	3575 Judy Lane	N	C	N	1 inch	10/1/1980	C	1 inch	12/20/1981	SF	Copper	1980 Material Manual
	3687 Judy Lane	N	C	N	1 inch	12/7/1980	C	1 inch	1/6/1982	SF	Copper	1980 Material Manual
	3606 Debra Anne	N	C	N	1 inch	6/16/2003	P	1 inch	6/16/2003	SF	Plastic	Install after lead ban
	3612 Debra Anne	N	C	N	1 inch	11/20/1981	C	1 inch	10/21/1983	SF	Copper	1980 Material Manual
	3615 Debra Anne	N	Plastic	N	1 inch	5/30/2017	C	1 inch	10/21/1983	SF	Copper	Install after lead ban
	3616 Debra Anne	N	C	N	1 inch	6/27/2007	Empty Lot		Empty Lot			Install after lead ban
	3622 Debra Anne	N	C	N	1 inch	6/27/2007	Empty Lot		Empty Lot			Install after lead ban
	3623 Debra Anne	N	C	N	1 inch	6/27/2007	Empty Lot		Empty Lot			Install after lead ban
	3628 Debra Anne	N	C	N	1 inch	6/27/2007	Empty Lot		Empty Lot			Install after lead ban

Champeau Rd  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side determination
	3567 Champeau Rd	N	C	N	1 inch	9/10/1980	C	1 inch	1/5/1982	SF	Copper	1981 Material Manual
	3585 Champeau Rd	N	C	N	1 inch	4/21/1992	P	1 inch	3/30/1998	SF	Plastic	Installed after lead ban
	3589 Champeau Rd	N	C	N	1 inch	4/21/1992	P	1 inch	11/20/1998	SF	Plastic	Installed after lead ban
	3593 Champeau Rd	N	C	N	1 inch	4/20/1992	P	1 inch	5/25/2000	SF	Plastic	Installed after lead ban
	3595 Champeau Rd	N	C	N	1 inch	9/10/1980	C	1 inch	8/30/1994	SF	Copper	1981 Material Manual
	3597 Champeau Rd	N	C	N	1 inch	4/20/1992	P	1 inch	9/19/2000	SF	Plastic	Installed after lead ban
	3695 Champeau Rd	N	C	N	1 inch	6/12/1993	P	1 inch	4/20/1996	SF	Plastic	Installed after lead ban
	3709 Champeau Rd	N	C	N	1 inch	6/12/1993	C	1 inch	7/11/1996	SF	Copper	Installed after lead ban
	3713 Champeau Rd	N	C	N	1 inch	6/15/1993	P	1 inch	9/9/1999	SF	Plastic	Installed after lead ban
	3717 Champeau Rd	N	C	N	1 inch	6/15/1993	P	1 inch	8/21/1997	SF	Plastic	Installed after lead ban
	3720 Champeau Rd	N	P	N	2 inch	6/21/1993	P	2 inch	6/25/1999	SF	Plastic	Installed after lead ban
	3721 Champeau Rd	N	C	N	1 inch	6/21/1993	C	1 inch	11/1/1996	SF	Copper	Installed after lead ban
	3724 Champeau Rd	N	C	N	1 inch	8/28/2001	Empty Lot		Empty Lot			Installed after lead ban
	3727 Champeau Rd	N	C	N	1 inch	8/30/2001	P	1 inch	11/10/2002	SF	Plastic	Installed after lead ban
	3728 Champeau Rd	N	C	N	1 inch	8/30/2001	Empty Lot		Empty Lot			Installed after lead ban
	3729 Champeau Rd	N	C	N	1 inch	8/30/2001	P	1 inch	5/27/2002	SF	Plastic	Installed after lead ban
	3730 Champeau Rd	N	C	N	1 inch	8/14/2001	P	1 inch	10/1/2001	SF	Plastic	Installed after lead ban
	3735 Champeau Rd	N	C	N	1 inch	8/12/2001	P	1 inch	5/27/2002	SF	Plastic	Installed after lead ban
	3736 Champeau Rd	N	C	N	1 inch	8/12/2001	Empty Lot		Empty Lot			Installed after lead ban
	3740 Champeau Rd	N	C	N	1 inch	8/14/2001	P	1 inch	7/14/2002	SF	Plastic	Installed after lead ban
	3741 Champeau Rd	N	C	N	1 inch	8/13/2001	C	1 inch	5/27/2002	SF	Copper	Installed after lead ban
	3750 Champeau Rd	N	C	N	1 inch	8/8/2001	Empty Lot		Empty Lot			Installed after lead ban
	3751 Champeau Rd	N	C	N	1 inch	8/8/2001	Empty Lot		Empty Lot			Installed after lead ban
	3759 Champeau Rd	N	C	N	1 inch	8/6/2001	Empty Lot		Empty Lot			Installed after lead ban
	3760 Champeau Rd	N	C	N	1 inch	8/6/2001	C	1 inch	7/11/2002	SF	Copper	Installed after lead ban
	3769 Champeau Rd	N	C	N	1 inch	8/2/2001	Empty Lot		Empty Lot			Installed after lead ban
	3779 Champeau Rd	N	C	N	1 inch	8/2/2001	Empty Lot		Empty Lot			Installed after lead ban
	3784 Champeau Rd	N	C	N	1 inch	7/24/2001	P	1 inch	5/21/2006	SF	Plastic	Installed after lead ban
	3805 Champeau Rd	N	C	N	1 inch	7/24/2001	Empty Lot		Empty Lot			Installed after lead ban
	3816 Champeau Rd	N	C	N	1 inch	7/24/2001	P	1 inch	9/11/2003	SF	Plastic	Installed after lead ban
	3820 Champeau Rd	N	C	N	1 inch	7/15/2001	P	1 inch	6/27/2010	SF	Plastic	Installed after lead ban
	3828 Champeau Rd	N	C	N	1 inch	7/15/2001	P	1 inch	6/14/2022	SF	Plastic	Installed after lead ban
	3836 Champeau Rd	N	C	N	1 inch	4/21/1981	C	1 inch	9/21/1985	SF	Copper	1981 Material Manual
	3844 Champeau Rd	N	C	N	1 inch	4/21/1981	C	1 inch	8/31/1982	SF	Copper	1981 Material Manual
	3849 Champeau Rd	N	C	N	1 inch	4/21/1981	Empty Lot		Empty Lot			1981 Material Manual
LC20+22	3850 + 3854 Champeau Rd	N	C	N	1 inch	4/21/1981	C	1 inch	11/25/1981	MF	Copper	1981 Material Manual
	3856 Champeau Rd	N	C	N	1 inch	4/21/1981	C	1 inch	10/20/1982	SF	Copper	1981 Material Manual
	3857 Champeau Rd	N	C	N	1 inch	4/20/1981	P	1 inch	5/25/2009	SF	Plastic	1981 Material Manual
	3861 Champeau Rd	N	C	N	1 inch	4/20/1981	C	1 inch	12/11/1981	SF	Copper	1981 Material Manual
	3862 Champeau Rd	N	C	N	1 inch	4/20/1981	P	1 inch	9/9/1997	SF	Plastic	1981 Material Manual
	3867 Champeau Rd	N	C	N	1 inch	4/20/1981	C	1 inch	12/11/1981	SF	Copper	1981 Material Manual
	3868 Champeau Rd	N	C	N	1 inch	4/16/1981	P	1 inch	6/6/1994	SF	Plastic	1981 Material Manual

Champeau Rd  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side determination
	3877 Champeau Rd	N	C	N	1 inch	6/12/2001	Empty Lot		Empty Lot			Installed after lead ban
	3880 Champeau Rd	N	C	N	1 inch	4/16/1981	P	1 inch	3/23/2003	SF	Plastic	1981 Material Manual
	3887 Champeau Rd	N	C	N	1 inch	6/12/2001	Empty Lot		Empty Lot			Installed after lead ban
	3900 Champeau Rd	N	C	N	1 inch	4/16/1981	C	1 inch	9/23/1996	SF	Copper	1981 Material Manual
	3922 Champeau Rd	N	C	N	1 inch	4/13/1981	C	1 inch	4/23/1982	SF	Copper	1981 Material Manual
	3925 Champeau Rd	N	C	N	1 inch	4/13/1981	P	1 inch	10/4/1993	SF	Plastic	1981 Material Manual
	3940 Champeau Rd	N	C	N	1 inch	4/8/1981	C	1 inch	6/7/1998	SF	Copper	1981 Material Manual
	3941 & 3943 Champeau Rd	N	C	N	1 inch	4/8/1981	C	1 inch	8/19/1998	MF	Copper	1981 Material Manual
	3944 Champeau Rd	N	C	N	1 inch	4/7/1981	C	1 inch	11/27/1997	SF	Copper	1981 Material Manual
	3950 Champeau Rd	N	C	N	1 inch	4/7/1981	C	1 inch	5/12/1997	SF	Copper	1981 Material Manual
	3951 Champeau Rd	N	C	N	1 inch	6/11/2001	Empty Lot		Empty Lot			Installed after lead ban
	3959 Champeau Rd	N	C	N	1 inch	4/7/1981	C	1 inch	12/12/1982	NONRES	Copper	1981 Material Manual
	3969 Champeau Rd	N	C	N	1 inch	4/5/1981	P	1.25 inch	8/13/1982	NONRES	Copper	1981 Material Manual
	3972 Champeau Rd	N	C	N	1 inch	4/13/1981	C	1 inch	12/11/1981	SF	Copper	1981 Material Manual
	4030 Champeau Rd	N	P	N	2 inch	8/10/2001	P	2 inch	6/6/2005	NONRES	Plastic	Installed after lead ban
	4050 Champeau Rd	N	P	N	1 inch	8/10/2001	P	1 inch	3/12/2015	NONRES	Plastic	Installed after lead ban

Edmund Rd, Charlotte Ct, Metzler Ct and Royal Bay Ridge Rd  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
2409	Edmund Rd	N	C	N	1 inch	9/16/1997	C	1 inch	8/18/1998	SF	Copper	Installed after lead ban
2414	Edmund Rd	N	C	N	1 inch	9/16/1997	P	1 inch	9/27/1998	SF	Plastic	Installed after lead ban
2420	Edmund Rd	N	C	N	1 inch	9/16/1997	P	1 inch	8/18/1998	SF	Plastic	Installed after lead ban
2428	Edmund Rd	N	C	N	1 inch	9/16/1997	P	1 inch	9/27/1998	SF	Plastic	Installed after lead ban
2429	Edmund Rd	N	C	N	1 inch	9/16/1997	P	1 inch	6/12/1999	SF	Plastic	Installed after lead ban
2434	Edmund Rd	N	C	N	1 inch	9/16/1997	C	1 inch	8/18/1998	SF	Copper	Installed after lead ban
2440	Edmund Rd	N	C	N	1 inch	9/16/1997	P	1 inch	9/27/1998	SF	Plastic	Installed after lead ban
2448	Edmund Rd	N	C	N	1 inch	9/16/1997	P	1 inch	8/18/1998	SF	Plastic	Installed after lead ban
2449	Edmund Rd	N	C	N	1 inch	9/16/1997	P	1 inch	6/12/1999	SF	Plastic	Installed after lead ban
2454	Edmund Rd	N	C	N	1 inch	9/16/1997	P	1 inch	9/27/1998	SF	Plastic	Installed after lead ban
2457	Edmund Rd	N	C	N	1 inch	9/16/1997	P	1 inch	6/12/1999	SF	Plastic	Installed after lead ban
2460	Edmund Rd	N	C	N	1 inch	9/16/1997	P	1 inch	11/1/1998	SF	Plastic	Installed after lead ban
2467	Edmund Rd	N	C	N	1 inch	9/16/1997	P	1 inch	10/26/2000	SF	Plastic	Installed after lead ban
2469	Edmund Rd	N	C	N	1 inch	9/16/1997	P	1 inch	10/26/2000	SF	Plastic	Installed after lead ban
2475	Edmund Rd	N	C	N	1 inch	9/16/1997	P	1 inch	11/14/2005	SF	Plastic	Installed after lead ban
2478	Edmund Rd	N	C	N	1 inch	9/16/1997	C	1 inch	10/11/2001	SF	Copper	Installed after lead ban
2490	Edmund Rd	N	Repaired (poly)	N	1 inch	9/16/1997	Empty Lot		Empty Lot			Installed after lead ban
2500	Edmund Rd	N	Repaired (poly)	N	1 inch	4/4/1981	P	1 inch	5/4/1993	SF	Plastic	1980 Maintenance Manual
2506	Edmund Rd	N	C	N	1 inch	4/4/1981	P	1 inch	10/10/1994	SF	Plastic	1980 Maintenance Manual
2510	Edmund Rd	N	C	N	1 inch	4/4/1981	C	1 inch	7/29/1995	SF	Copper	1980 Maintenance Manual
2513	Edmund Rd	N	C	N	1 inch	4/4/1981	P	1 inch	7/29/1995	SF	Plastic	1980 Maintenance Manual
2515	Edmund Rd	N	C	N	1 inch	4/4/1981	C	1 inch	7/29/1995	SF	Copper	1980 Maintenance Manual
2522	Edmund Rd	N	C	N	1 inch	4/4/1981	C	1 inch	8/11/1993	SF	Plastic	1980 Maintenance Manual
2535	Edmund Rd	N	P	N	1 inch	3/13/2025	Empty Lot		Empty Lot	SF		Installed after lead ban
2545	Edmund Rd	N	P	N	1 inch	3/13/2025	Empty Lot		Empty Lot	SF		Installed after lead ban
2555	Edmund Rd	N	P	N	1 inch	3/12/2025	Empty Lot		Empty Lot	SF		Installed after lead ban
2565	Edmund Rd	N	P	N	1 inch	3/12/2025	Empty Lot		Empty Lot	SF		Installed after lead ban
2570	Edmund Rd	N	C	N	1 inch	4/4/1981	C	1 inch	4/14/1987	SF	Copper	1980 Maintenance Manual
2590	Edmund Rd	N	C	N	1 inch	4/4/1981	C	1 inch	10/10/1991	SF	Copper	1980 Maintenance Manual
3920	Charlotte Ct	N	C	N	1 inch	6/9/1993	P	1 inch	7/29/1995	SF	Plastic	Installed after lead ban
3921	Charlotte Ct	N	C	N	1 inch	6/9/1993	P	1 inch	10/10/1994	SF	Plastic	Installed after lead ban
3928	Charlotte Ct	N	C	N	1 inch	6/9/1993	C	1 inch	7/29/1995	SF	Copper	Installed after lead ban
3929	Charlotte Ct	N	C	N	1 inch	6/9/1993	P	1 inch	9/27/1998	SF	Plastic	Installed after lead ban
3921	Metzler Ct	N	C	N	1 inch	4/10/1995	P	1 inch	8/14/1996	SF	Plastic	Installed after lead ban
3922	Metzler Ct	N	C	N	1 inch	4/10/1995	P	1 inch	7/23/1997	SF	Plastic	Installed after lead ban
3924	Metzler Ct	N	C	N	1 inch	4/10/1995	P	1 inch	7/23/1997	SF	Plastic	Installed after lead ban
3926	Metzler Ct	N	C	N	1 inch	4/10/1995	P	1 inch	7/23/1997	SF	Plastic	Installed after lead ban
3928	Metzler Ct	N	C	N	1 inch	4/10/1995	P	1 inch	5/1/1998	SF	Plastic	Installed after lead ban
3930	Metzler Ct	N	C	N	1 inch	4/10/1995	C	1 inch	9/2/1999	SF	Copper	Installed after lead ban

Edmund Rd, Charlotte Ct, Metzler Ct and Royal Bay Ridge Rd  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
2408	Royal Bay Ridge	N	C	N	1 inch	8/4/1997	P	1 inch	8/10/1998	SF	Plastic	Installed after lead ban
2411	Royal Bay Ridge	N	C	N	1 inch	8/14/1997	P	1 inch	8/10/1998	SF	Plastic	Installed after lead ban
2416	Royal Bay Ridge	N	C	N	1 inch	7/31/1997	C	1 inch	7/29/1999	SF	Copper	Installed after lead ban
2417	Royal Bay Ridge	N	C	N	1 inch	8/4/1997	P	1 inch	7/29/1999	SF	Plastic	Installed after lead ban
2425	Royal Bay Ridge	N	C	N	1 inch	8/4/1997	P	1 inch	8/10/1998	SF	Plastic	Installed after lead ban
2431	Royal Bay Ridge	N	C	N	1 inch	7/31/1997	P	1 inch	8/10/1998	SF	Plastic	Installed after lead ban
2436	Royal Bay Ridge	N	C	N	1 inch	7/30/1997	P	1 inch	7/29/1999	SF	Plastic	Installed after lead ban
2437	Royal Bay Ridge	N	C	N	1 inch	7/31/1997	P	1 inch	10/16/1999	SF	Plastic	Installed after lead ban
2442	Royal Bay Ridge	N	C	N	1 inch	7/30/1997	P	1 inch	9/12/1999	SF	Plastic	Installed after lead ban
2445	Royal Bay Ridge	N	C	N	1 inch	7/30/1997	P	1 inch	8/10/1998	SF	Plastic	Installed after lead ban
2450	Royal Bay Ridge	N	C	N	1 inch	7/30/1997	P	1 inch	9/12/1999	SF	Plastic	Installed after lead ban
2456	Royal Bay Ridge	N	C	N	1 inch	7/30/1997	P	1 inch	9/12/1999	SF	Plastic	Installed after lead ban
2457	Royal Bay Ridge	N	C	N	1 inch	7/29/1997	P	1 inch	10/16/1999	SF	Plastic	Installed after lead ban
2461	Royal Bay Ridge	N	C	N	1 inch	7/28/1997	C	1 inch	6/14/1999	SF	Copper	Installed after lead ban
2466	Royal Bay Ridge	N	C	N	1 inch	7/29/1997	P	1 inch	6/14/1999	SF	Plastic	Installed after lead ban
3915	Royal Bay Ridge	N	C	N	1 inch	7/24/1997	P	1 inch	11/7/1999	SF	Plastic	Installed after lead ban
3927	Royal Bay Ridge	N	C	N	1 inch	7/28/1997	P	1 inch	10/16/1999	SF	Plastic	Installed after lead ban
3941	Royal Bay Ridge	N	C	N	1 inch	7/28/1997	P	1 inch	11/7/1999	SF	Plastic	Installed after lead ban
3949	Royal Bay Ridge	N	C	N	1 inch	7/29/1997	P	1 inch	11/7/1999	SF	Plastic	Installed after lead ban

Rebecca Ann Dr, Jody Dr, Jake Dr and Settlement Heights Dr  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
	2562 Rebecca Ann	N	C	N	1 inch	6/15/1993	C	1 inch	5/14/1996	SF	Copper	Installed after lead ban
	3720 Rebecca Ann	N	C	N	1 inch	6/15/1993	P	1 inch	8/10/2001	SF	Plastic	Installed after lead ban
	2514 Jody Dr	N	C	N	1 inch	6/15/1993	C	1 inch	10/14/1996	SF	Copper	Installed after lead ban
	2515 Jody Dr	N	C	N	1 inch	6/15/1993	C	1 inch	8/30/1994	SF	Copper	Installed after lead ban
	2525 Jody Dr	N	C	N	1 inch	6/15/1993	C	1 inch	10/14/1996	SF	Copper	Installed after lead ban
	2533 Jody Dr	N	C	N	1 inch	6/15/1993	P	1 inch	8/30/1994	SF	Plastic	Installed after lead ban
	2540 Jody Dr	N	C	N	1 inch	6/15/1993	P	1 inch	3/3/2003	SF	Plastic	Installed after lead ban
	2541 Jody Dr	N	C	N	1 inch	6/15/1993	P	1 inch	10/14/1996	SF	Plastic	Installed after lead ban
	2550 Jody Dr	N	C	N	1 inch	6/15/1993	P	1 inch	8/30/1994	SF	Plastic	Installed after lead ban
	2551 Jody Dr	N	C	N	1 inch	6/15/1993	C	1 inch	7/5/1995	SF	Copper	Installed after lead ban
	2554 Jody Dr	N	C	N	1 inch	6/15/1993	P	1 inch	5/2/1996	SF	Plastic	Installed after lead ban
	2555 Jody Dr	N	C	N	1 inch	6/15/1993	P	1 inch	4/4/1994	SF	Plastic	Installed after lead ban
	2567 Jody Dr	N	C	N	1 inch	6/15/1993	P	1 inch	5/2/1996	SF	Plastic	Installed after lead ban
	2574 Jody Dr	N	C	N	1 inch	6/15/1993	P	1 inch	10/16/2001	SF	Plastic	Installed after lead ban
	2575 Jody Dr	N	C	N	1 inch	6/15/1993	P	1 inch	10/16/2001	SF	Plastic	Installed after lead ban
	2581 Jody Dr	N	C	N	1 inch	6/15/1993	C	1 inch	5/30/1995	MF	Copper	Installed after lead ban
	2590 Jody Dr	N	C	N	1 inch	6/15/1993	C	1 inch	6/6/2002	SF	Plastic	Installed after lead ban
W1	2619 Jody Dr	N	C	N	1 inch	4/27/1981	C	1 inch	8/29/1981	NONRES	Copper	Installed after lead ban
EP1	2621 Jody Dr	N	C	N	1.5 inch	6/27/1997	P	1.5 inch	8/27/1997	NONRES	Copper	Installed after lead ban
	2622 Jody Dr	N	C	N	1 inch	6/27/1997	Empty Lot		Empty Lot			Installed after lead ban
	2628 Jody Dr	N	C	N	1 inch	6/27/1997	Empty Lot		Empty Lot			Installed after lead ban
	2538 Jake Dr	N	C	N	1 inch	6/15/1993	P	1 inch	9/9/1999	SF	Plastic	Installed after lead ban
	2543 Jake Dr	N	C	N	1 inch	6/15/1993	P	1 inch	6/24/1997	SF	Plastic	Installed after lead ban
	2546 Jake Dr	N	C	N	1 inch	6/15/1993	P	1 inch	5/16/2000	SF	Plastic	Installed after lead ban
	2553 Jake Dr	N	C	N	1 inch	6/15/1993	P	1 inch	4/20/1998	SF	Plastic	Installed after lead ban
	2556 Jake Dr	N	C	N	1 inch	6/15/1993	C	1 inch	11/11/1996	SF	Copper	Installed after lead ban
	2557 Jake Dr	N	C	N	1 inch	6/15/1993	P	1 inch	6/24/1997	SF	Plastic	Installed after lead ban
	2558 Jake Dr	N	C	N	1 inch	6/15/1993	P	1 inch	5/16/2000	SF	Plastic	Installed after lead ban
	2566 Jake Dr	N	C	N	1 inch	6/15/1993	Empty Lot		Empty Lot			Installed after lead ban
	3712 Settlement Heights	N	C	N	1 inch	6/15/1993	C	1 inch	4/27/1996	SF	Copper	Installed after lead ban
	3713 Settlement Heights	N	C	N	1 inch	6/15/1993	P	1 inch	4/27/1996	SF	Plastic	Installed after lead ban
	3715 Settlement Heights	N	C	N	1 inch	6/15/1993	C	1 inch	8/8/1999	SF	Copper	Installed after lead ban
	3716 Settlement Heights	N	C	N	1 inch	6/15/1993	C	1 inch	10/1/1997	SF	Copper	Installed after lead ban
	3720 Settlement Heights	N	C	N	1 inch	6/15/1993	C	1 inch	10/1/1997	SF	Copper	Installed after lead ban

Hackberry Ct, Redbud Ct, Buckeye Way, and Sussex Rd  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
4030	Hackberry	N	C	N	1 inch	3/27/1992	C	1 inch	3/16/1993	SF	Copper	Installed after lead ban
4036	Hackberry	N	C	N	1 inch	3/27/1992	P	1 inch	8/24/1996	SF	Plastic	Installed after lead ban
4037	Hackberry	N	C	N	1 inch	3/27/1992	C	1 inch	8/24/1996	SF	Copper	Installed after lead ban
4042	Hackberry	N	C	N	1 inch	3/27/1992	P	1 inch	7/10/1997	SF	Plastic	Installed after lead ban
4048	Hackberry	N	C	N	1 inch	3/27/1992	P	1 inch	6/9/1994	SF	Plastic	Installed after lead ban
4049	Hackberry	N	C	N	1 inch	3/27/1992	C	1 inch	5/4/1998	SF	Plastic	Installed after lead ban
4054	Hackberry	N	C	N	1 inch	3/27/1992	P	1 inch	3/16/1993	SF	Plastic	Installed after lead ban
4055	Hackberry	N	C	N	1 inch	3/27/1992	P	1 inch	4/29/1999	SF	Plastic	Installed after lead ban
4060	Hackberry	N	C	N	1 inch	3/27/1992	C	1 inch	6/9/1994	SF	Copper	Installed after lead ban
4066	Hackberry	N	C	N	1 inch	3/27/1992	P	1 inch	8/6/1999	SF	Plastic	Installed after lead ban
4072	Hackberry	N	C	N	1 inch	3/27/1992	P	1 inch	11/4/1998	SF	Plastic	Installed after lead ban
4078	Hackberry	N	C	N	1 inch	3/27/1992	P	1 inch	11/4/1998	SF	Plastic	Installed after lead ban
4084	Hackberry	N	C	N	1 inch	3/27/1992	P	1 inch	8/9/2000	SF	Plastic	Installed after lead ban
4090	Hackberry	N	C	N	1 inch	3/27/1992	P	1 inch	4/29/1999	SF	Plastic	Installed after lead ban
4096	Hackberry	N	C	N	1 inch	3/27/1992	C	1 inch	7/10/1997	SF	Copper	Installed after lead ban
5007	Redbud	N	C	N	1 inch	3/27/1992	P	1 inch	8/9/2000	SF	Plastic	Installed after lead ban
5015	Redbud	N	C	N	1 inch	3/27/1992	P	1 inch	8/9/2000	SF	Plastic	Installed after lead ban
5019	Redbud	N	C	N	1 inch	3/27/1992	C	1 inch	7/10/1997	SF	Copper	Installed after lead ban
5025	Redbud	N	C	N	1 inch	3/27/1992	C	1 inch	6/9/1994	SF	Copper	Installed after lead ban
5032	Redbud	N	C	N	1 inch	3/27/1992	P	1 inch	9/1/1997	SF	Plastic	Installed after lead ban
5038	Redbud	N	C	N	1 inch	3/27/1992	P	1 inch	9/1/1997	SF	Plastic	Installed after lead ban
5044	Redbud	N	C	N	1 inch	3/27/1992	P	1 inch	11/4/1998	SF	Plastic	Installed after lead ban
5050	Redbud	N	C	N	1 inch	3/27/1992	C	1 inch	8/9/2000	SF	Copper	Installed after lead ban
4000	Buckeye	N	C	N	1 inch	3/27/1992	C	1 inch	9/30/1997	SF	Copper	Installed after lead ban
4001	Buckeye	N	C	N	1 inch	3/27/1992	P	1 inch	9/30/1997	SF	Plastic	Installed after lead ban
4006	Buckeye	N	C	N	1 inch	3/27/1992	P	1 inch	5/26/1993	SF	Plastic	Installed after lead ban
4007	Buckeye	N	C	N	1 inch	3/27/1992	P	1 inch	8/2/1996	SF	Plastic	Installed after lead ban
4012	Buckeye	N	C	N	1 inch	3/27/1992	P	1 inch	10/19/1998	SF	Plastic	Installed after lead ban
4013	Buckeye	N	C	N	1 inch	3/27/1992	P	1 inch	8/2/1996	SF	Plastic	Installed after lead ban
4018	Buckeye	N	C	N	1 inch	3/27/1992	P	1 inch	7/12/1993	SF	Plastic	Installed after lead ban
4019	Buckeye	N	C	N	1 inch	3/27/1992	P	1 inch	7/12/1993	SF	Plastic	Installed after lead ban
4025	Buckeye	N	C	N	1 inch	3/27/1992	P	1 inch	11/1/2004	SF	Plastic	Installed after lead ban
2516	Sussex	N	C	N	1 inch	3/27/1992	P	1 inch	4/27/1999	SF	Plastic	Installed after lead ban
2522	Sussex	N	C	N	1 inch	3/27/1992	P	1 inch	4/27/1999	SF	Plastic	Installed after lead ban
2528	Sussex	N	C	N	1 inch	3/27/1992	P	1 inch	8/3/2017	SF	Plastic	Installed after lead ban
2534	Sussex	N	C	N	1 inch	3/27/1992	P	1 inch	6/14/2003	SF	Plastic	Installed after lead ban
2539	Sussex	N	C	N	1 inch	3/27/1992	P	1 inch	11/30/1992	SF	Plastic	Installed after lead ban
2588	Sussex	N	C	N	1 inch	3/27/1992	P	1 inch	10/9/2001	SF	Plastic	Installed after lead ban

Rose Garden Way and Sandra Rose Ln  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously Lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Material	Basis of street side material classification
	3714,16,18,20,22 Rose Garden	N	C	N	2 inch	1994	C	2 inch	6/10/1998	MF	Plastic	Installed after lead ban
										SF	Plastic	
										SF	Plastic	
										SF	Plastic	
										SF	Plastic	
	3725 Rose Garden	N	C	N	1 inch	5/9/1994	C	1 inch	4/10/2000	MF	Copper	Installed after lead ban
	3724,26,28,30,32,34 Rose Garden	N	C	N	2 inch	5/9/1994	C	2 inch	7/3/1996	MF	Copper	Installed after lead ban
										SF	Copper	
										SF	Copper	
										SF	Copper	
	3736,38,40,42 Rose Garden	N	C	N	2 inch	5/9/1994	C	2 inch	5/25/1999	MF	Plastic	Installed after lead ban
										SF	Plastic	
										SF	Plastic	
										SF	Plastic	
	2614 Sandra Rose	N	C	N	1 inch	5/9/1994	C	1 inch	3/16/1995	MF	Copper	Installed after lead ban
	2620 + 2622 Sandra Rose	N	C	N	1 inch	5/9/1994	C	1 inch	8/14/1996	MF	Copper	Installed after lead ban
	2623 + 2625 Sandra Rose	N	C	N	1 inch	5/9/1994	P	1 inch	6/16/2004	MF	Plastic	Installed after lead ban
	2627 + 2629 Sandra Rose	N	C	N	1 inch	5/9/1994	P	1 inch	6/16/2004	MF	Plastic	Installed after lead ban
	2628 + 2630 Sandra Rose	N	C	N	1 inch	5/9/1994	C	1 inch	5/14/1994	MF	Copper	Installed after lead ban
	2631 + 2633 Sandra Rose	N	C	N	1 inch	5/9/1994	P	1.25 inch	9/27/2002	MF	Plastic	Installed after lead ban
	2642 + 2644 Sandra Rose	N	C	N	1 inch	5/9/1994	C	1 inch	5/14/1994	MF	Copper	Installed after lead ban
	2643 + 2645 Sandra Rose	N	C	N	1 inch	5/9/1994	P	1.25 inch	9/27/2002	MF	Plastic	Installed after lead ban
	2657 + 2659 Sandra Rose	N	C	N	1 inch	5/9/1994	P	1 inch	6/14/2003	MF	Plastic	Installed after lead ban
	2660 + 2662 Sandra Rose	N	C	N	1 inch	5/9/1994	P	1 inch	10/10/1998	MF	Copper	Installed after lead ban
	2667 + 2669 Sandra Rose	N	C	N	1 inch	5/9/1994	C	1 inch	12/4/1997	MF	Copper	Installed after lead ban
	2672 + 2674 Sandra Rose	N	C	N	1 inch	5/9/1994	P	1 inch	8/15/1996	MF	Plastic	Installed after lead ban
	2685 Sandra Rose	N	C	N	1 inch	5/9/1994	C	1 inch	10/14/2000	MF	Copper	Installed after lead ban
	2690 + 2692 Sandra Rose	N	C	N	1 inch	5/9/1994	P	1 inch	6/14/2003	MF	Plastic	Installed after lead ban

Norrie Dr, Scott Tower Dr, Debauche Dr, and Church Rd  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
3815 Norrie Dr		N	P	N	2 inch	11/1/2019	P	2 inch	2/10/2022	NONRES	Plastic	Installed after lead ban
3818 Norrie Dr		N	P	N	2 inch	11/15/2023	P (Not Connected)	2 inch	11/15/2023	NONRES	Plastic	Installed after lead ban
3849 Norrie Dr							Empty Lot			NONRES		Installed after lead ban
3851 Norrie Dr		N	P	N	2 inch	11/1/2019	Empty Lot			NONRES		Installed after lead ban
3853 Norrie Dr							Empty Lot					Installed after lead ban
3860 Norrie Dr		N	P	N	2 inch	11/1/2019	P	2 inch	3/31/2021	NONRES	Plastic	Installed after lead ban
3861 Norrie Dr		N	P	N	2 inch	11/1/2019	P	2 inch	10/26/2020	NONRES	Plastic	Installed after lead ban
3862 Norrie Dr		N	P	N	2 inch	10/15/2021	P	2 inch	10/15/2021	NONRES	Plastic	Installed after lead ban
3863 Norrie Dr		N	P	N	2 inch	10/15/2021	P	2 inch	10/15/2021	NONRES	Plastic	Installed after lead ban
3864 Norrie Dr		N	P	N	2 inch	10/15/2021	P	2 inch	10/15/2021	NONRES	Plastic	Installed after lead ban
3865 Norrie Dr		N	P	N	2 inch	10/16/2021	P	2 inch	10/16/2021	NONRES	Plastic	Installed after lead ban
3866 Norrie Dr		N	P	N	2 inch	10/16/2021	P	2 inch	10/16/2021	NONRES	Plastic	Installed after lead ban
3867 Norrie Dr		N	P	N	2 inch	10/16/2021	P (Not Connected)	2 inch	10/16/2021	NONRES	Plastic	Installed after lead ban
2560 Scott Tower Rd		N	C	N	1 inch	3/12/1999	C	1 inch	6/12/1991	NONRES	Copper	Installed after lead ban
2580 Scott Tower Rd		N	C	N	1 inch	3/12/1999	Empty Lot		Empty Lot	NONRES		Installed after lead ban
2581 Scott Tower Rd		N	C	N	1 inch	3/12/1999	Empty Lot		Empty Lot	NONRES		Installed after lead ban
2661 Scott Tower Rd		N	P	N	2 inch	2/7/2002	P	2 inch	10/9/2002	NONRES	Copper	Installed after lead ban
2633 DeBauche Dr		N	P	N	2 inch	11/28/2023	P (Not Connected)	2 inch	11/14/2023			Installed after lead ban
2634 DeBauche Dr		N	P	N	2 inch	11/28/2023	P	2 inch	11/14/2023	NONRES	Plastic	Installed after lead ban
2635 DeBauche Dr		N	P	N	2 inch	11/28/2023	P	2 inch	11/14/2023			Installed after lead ban
2636 DeBauche Dr		N	P	N	2 inch	11/28/2023	P	2 inch	11/14/2023			Installed after lead ban
2637 DeBauche Dr		N	P	N	2 inch	11/28/2023	P (Not Connected)	2 inch	11/14/2023			Installed after lead ban
2638 DeBauche Dr		N	P	N	2 inch	11/28/2023	P (Not Connected)	2 inch	11/14/2023			Installed after lead ban
2639 DeBauche Dr		N	P	N	2 inch	11/28/2023	P (Not Connected)	2 inch	11/14/2023			Installed after lead ban
2640 DeBauche Dr		N	P	N	2 inch	11/28/2023	P	2 inch	11/14/2023	NONRES	Plastic	Installed after lead ban
2642 DeBauche Dr		N	P	N	2 inch	11/28/2023	P	2 inch	11/14/2023			Installed after lead ban
3840 Church Rd		N	C	N	1 inch	10/10/1981	C	1 inch	12/22/1981	SF	Copper	1980 Material Manual

2409-2911 Bay Settlement Rd  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side				Property side line material	Property side size	Property side install date	Building type	Plumbing Material	Basis of street side classification
			Street side material	Previously Lead	service size	Street side install date						
LC17	2404 Bay Settlement Rd	N	C	N	1 inch	9/25/1980	C	1 inch	7/14/1981	SF	Copper	1980 Material Manual
	2407 Bay Settlement Rd	N	C	N	1 inch	9/17/1980	(demolished)	1 inch	11/8/1982			1980 Material Manual
	2408 Bay Settlement Rd	N	C	N	1 inch	12/11/1980	C	1 inch	12/1/1981	SF	Copper	1980 Material Manual
	2416 Bay Settlement Rd	N	C	N	1 inch	5/18/1981	C	1 inch	12/29/1981	SF	Copper	1980 Material Manual
	2428 Bay Settlement Rd	N	C	N	1 inch	9/18/1980	C	1 inch	5/4/1982	SF	Copper	1980 Material Manual
	2434 Bay Settlement Rd	N	C	N	1 inch	5/12/1981	C	1 inch	1/30/1982	SF	Copper	1980 Material Manual
	2436 Bay Settlement Rd	N	C	N	1 inch	12/1/1980	P	1 inch	12/1/1981	SF	Copper	1980 Material Manual
D3	2446 Bay Settlement Rd	N	C	N	1 inch	5/19/1981	C	1 inch	12/1/1981	O	Copper	1980 Material Manual
	2453 Bay Settlement Rd	N	C	N	1 inch	9/16/1980	C	1 inch	1/15/1982	SF	Copper	1980 Material Manual
LC4	2462 Bay Settlement Rd	N	C	N	1 inch	9/24/1980	C	1 inch	3/13/1982	SF	Copper	1980 Material Manual
LC3	2468 Bay Settlement Rd	N	C	N	1 inch	9/22/1980	C	1 inch	11/28/1981	SF	Copper	1980 Material Manual
	2492 Bay Settlement Rd	N	C	N	1 inch	10/1/1980	C	1 inch	6/30/1986	SF	Copper	1980 Material Manual
LC21	2512 Bay Settlement Rd	N	C	N	1 inch	5/18/1981	C	1 inch	11/25/1981	SF	Copper	1980 Material Manual
	2535 Bay Settlement Rd	N	C	N	1 inch	5/14/1981	C	1 inch	10/21/1981	SF	Copper	1980 Material Manual
	2545 Bay Settlement Rd	N	C	N	1 inch	5/14/1981	P	1 inch	4/28/1982	SF	Plastic	1980 Material Manual
	2559 Bay Settlement Rd	N	C	N	1 inch	5/12/1981	C	1 inch	10/26/1981	SF	Copper	1980 Material Manual
	2569 Bay Settlement Rd	N	C	N	1 inch	5/12/1981	C	1 inch	1/14/1982	SF	Copper	1980 Material Manual
	2584 Bay Settlement Rd	N	C	N	1 inch	5/11/1981	C	1 inch	11/25/1981	O	Galv. Copper	1980 Material Manual
	2589 Bay Settlement Rd	N	C	N	1 inch	5/12/1981	C	1 inch	12/17/1981	SF	Copper, Plastic	1980 Material Manual
	2609 Bay Settlement Rd	N	C	N	1 inch	5/12/1981	C	1 inch	12/29/1981	SF	Copper	1980 Material Manual
	2617 Bay Settlement Rd	N	P	N	1 inch	5/24/2007	P	1 inch	4/5/2021	SF	Plastic	Installed after lead ban
	2627 + 2629 Bay Settlement Rd	N	C	N	1 inch	1/3/1988	C	1 inch	11/12/1988	SF	Copper	Installed after lead ban
	2633 Bay Settlement Rd	N	C	N	1 inch	5/13/1981	C	1 inch	6/8/1981	SF	Copper	1980 Material Manual
	2638 Bay Settlement Rd	N	C	N	1 inch	5/25/1981	C	1 inch	1/13/1982	O	Copper	1980 Material Manual
	2646 Bay Settlement Rd	N	C	N	1 inch	5/25/1981	P	1 inch	11/28/1981	SF	Plastic	1980 Material Manual
	2649 Bay Settlement Rd	N	C	N	1 inch	5/13/1981	C	1 inch	11/24/1982	SF	Copper	1980 Material Manual
	2652 Bay Settlement Rd	N	C	N	1 inch	5/4/1990	C	1 inch	10/26/1990	SF	Copper	Installed after lead ban
	2661 Bay Settlement Rd	N	C	N	1 inch	5/13/1981	C	1 inch	6/25/1982	SF	Copper	1980 Material Manual
	2673 Bay Settlement Rd	N	C	N	1 inch	5/13/1981	C	1 inch	8/8/1981	SF	Copper	1980 Material Manual
	2676 Bay Settlement Rd	N	C	N	1 inch	5/26/1981	C	1 inch	10/11/1982	SF	Copper	1980 Material Manual
	2686 Bay Settlement Rd	N	C	N	1 inch	5/13/1981	P	1 inch	4/21/1984	SF	Copper	1980 Material Manual
	2694 Bay Settlement Rd	N	C	N	1 inch	5/27/1981	C	1 inch	5/17/1991	SF	Copper	1980 Material Manual
	2697 Bay Settlement Rd	N	C	N	1 inch	7/15/1982	C	1 inch	9/7/1982	SF	Copper	1980 Material Manual
2703 Bay Settlement Rd	N	C	N	1 inch	5/14/1981	C	1 inch	9/2/1982	SF	Copper	1980 Material Manual	
2712 Bay Settlement Rd	N	C	N	1 inch	5/28/1981	C	1 inch	12/18/1981	SF	Copper	1980 Material Manual	
2717 Bay settlement Rd	N	C	N	1 inch	5/14/1981	C	1 inch	12/4/1981	SF	Copper	1980 Material Manual	
2722 Bay Settlement Rd	N	C	N	1 inch	5/25/1981	C	1 inch	11/13/1982	SF	Copper	1980 Material Manual	
2731 Bay Settlement Rd	N	C	N	1 inch	5/14/1981	P	1 inch	12/11/1981	SF	Plastic	1980 Material Manual	
2737 Bay Settlement Rd	N	C	N	1 inch	5/14/1981	C	1 inch	6/27/1987	SF	Copper	1980 Material Manual	
2743 Bay Settlement Rd	N	C	N	1 inch	5/14/1981	C	1 inch	4/1/1982	SF	Copper	1980 Material Manual	
2753 Bay Settlement Rd	N	C	N	1 inch	5/18/1981	C	1 inch	1/3/1983	SF	Copper	1980 Material Manual	

2409-2911 Bay Settlement Rd  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side				Property side line material	Property side size	Property side install date	Building type	Plumbing Material	Basis of street side classification
			Street side material	Previously Lead	service size	Street side install date						
2763	Bay Settlement Rd	N	C	N	1 inch	5/15/1981	P	1 inch	4/23/1982	SF	Plastic	1980 Material Manual
2770	Bay Settlement Rd	N	C	N	1 inch	5/15/1981	C	1 inch	12/4/1981	O	Copper	1980 Material Manual
2770	Bay Settlement Rd (Maintenance)	N	P	N	1 inch	12/12/2023	P	1 inch	12/12/2023	NONRES	Copper, Plastic	Installed after lead ban
2771	Bay Settlement Rd	N	C	N	1 inch	5/15/1981	C	1 inch	8/17/1983	SF	Copper	1980 Material Manual
2779	Bay Settlement Rd	N	C	N	1 inch	5/15/1981	C	1 inch	9/9/1993	SF	Copper	1980 Material Manual
2787	Bay Settlement Rd	N	C	N	1 inch	6/5/1981	C	1 inch	3/13/1982	SF	Copper	1980 Material Manual
2804	Bay Settlement Rd	N	C	N	1 inch	10/19/1981	P	1 inch	12/15/2022	SF	Plastic	1980 Material Manual
2811	Bay Settlement Rd	N	C	N	1 inch	10/19/1981	Empty Lot		Empty Lot			1980 Material Manual
2814	Bay Settlement Rd	N	C	N	1 inch	10/19/1981	Empty Lot		Empty Lot			1980 Material Manual
2819	Bay Settlement Rd	N	C	N	1 inch	10/19/1981	C	1 inch	8/24/1982	SF	Copper	1980 Material Manual
2826	Bay Settlement Rd	N	C	N	1 inch	10/19/1981	P	1 inch	8/13/2001	SF	Plastic	1980 Material Manual
2832	Bay Settlement Rd	N	C	N	1 inch	10/20/1981	P	1 inch	10/23/2001	SF	Plastic	1980 Material Manual
2833	Bay Settlement Rd	N	C	N	1 inch	10/20/1981	C	1 inch	5/17/1989	SF	Copper	1980 Material Manual
2838	Bay Settlement Rd	N	C	N	1 inch	10/20/1981	P	1 inch	7/6/2001	SF	Plastic	1980 Material Manual
2839	Bay Settlement Rd	N	C	N	1 inch	10/21/1981	C	1 inch	8/12/1988	SF	Plastic	1980 Material Manual
2845	Bay Settlement Rd	N	C	N	1 inch	10/21/1981	C	1 inch	8/24/1988	SF	Copper	1980 Material Manual
2846	Bay Settlement Rd	N	C	N	1 inch	10/21/1981	P	1 inch	5/23/2001	SF	Plastic	1980 Material Manual
2849	Bay Settlement Rd	N	C	N	1 inch	10/22/1981	P	1 inch	10/27/2004	SF	Plastic	1980 Material Manual
2858	Bay Settlement Rd	N	C	N	1 inch	10/22/1981	P	1 inch	6/17/2001	SF	Plastic	1980 Material Manual
2863	Bay Settlement Rd	N	C	N	1 inch	10/22/1981	P	1 inch	9/14/1999	SF	Plastic	1980 Material Manual
2864	Bay Settlement Rd	N	C	N	1 inch	10/25/1981	P	1 inch	5/25/2001	SF	Plastic	1980 Material Manual
2869	Bay Settlement Rd	N	C	N	1 inch	10/25/1981	C	1 inch	7/6/1989	SF	Copper	1980 Material Manual
2875	Bay Settlement Rd	N	C	N	1 inch	10/25/1981	C	1 inch	10/12/1988	SF	Copper	1980 Material Manual
2876	Bay Settlement Rd	N	C	N	1 inch	10/26/1981	P	1 inch	5/2/2001	SF	Plastic	1980 Material Manual
2881	Bay Settlement Rd	N	C	N	1 inch	10/26/1981	C	1 inch	4/6/1987	SF	Copper	1980 Material Manual
2884	Bay Settlement Rd	N	C	N	1 inch	10/26/1981	P	1 inch	7/7/2001	SF	Plastic	1980 Material Manual
2889	Bay Settlement Rd	N	C	N	1 inch	10/27/1981	P	1 inch	6/14/1993	SF	Plastic	1980 Material Manual
2892	Bay Settlement Rd	N	C	N	1 inch	10/27/1981	P	1 inch	11/1/2001	SF	Copper	1980 Material Manual
2895	Bay Settlement Rd	N	C	N	1 inch	10/27/1981	C	1 inch	12/22/1986	SF	Copper	1980 Material Manual
2900	Bay Settlement Rd	N	C	N	1 inch	10/27/1981	P	1 inch	9/23/2001	SF	Plastic	1980 Material Manual
2905	Bay Settlement Rd	N	C	N	1 inch	10/27/1981	C	1 inch	10/31/1986	SF	Copper	1980 Material Manual
2908	Bay Settlement Rd	N	C	N	1 inch	10/27/1981	P	1 inch	4/12/2001	SF	Plastic	1980 Material Manual
2911	Bay Settlement Rd	N	C	N	1 inch	10/27/1981	C	1 inch	6/27/1989	SF	Copper	1980 Material Manual

2916-3428 Bay Settlement Rd and Bay Settlement Ct  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously Lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
2916	Bay Settlement Rd	N	C	N	1 inch	10/27/1981	P	1 inch	8/8/2001	SF	Plastic	1980 Material Manual
2919	Bay Settlement Rd	N	C	N	1 inch	10/27/1981	C	1 inch	9/17/1984	SF	Copper	1980 Material Manual
2920	Bay Settlement Rd	N	C	N	1 inch	10/28/1981	P	1 inch	4/23/2001	SF	Plastic	1980 Material Manual
2921	Bay Settlement Rd	N	C	N	1 inch	10/28/1981	P	1 inch	11/11/1998	SF	Plastic	1980 Material Manual
2926	Bay Settlement Rd	N	C	N	1 inch	10/28/1981	P	1 inch	7/7/2001	SF	Plastic	1980 Material Manual
2932	Bay Settlement Rd	N	C	N	1 inch	10/13/1981	P	1 inch	7/16/2001	SF	Plastic	1980 Material Manual
2933	Bay Settlement Rd	N	C	N	1 inch	10/13/1981	C	1 inch	12/1/1981	SF	Copper	1980 Material Manual
2946	Bay Settlement Rd	N	C	N	1 inch	10/13/1981	P	1 inch	8/19/2001	SF	Plastic	1980 Material Manual
2947	Bay Settlement Rd	N	C	N	1 inch	10/13/1981	C	1 inch	12/27/1982	SF	Copper	1980 Material Manual
2961	Bay Settlement Rd	N	C	N	1 inch	10/12/1981	C	1 inch	12/1/1981	SF	Copper	1980 Material Manual
2966	Bay Settlement Rd	N	C	N	1 inch	10/12/1981	C	1 inch	10/27/2001	SF	Copper	1980 Material Manual
2973	Bay Settlement Rd	N	C	N	1 inch	10/11/1981	C	1 inch	12/15/1981	SF	Copper	1980 Material Manual
2976	Bay Settlement Rd	N	C	N	1 inch	10/11/1981	C	1 inch	8/23/2003	SF	Copper	1980 Material Manual
2977	Bay Settlement Rd	N	C	N	1 inch	10/11/1981	C	1 inch	12/11/1981	SF	Copper	1980 Material Manual
2979	Bay Settlement Rd	N	C	N	1 inch	10/10/1981	C	1 inch	10/27/1988	SF	Copper	1980 Material Manual
2980	Bay Settlement Rd	N	C	N	1 inch	10/10/1981	C	1 inch	12/11/1981	SF	Copper	1980 Material Manual
2985	Bay Settlement Rd	N	C	N	1 inch	10/10/1981	C	1 inch	9/9/1984	SF	Copper	1980 Material Manual
3002	Bay Settlement Rd	N	C	N	1 inch	10/6/1981	C	1 inch	12/30/1981	SCH/CC	Copper	1980 Material Manual
	Holy Cross School Add. 1994	N	C	N	1.5 inch	4/28/1994	C	1.5 inch	8/25/1994	SCH/CC	Copper	Installed after lead ban
3009	Bay Settlement Rd	N	P	N	2 inch	3/15/2019	P	2 inch	3/15/2019	O	Copper	Installed after lead ban
3026	Bay Settlement Rd	N	P	N	1 inch	4/20/2017	P	1 inch	7/18/2017	SF	Plastic	Installed after lead ban
3058	Bay Settlement Rd	N	C	N	1 inch	8/25/1981	C	1 inch	11/28/1981	SF	Copper	1980 Material Manual
3063	Bay Settlement Ct	N	C	N	1 inch	8/8/1989	P	1 inch	10/25/2018	SF	Plastic	Installed after lead ban
3064	Bay Settlement Ct	N	C	N	1 inch	8/8/1989	P	1 inch	12/29/2022	SF	Plastic	Installed after lead ban
3069	Bay Settlement Ct	N	C	N	1 inch	8/8/1989	C	1 inch	10/12/1991	SF	Copper	Installed after lead ban
3071	Bay Settlement Ct	N	C	N	1 inch	8/8/1989	C	1 inch	8/2/1994	SF	Copper, Plastic	Installed after lead ban
3071	Bay Settlement Ct (Poolhouse)	N	P	N	1.50 inch	5/16/2024	P	1.25 inch	5/16/2024	SF	Plastic	Installed after lead ban
3064	Bay Settlement Ct (Not in use)	N	C	N	1 inch	8/8/1989	Not in use					Installed after lead ban
3085	Bay Settlement Rd	N	C	N	1 inch	6/4/1981	P	1 inch	6/11/1990	SF	Plastic	1980 Material Manual
3094	Bay Settlement Rd	N	P	N	1.25 inch	12/1/2020	P	1.25 inch	3/4/2021	SF	Plastic	Installed after lead ban
3095	Bay Settlement Rd	N	P	N	1.5 inch	5/25/2008	P	1.5 inch	11/12/2008	SF	Plastic	Installed after lead ban
3116	Bay Settlement Rd	N	C	N	1 inch	6/4/1981	C	1 inch	11/27/1982	SF	Copper	1980 Material Manual
3119	Bay Settlement Rd	N	C	N	1 inch	5/27/1981	C	1 inch	10/26/1981	SF	Copper	1980 Material Manual
3125	Bay Settlement Rd	N	P	N	1 inch	4/14/2017	P	1 inch	8/12/2017	SF	Plastic	Installed after lead ban
3126	Bay Settlement Rd	N	C	N	1 inch	6/4/1981	C	1 inch	7/3/1982	SF	Copper	1980 Material Manual
3133	Bay Settlement Rd	N	C	N	1 inch	5/26/1981	C	1 inch	11/15/1981	SF	Copper	1980 Material Manual
3141	Bay Settlement Rd	N	P	N	1 inch	6/14/2003	P	1 inch	10/4/2003	SF	Plastic	Installed after lead ban
3171	Bay Settlement Rd	N	C	N	1 inch	5/26/1981	C	1 inch	11/2/1981	SF	Copper	1980 Material Manual
3183	Bay Settlement Rd	N	C	N	1 inch	7/15/1987	C	1 inch	10/25/1987	SF	Copper	Installed after lead ban

2916-3428 Bay Settlement Rd and Bay Settlement Ct  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously Lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
	3195 Bay Settlement Rd	N	C	N	1 inch	5/19/1981	C	1 inch	3/11/1985	SF	Copper	1980 Material Manual
	3209 Bay Settlement Rd	N	C	N	1 inch	6/16/1981	C	1 inch	12/1/1981	SF	Copper	1980 Material Manual
	3221 Bay Settlement Rd	N	C	N	1 inch	5/20/1981	C	1 inch	2/1/1982	SF	Copper	1980 Material Manual
	3225 Bay Settlement Rd	N	P	N	1 inch	6/6/2000	P	1 inch	10/2/2000	SF	Plastic	Installed after lead ban
	3230 Bay Settlement Rd	N	C	N	1 inch	5/20/1981	C	1 inch	12/2/1981	SF	Copper	1980 Material Manual
	3231 Bay Settlement Rd	N	C	N	1 inch	5/19/1981	C	1 inch	11/25/1981	SF	Copper	1980 Material Manual
	3232 Bay Settlement Rd	N	C	N	1 inch	6/1/1981	C	1 inch	11/25/1981	SF	Copper	1980 Material Manual
	3249 Bay Settlement Rd	N	C	N	1 inch	5/5/1981	C	1 inch	12/2/1981	SF	Copper	1980 Material Manual
	3254 Bay Settlement Rd	N	C	N	1 inch	4/17/1981	C	1 inch	11/14/1981	O	Galvan. Copper	1980 Material Manual
	3263 Bay Settlement Rd	N	C	N	1 inch	5/5/1981	C	1 inch	10/20/1981	SF	Copper	1980 Material Manual
	3271 Bay Settlement Rd	N	C	N	1 inch	5/5/1981	P	1 inch	11/11/2021	SF	Plastic	1980 Material Manual
	3279 Bay Settlement Rd	N	C	N	1 inch	4/7/1981	P	1 inch	2/10/1982	SF	Plastic	1980 Material Manual
	3290 Bay Settlement Rd	N	P	N	1 inch	7/9/2003	P	1 inch	12/5/2003	SF	Plastic	Installed after lead ban
	3289 Bay Settlement Rd	N	C	N	1 inch	8/28/1993	C	1 inch	11/1/1993	SF	Copper	Installed after lead ban
	3304 Bay Settlement Rd	N	P	N	1 inch	4/27/1986	P	1 inch	9/9/1986	SF	Plastic	Installed after lead ban
	3305 Bay Settlement Rd	N	C	N	1 inch	7/27/1993	C	1 inch	10/10/1993	SF	Copper	Installed after lead ban
	3325 Bay Settlement Rd	N	C	N	1 inch	4/7/1981	C	1 inch	10/22/1981	SF	Copper	1980 Material Manual
	3326 Bay Settlement Rd	N	P	N	2 inch	8/12/2004	P	2 inch	11/14/2004	SF	Plastic	Installed after lead ban
	3330 Bay Settlement Rd	N	P	N	1.5 inch	8/12/2004	P	1.5 inch	12/15/2004	SF	Plastic	Installed after lead ban
	3331 Bay Settlement Rd	N	C	N	1 inch	4/7/1981	C	1 inch	10/27/1981	SF	Copper	1980 Material Manual
	3343 Bay Settlement Rd	N	C	N	1 inch	4/7/1981	C	1 inch	12/17/1981	SF	Copper	1980 Material Manual
	3344 Bay Settlement Rd	N	P	N	1 inch	6/30/1998	P	1 inch	9/7/1998	SF	Plastic	Installed after lead ban
	3352 Bay Settlement Rd	N	C	N	1 inch	3/15/2000	P	1 inch	7/27/2000	SF	Plastic	Installed after lead ban
LC6	3355 Bay Settlement Rd	N	C	N	1 inch	4/7/1981	C	1 inch	1/9/1982	SF	Copper	1980 Material Manual
	3360 Bay Settlement Rd	N	P	N	1 inch	5/12/2002	P	1 inch	8/18/2002	SF	Plastic	Installed after lead ban
	3361 Bay Settlement Rd	N	C	N	1 inch	4/7/1981	C	1 inch	11/26/1981	SF	Copper	1980 Material Manual
	3367 Bay Settlement Rd	N	C	N	1 inch	5/1/1997	C	1 inch	7/27/1997	SF	Copper	Installed after lead ban
	3370 Bay Settlement Rd	N	P	N	1 inch	7/11/2021	P	1 inch	8/28/1996	SF	Plastic	Installed after lead ban
LC11	3371 Bay Settlement Rd	N	C	N	1 inch	4/7/1981	C	1 inch	2/2/1982	SF	Copper	1980 Material Manual
	3382 Bay Settlement Rd	N	C	N	1 inch	6/2/1981	C	1 inch	4/2/1982	SF	Copper	1980 Material Manual
	3377 Bay Settlement Rd	N	C	N	1 inch	7/14/1991	C	1 inch	10/4/1991	SF	Copper	Installed after lead ban
	3385 Bay Settlement Rd	N	C	N	1 inch	4/7/1981	C	1 inch	12/8/1981	SF	Copper	1980 Material Manual
	3386 Bay Settlement Rd	N	C	N	1 inch	6/2/1981	C	1 inch	11/30/1981	SF	Copper	1980 Material Manual
	3391 Bay Settlement Rd	N	C	N	1 inch	4/7/1981	C	1 inch	5/20/1982	SF	Copper	1980 Material Manual
	3427 Bay Settlement Rd	N	C	N	1 inch	6/8/1981	C	1 inch	12/9/1981	SF	Copper	1980 Material Manual
D5	3426 Bay Settlement Rd (Park)	N	C	N	1 inch	6/8/1981	C	1 inch	5/23/1982	O	Copper	1980 Material Manual

Empty Lots Bay Settlement Rd  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Basis of street side classification
2431 Bay Settlement Rd		N	Copper	N	1 inch	9/16/1980			1980 Material Manual
	SC-221	N	Copper	N	1 inch	9/16/1980			1980 Material Manual
2450 Bay Settlement Rd		N	Copper	N	1 inch	11/19/1980			1980 Material Manual
	SC-225-4	N	Plastic	N	1 inch	5/31/2007			Installed after lead ban
	SC-215-5	N	Plastic	N	1 inch	6/5/2007			Installed after lead ban
	SC-214	N	Plastic	N	1 inch	6/5/2007			Installed after lead ban
	SC-213-1A	N	Plastic	N	1 inch	6/6/2007			Installed after lead ban
	SC-213-1B	N	Plastic	N	1 inch	6/6/2007			Installed after lead ban
	SC-213-1C	N	Plastic	N	1 inch	6/6/2007			Installed after lead ban
	SC-213-1D	N	Plastic	N	1 inch	6/6/2007			Installed after lead ban
	SC-213-1E	N	Plastic	N	1 inch	6/7/2007			Installed after lead ban
	SC-211	N	Copper	N	1 inch	5/11/1981			1980 Material Manual
2610 Bay Settlement Rd		N	Copper	N	2 inch	5/21/1981			1980 Material Manual
2616 Bay Settlement Rd		N	Copper	N	1 inch	5/21/1981			1980 Material Manual
2617 Bay Settlement Rd		N	Plastic	N	1 inch	5/24/2007			Installed after lead ban
	SC-206-1	N	Plastic	N	1 inch	5/29/2007			Installed after lead ban
	SC-208-5	N	Plastic	N	1 inch	5/24/2007			Installed after lead ban
	SC-208-3	N	Plastic	N	1 inch	5/30/2007			Installed after lead ban
	SC-202-1	N	Plastic	N	1 inch	5/30/2007			Installed after lead ban
	SC-201	N	Plastic	N	1 inch	6/11/2007			Installed after lead ban
	SC-203	N	Plastic	N	1 inch	6/1/2007			Installed after lead ban
	SC-195-1-3	N	Plastic	N	1 inch	5/31/2007			Installed after lead ban
	SC-22-120-5	N	Copper	N	1 inch	10/13/1986			Installed after lead ban
	SC-22-91	N	Copper	N	1 inch	10/20/1981			1980 Material Manual
	SC-22-95A	N	Copper	N	1 inch	9/7/1982			1980 Material Manual
	SC-22-95B	N	Copper	N	1 inch	9/7/1982			1980 Material Manual
	SC-797-8	N	Copper	N	1 inch	10/10/1989			Installed after lead ban
	SC-797-2	N	Copper	N	1 inch	10/10/1989			Installed after lead ban
	SC-86-4A	N	Plastic	N	1 inch	8/14/2021			Installed after lead ban
	SC-86-4B	N	Plastic	N	1 inch	8/14/2021			Installed after lead ban
	SC-86-4C	N	Plastic	N	1 inch	8/14/2021			Installed after lead ban
	SC-86-4D	N	Plastic	N	1 inch	8/14/2021			Installed after lead ban
	SC-347-2	N	Plastic	N	1 inch	8/16/2021			Installed after lead ban
	SC-346	N	Plastic	N	1 inch	8/16/2021			Installed after lead ban
	SC-345-A	N	Plastic	N	1 inch	8/21/2021			Installed after lead ban
	SC-345-B	N	Plastic	N	1 inch	8/21/2021			Installed after lead ban
	SC-345-C	N	Plastic	N	1 inch	8/21/2021			Installed after lead ban
	SC-345-D	N	Plastic	N	1 inch	8/21/2021			Installed after lead ban
	SC-83	N	Plastic	N	1 inch	8/23/2021			Installed after lead ban
	SC-337	N	Plastic	N	1 inch	8/23/2021			Installed after lead ban

Van Lanen Rd  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously Lead	Street side service size	Street side install date	Property side material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
	3708 Van Lanen	N	C	N	1 inch	6/2/1981	C and G	1 inch	12/22/1981	SF	Galv. & copper	1980 Material Manual
	3718 Van Lanen	N	C	N	1 inch	5/28/1981	C	1 inch	12/22/1981	SF	Copper	1980 Material Manual
	3720 Van Lanen	N	C	N	1 inch	4/27/1995	P	1 inch	8/13/1995	SF	Plastic	Installed after lead ban
	3726 Van Lanen	N	C	N	1 inch	5/28/1982	C	1 inch	1/11/1982	SF	Copper	1980 Material Manual
	3734 Van Lanen	N	P	N	1 inch	6/27/1995	P	1 inch	9/10/1995	SF	Plastic	Installed after lead ban
	3737 Van Lanen	N	C	N	1 inch	11/3/1980	C	1 inch	6/5/1985	SF	Copper	1980 Material Manual
	3740 Van Lanen	N	P	N	1 inch	7/11/1994	C	1 inch	10/1/1994	SF	Copper	Installed after lead ban
	3742 Van Lanen	N	C	N	1 inch	5/25/1993	P	1 inch	8/9/1993	SF	Plastic	Installed after lead ban
	3750 Van Lanen	N	C	N	1 inch	8/14/1992	C	1 inch	9/26/1992	SF	Copper	Installed after lead ban
	3760 Van Lanen	N	C	N	1 inch	5/1/1993	P	1 inch	10/12/1993	SF	Plastic	Installed after lead ban
	3777 Van Lanen	N	C	N	1 inch	10/20/1986	C	1 inch	10/27/1986	SF	Copper	Installed after lead ban
	3806 Van Lanen	N	C	N	1 inch	5/27/1981	C	1 inch	12/2/1981	SF	Copper	1980 Material Manual
	3829 Van Lanen	N	P	N	1 inch	3/26/2025	P	1 inch	8/28/2025	SF	Plastic	Installed after lead ban
	3833 Van Lanen	N	P	N	1 inch	3/26/2025	P	1 inch	8/25/2025	SF	Plastic	Installed after lead ban
	3837 Van Lanen	N	P	N	1 inch	3/25/2025	P	1.25 inch	5/16/2025	SF	Plastic	Installed after lead ban
	3838 Van Lanen	N	P	N	1 inch	6/15/1988	C	1 inch	8/23/1988	SF	Copper	Installed after lead ban
	3841 Van Lanen	N	P	N	1 inch	3/27/2025	P	1 inch	7/31/2025	SF	Plastic	Installed after lead ban
	3844 Van Lanen	N	P	N	1 inch	7/30/1995	P	1 inch	10/30/1995	SF	Plastic	Installed after lead ban
	3850 Van Lanen	N	C	N	1 inch	6/11/1988	C	1 inch	9/23/1988	SF	Copper	Installed after lead ban
	3858 Van Lanen	N	C	N	1 inch	5/12/1990	C	1 inch	8/14/1990	SF	Copper	Installed after lead ban
	3868 Van Lanen	N	C	N	1 inch	5/12/1990	C	1 inch	8/27/1990	SF	Copper	Installed after lead ban
	3869 Van Lanen	N	P	N	1 inch	3/27/2025	Empty Lot		Empty Lot	SF		Installed after lead ban
	3871 Van Lanen	N	P	N	1 inch	3/28/2025	P	1 inch	7/1/2025	SF	Plastic	Installed after lead ban
	3873 Van Lanen	N	P	N	1 inch	3/28/2025	Empty Lot		Empty Lot	SF		Installed after lead ban
	3874 Van Lanen	N	C	N	1 inch	7/10/1992	C	1 inch	11/12/1992	SF	Copper	Installed after lead ban
	3955 Van Lanen	N	C	N	1 inch	8/10/1997	P	1 inch	11/22/1997	SF	Plastic	Installed after lead ban
	3960 Van Lanen	N	C	N	1 inch	11/2/1981	C	1 inch	12/23/1983	SF	Copper	1980 Material Manual
	3963 Van Lanen	N	P	N	1 inch	5/10/1994	C	1 inch	9/26/1994	SF	Plastic	Installed after lead ban
	3979 Van Lanen	N	C	N	1 inch	6/15/1981	Empty Lot		Empty Lot	SF		1980 Material Manual
	SC-332	N	C	N	1 inch	10/26/1980	Empty Lot		Empty Lot			1980 Material Manual
	SC-336-1	N	P	N	1 inch	7/7/2021	Empty Lot		Empty Lot			Installed after lead ban
	SC-336-2	N	P	N	1 inch	7/7/2021	Empty Lot		Empty Lot			Installed after lead ban

Bay Heights Dr, Sandpiper Way and Heron Ln  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
3309	Bay Heights Dr	N	C	N	1 inch	6/11/2004	Empty lot		Empty Lot			Installed after lead ban
3312	Bay Heights Dr	N	C	N	1 inch	6/11/2004	P	1 inch	7/3/2005	SF	Plastic	Installed after lead ban
3315	Bay Heights Dr	N	C	N	1 inch	6/11/2004	Empty lot		Empty lot			Installed after lead ban
3316	Bay Heights Dr	N	C	N	1 inch	6/10/2004	P	1 inch	8/11/2007	SF	Plastic	Installed after lead ban
3321	Bay Heights Dr	N	C	N	1 inch	6/10/2004	Empty lot		Empty Lot			Installed after lead ban
3320	Bay Heights Dr	N	C	N	1 inch	6/10/2004	P	1 inch	10/14/2004	SF	Plastic	Installed after lead ban
3326	Bay Heights Dr	N	C	N	1 inch	6/9/2004	P	1 inch	10/14/2004	SF	Plastic	Installed after lead ban
3327	Bay Heights Dr	N	C	N	1 inch	6/9/2004	P	1 inch	5/1/2015	SF	Plastic	Installed after lead ban
3331	Bay Heights Dr	N	C	N	1 inch	8/22/1998	P	1 inch	8/21/1999	SF	Plastic	Installed after lead ban
3334	Bay Heights Dr	N	C	N	1 inch	8/22/1998	P	1 inch	8/21/1999	SF	Plastic	Installed after lead ban
3346	Bay Heights Dr	N	C	N	1 inch	8/21/1998	P	1 inch	8/21/1999	SF	Plastic	Installed after lead ban
3347	Bay Heights Dr	N	C	N	1 inch	8/21/1998	P	1 inch	4/14/2000	SF	Plastic	Installed after lead ban
3351	Bay Heights Dr	N	C	N	1 inch	8/20/1998	P	1 inch	6/12/1999	SF	Plastic	Installed after lead ban
3352	Bay Heights Dr	N	C	N	1 inch	8/20/1998	P	1 inch	6/12/1999	SF	Plastic	Installed after lead ban
3353	Bay Heights Dr	N	C	N	1 inch	5/17/1992	P	1 inch	10/1/1997	SF	Plastic	Installed after lead ban
3363	Bay Heights Dr	N	C	N	1 inch	5/17/1992	P	1 inch	7/21/1994	SF	Plastic	Installed after lead ban
3373	Bay Heights Dr	N	C	N	1 inch	5/16/1992	P	1 inch	11/12/1995	SF	Plastic	Installed after lead ban
3383	Bay Heights Dr	N	C	N	1 inch	5/16/1992	P	1 inch	5/25/1996	SF	Plastic	Installed after lead ban
3727	Sandpiper Way	N	C	N	1 inch	8/20/1998	P	1 inch	7/22/2002	SF	Plastic	Installed after lead ban
3742	Sandpiper Way	N	C	N	1 inch	8/20/1998	P	1 inch	6/29/1999	SF	Plastic	Installed after lead ban
3747	Sandpiper Way	N	C	N	1 inch	8/20/1998	P	1 inch	8/23/1999	SF	Plastic	Installed after lead ban
3750	Sandpiper Way	N	C	N	1 inch	8/19/1998	C	1 inch	8/23/1999	SF	Copper	Installed after lead ban
3757	Sandpiper Way	N	C	N	1 inch	8/19/1998	P	1 inch	6/29/1999	SF	Plastic	Installed after lead ban
3758	Sandpiper Way	N	C	N	1 inch	8/19/1998	P	1 inch	7/22/2002	SF	Plastic	Installed after lead ban
3766	Sandpiper Way	N	C	N	1 inch	6/27/1996	P	1 inch	9/9/1999	SF	Plastic	Installed after lead ban
3767	Sandpiper Way	N	C	N	1 inch	8/18/1998	P	1 inch	9/9/1999	SF	Plastic	Installed after lead ban
3772	Sandpiper Way	N	C	N	1 inch	6/27/1996	P	1 inch	9/9/1999	SF	Plastic	Installed after lead ban
3779	Sandpiper Way	N	C	N	1 inch	6/26/1996	P	1 inch	10/11/1998	SF	Plastic	Installed after lead ban
3780	Sandpiper Way	N	C	N	1 inch	6/26/1996	P	1 inch	6/24/1997	SF	Plastic	Installed after lead ban
3790	Sandpiper Way	N	C	N	1 inch	6/26/1996	P	1 inch	10/11/1998	SF	Plastic	Installed after lead ban
3801	Sandpiper Way	N	C	N	1 inch	6/25/1996	C	1 inch	8/1/1999	SF	Copper	Installed after lead ban
3807	Sandpiper Way	N	C	N	1 inch	6/25/1996	P	1 inch	8/1/1999	SF	Plastic	Installed after lead ban
3811	Sandpiper Way	N	C	N	1 inch	6/25/1996	P	1 inch	10/4/1998	SF	Plastic	Installed after lead ban
3816	Sandpiper Way	N	C	N	1 inch	6/24/1996	P	1 inch	10/4/1998	SF	Plastic	Installed after lead ban
3821	Sandpiper Way	N	C	N	1 inch	6/24/1996	P	1 inch	10/4/1998	SF	Plastic	Installed after lead ban
3831	Sandpiper Way	N	C	N	1 inch	6/24/1996	P	1 inch	10/4/1998	SF	Plastic	Installed after lead ban
3838	Sandpiper Way	N	C	N	1 inch	8/14/1999	C	1 inch	7/30/2003	SF	Copper	Installed after lead ban
3841	Sandpiper Way	N	C	N	1 inch	8/14/1999	P	1 inch	11/2/2000	SF	Plastic	Installed after lead ban
3850	Sandpiper Way	N	C	N	1 inch	8/14/1999	P	1 inch	11/2/2000	SF	Plastic	Installed after lead ban
3851	Sandpiper Way	N	C	N	1 inch	8/15/1999	P	1 inch	6/28/2001	SF	Plastic	Installed after lead ban
3860	Sandpiper Way	N	C	N	1 inch	8/15/1999	P	1 inch	8/20/2002	SF	Plastic	Installed after lead ban

Bay Heights Dr, Sandpiper Way and Heron Ln  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
3861	Sandpiper Way	N	C	N	1 inch	8/15/1999	P	1 inch	7/14/2005	SF	Plastic	Installed after lead ban
3871	Sandpiper Way	N	C	N	1 inch	8/16/1999	P	1 inch	4/26/2021	SF	Plastic	Installed after lead ban
3878	Sandpiper Way	N	C	N	1 inch	8/16/1999	P	1 inch	5/12/2002	SF	Plastic	Installed after lead ban
3881	Sandpiper Way	N	C	N	1 inch	8/16/1999	P	1 inch	9/23/2000	SF	Plastic	Installed after lead ban
3891	Sandpiper Way	N	C	N	1 inch	8/20/1999	C	1 inch	5/12/2002	SF	Copper	Installed after lead ban
3892	Sandpiper Way	N	C	N	1 inch	8/20/1999	C	1 inch	6/22/2001	SF	Copper	Installed after lead ban
3901	Sandpiper Way	N	C	N	1 inch	8/20/1999	C	1 inch	9/23/2000	SF	Copper	Installed after lead ban
3743	Heron Lane	N	C	N	1 inch	5/18/1992	P	1 inch	4/26/1995	SF	Plastic	Installed after lead ban
3744	Heron Lane	N	C	N	1 inch	5/18/1992	P	1 inch	7/27/1995	SF	Plastic	Installed after lead ban
3750	Heron Lane	N	C	N	1 inch	5/18/1992	P	1 inch	4/26/1995	SF	Plastic	Installed after lead ban
3751	Heron Lane	N	C	N	1 inch	5/18/1992	C	1 inch	7/27/1995	SF	Copper	Installed after lead ban
3752	Heron Lane	N	C	N	1 inch	6/1/1994	P	1 inch	9/20/1996	SF	Plastic	Installed after lead ban
3753	Heron Lane	N	C	N	1 inch	6/1/1994	P	1 inch	9/20/1996	SF	Plastic	Installed after lead ban
3757	Heron Lane	N	C	N	1 inch	6/1/1994	P	1 inch	6/22/1997	SF	Plastic	Installed after lead ban
3761	Heron Lane	N	C	N	1 inch	6/2/1994	P	1 inch	6/22/1997	SF	Plastic	Installed after lead ban

Loon Ln, Egret Dr, Osprey Ln and Sparrow Ln  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously Lead	Street side service size	Street side install date	Property side material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
3210	Loon Ln	N	C	N	1 inch	9/10/1996	P	1 inch	5/24/1998	SF	Plastic	Installed after lead ban
3215	Loon Ln	N	C	N	1 inch	7/12/2001	P	1 inch	10/4/2002	SF	Plastic	Installed after lead ban
3220	Loon Ln	N	C	N	1 inch	7/12/2001	P	1 inch	9/14/2001	SF	Plastic	Installed after lead ban
3240	Loon Ln	N	C	N	1 inch	7/11/2001	P	1 inch	5/1/2002	SF	Plastic	Installed after lead ban
3260	Loon Ln	N	C	N	1 inch	7/11/2001	P	1 inch	8/11/2002	SF	Plastic	Installed after lead ban
3275	Loon Ln	N	C	N	1 inch	7/11/2001	P	1 inch	6/27/2002	SF	Plastic	Installed after lead ban
3335	Loon Ln	N	C	N	1 inch	7/10/2001	C	1 inch	11/5/2002	SF	Copper	Installed after lead ban
3338	Loon Ln	N	C	N	1 inch	7/10/2001	P	1 inch	7/22/2002	SF	Plastic	Installed after lead ban
3367	Loon Ln	N	C	N	1 inch	7/9/2001	P	1 inch	8/11/2002	SF	Plastic	Installed after lead ban
3370	Loon Ln	N	C	N	1 inch	7/9/2001	P	1 inch	5/27/2002	SF	Plastic	Installed after lead ban
3311	Egret	N	C	N	1 inch	7/27/2003	Empty Lot		Empty Lot			Installed after lead ban
3318	Egret	N	P	N	1 inch	replaced 02/14/2017	P	1 inch	6/24/2006	SF	Plastic	Installed after lead ban
3319	Egret	N	C	N	1 inch	7/27/2003	P	1 inch	9/12/2005	SF	Plastic	Installed after lead ban
3327	Egret	N	C	N	1 inch	7/27/2003	P	1 inch	7/17/2017	SF	Plastic	Installed after lead ban
3358	Egret	N	C	N	1 inch	6/15/2001	P	1 inch	5/12/2004	SF	Plastic	Installed after lead ban
3761	Egret	N	C	N	1 inch	6/15/2001	P	1 inch	8/29/2002	SF	Plastic	Installed after lead ban
3764	Egret	N	C	N	1 inch	6/15/2001	P	1 inch	6/22/2015	SF	Plastic	Installed after lead ban
3770	Egret	N	C	N	1 inch	6/13/2001	P	1 inch	10/26/2002	SF	Plastic	Installed after lead ban
3773	Egret	N	C	N	1 inch	6/13/2001	C	1 inch	8/27/2001	SF	Copper	Installed after lead ban
3778	Egret	N	C	N	1 inch	6/12/2001	P	1 inch	5/11/2002	SF	Plastic	Installed after lead ban
3785	Egret	N	C	N	1 inch	6/12/2001	P	1 inch	7/26/2002	SF	Plastic	Installed after lead ban
3798	Egret	N	C	N	1 inch	6/12/2001	P	1 inch	6/8/2002	SF	Plastic	Installed after lead ban
3290	Osprey	N	P	N	1 inch	replaced 05/05/2014	Empty Lot		Empty Lot			Installed after lead ban
3300	Osprey	N	P	N	1 inch	replaced 05/05/2014	Empty Lot		Empty Lot			Installed after lead ban
3307	Osprey	N	P	N	1 inch	replaced 05/05/2014	P	1 inch	7/23/2005	SF	Plastic	Installed after lead ban
3310	Osprey	N	P	N	1 inch	replaced 05/05/2014	P	1 inch	7/23/2005	SF	Plastic	Installed after lead ban
3315	Osprey	N	P	N	1 inch	replaced 05/06/2014	P	1 inch	9/29/2011	SF	Plastic	Installed after lead ban
3316	Osprey	N	P	N	1 inch	replaced 05/06/2014	P	1 inch	6/16/2010	SF	Plastic	Installed after lead ban
3320	Osprey	N	P	N	1 inch	replaced 05/06/2014	C	1 inch	5/25/2012	SF	Plastic	Installed after lead ban
3323	Osprey	N	P	N	1 inch	replaced 05/06/2014	P	1 inch	8/10/2010	SF	Plastic	Installed after lead ban
3327	Osprey	N	P	N	1 inch	replaced 05/07/2014	P	1 inch	6/14/2008	SF	Plastic	Installed after lead ban
3328	Osprey	N	P	N	1 inch	replaced 05/07/2014	P	1 inch	9/27/2015	SF	Plastic	Installed after lead ban
3331	Osprey	N	P	N	1 inch	replaced 05/07/2014	P	1 inch	7/7/2011	SF	Plastic	Installed after lead ban
3332	Osprey	N	P	N	1 inch	replaced 05/07/2014	P	1 inch	5/14/2002	SF	Plastic	Installed after lead ban
3350	Sparrow	N	P	N	1 inch	5/27/1994	C	1 inch	6/23/1996	SF	Copper	Installed after lead ban
3351	Sparrow	N	P	N	1 inch	5/27/1994	P	1 inch	8/7/1996	SF	Plastic	Installed after lead ban
3360	Sparrow	N	P	N	1 inch	5/27/1994	P	1 inch	5/19/2025	SF	Plastic	Installed after lead ban

Nicolet Dr  
Lead and Copper Report

Site ID	Address	Street side Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
	3588 Nicolet Dr	N	P	N	1.25 inch	11/12/2019	P	1.25 inch	11/12/2019	SF	Plastic	Installed after lead ban
	3601 Nicolet Dr	N	P	N	2 inch	7/13/2020	C	1.25 inch	7/13/2020	SF	Copper	Installed after lead ban
	3610 Nicolet Dr	N	C	N	1 inch	9/28/1981	P	1 inch	6/30/1999	SF	Plastic	1980 Material Manual
	3647 Nicolet Dr	N	C	N	1 inch	9/28/1981	C	1 inch	10/11/1981	SF	Plastic	1980 Material Manual
	3663 Nicolet Dr	N	C	N	1 inch	9/28/1981	P	1 inch	10/11/1981	SF	Copper	1980 Material Manual
	3721 Nicolet Dr	N	C	N	1 inch	9/28/1981	C	1 inch	1/14/1982	SF	Copper	1980 Material Manual
	3726 Nicolet Dr	N	P	N	2 inch	9/26/2023	Plastic (Not Connected)	2 inch	9/26/2023	SF	Plastic	Installed after lead ban
	3730 Nicolet Dr	N	C	N	1 inch	9/30/1981	C	1 inch	8/1/1990	SF	Copper	1980 Material Manual
	3754 Nicolet Dr	N	C	N	1 inch	9/30/1981	P	1 inch	12/12/1982	SF	Plastic	1980 Material Manual
	3762 Nicolet Dr	N	C	N	1 inch	9/30/1981	P	1 inch	7/1/2013	SF	Plastic	1980 Material Manual
	3802 Nicolet Dr	N	C	N	1 inch	9/10/1998	Empty Lot		Empty Lot			Installed after lead ban
	3810 Nicolet Dr	N	C	N	1 inch	9/10/1998	C	1 inch	5/14/2000	SF	Copper	Installed after lead ban
	3820 Nicolet Dr	N	C	N	1 inch	9/10/1998	P	1 inch	9/9/2001	SF	Plastic	Installed after lead ban
	3830 Nicolet Dr	N	C	N	1 inch	9/9/1998	P	1 inch	9/9/2001	SF	Plastic	Installed after lead ban
	3840 Nicolet Dr	N	C	N	1 inch	9/9/1998	C	1 inch	8/10/1999	SF	Copper	Installed after lead ban
	3850 Nicolet Dr	N	C	N	1 inch	9/9/1998	P	1 inch	8/10/1999	SF	Plastic	Installed after lead ban
	3860 Nicolet Dr	N	C	N	1 inch	9/8/1998	P	1 inch	8/10/1999	SF	Plastic	Installed after lead ban
	3890 Nicolet Dr	N	C	N	1 inch	3/26/1981	Empty Lot		Empty Lot			Installed after lead ban
	3895 Nicolet Dr	N	C	N	1 inch	7/22/1981	C	1 inch	11/28/1981	SF	Copper	1980 Material Manual
LC15	3928 Nicolet Dr	N	C	N	1 inch	3/26/1981	C	1 inch	6/12/1982	SF	Copper	1980 Material Manual
	3944 Nicolet Dr	N	C	N	1 inch	3/26/1981	C	1 inch	5/24/1983	SF	Copper	1980 Material Manual
	3947 Nicolet Dr	N	C	N	1 inch	7/27/1981	P	1 inch	3/27/1982	SF	Plastic	1980 Material Manual
	3957 Nicolet Dr	N	C	N	1 inch	7/27/1981	C	1 inch	3/27/1982	SF	Copper	1980 Material Manual
	3963 Nicolet Dr	N	C	N	1 inch	7/28/1981	C	1 inch	11/30/1981	SF	Copper	1980 Material Manual
	3967 Nicolet Dr	N	C	N	1 inch	7/28/1981	P	1 inch	6/21/1983	SF	Plastic	1980 Material Manual
	3971 Nicolet Dr	N	C	N	1 inch	7/28/1981	C	1 inch	11/10/1981	SF	Copper	1980 Material Manual
	3990 Nicolet Dr	N	C	N	1 inch	7/28/1981	C	1 inch	1/14/1982	SF	Copper	1980 Material Manual
	3996 Nicolet Dr	N	C	N	1 inch	7/28/1981	Disconnected 09/11/2023					1980 Material Manual
	4000 Nicolet Dr	N	P	N	1 inch	3/9/2008	C	1 inch	10/10/2008	SF	Copper	Installed after lead ban
	4030 Nicolet Dr	N	P	N	1 inch	6/12/2021	P	1 inch	10/7/2021	SF	Plastic	Installed after lead ban
	4046 Nicolet Dr	N	P	N	1 inch	3/9/2008	P	1 inch	11/23/2010	SF	Plastic	Installed after lead ban
	4050 Nicolet Dr	N	P	N	1 inch	3/9/2008	P	1 inch	11/23/2010	O	Copper	Installed after lead ban
	4061 Nicolet Dr	N	P	N	1 inch	3/9/2008	P	1 inch	1/22/2011	SF	Plastic	Installed after lead ban
	4069 Nicolet Dr	N	P	N	1 inch	3/8/2008	P	1 inch	5/25/2008	SF	Copper	Installed after lead ban
	4070 Nicolet Dr	N	P	N	1 inch	3/8/2008	P	1 inch	1/7/2011	SF	Plastic	Installed after lead ban
	4077 Nicolet Dr	N	P	N	1 inch	3/8/2008	P	1 inch	6/14/2009	SF	Plastic	Installed after lead ban
	4087 Nicolet Dr	N	P	N	1 inch	3/8/2008	P	1 inch	12/11/2010	SF	Plastic	Installed after lead ban
	4101 Nicolet Dr	N	P	N	1 inch	3/7/2008	P	1 inch	11/18/2010	SF	Plastic	Installed after lead ban
	4124 Nicolet Dr	N	P	N	1 inch	3/7/2008	P	1 inch	12/18/2010	SF	Plastic	Installed after lead ban
	4125 Nicolet Dr	N	P	N	1 inch	3/7/2008	P	1 inch	1/7/2011	SF	Copper	Installed after lead ban
	4137 Nicolet Dr	N	P	N	1 inch	3/7/2008	C	1 inch	12/10/2011	SF	Copper	Installed after lead ban
	4139 Nicolet Dr	N	P	N	1 inch	3/6/2008	P	1 inch	12/18/2010	SF	Plastic	Installed after lead ban

Nicolet Dr  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
4143	Nicolet Dr	N	P	N	1 inch	3/6/2008	C	1 inch	12/7/2010	SF	Copper	Installed after lead ban
4149	Nicolet Dr	N	P	N	1 inch	3/6/2008	P	1 inch	1/7/2011	SF	Copper	Installed after lead ban
4159	Nicolet Dr	N	P	N	1 inch	3/6/2008	C	1 inch	12/30/2010	SF	Copper	Installed after lead ban
4160	Nicolet Dr	N	P	N	2 inch	3/2/2008	P	2 inch	1/18/2012	SF	Copper	Installed after lead ban
4171	Nicolet Dr	N	P	N	1 inch	3/2/2008	C	1 inch	12/11/2010	SF	Copper	Installed after lead ban
4181	Nicolet Dr	N	P	N	1 inch	3/2/2008	P	1 inch	1/7/2011	SF	Plastic	Installed after lead ban
4188	Nicolet Dr	N	P	N	1 inch	3/2/2008	P	1 inch	11/23/2010	SF	Plastic	Installed after lead ban
4197	Nicolet Dr	N	P	N	1 inch	3/1/2008	C	1 inch	11/26/2010	SF	Copper	Installed after lead ban
4201	Nicolet Dr	N	P	N	1 inch	3/1/2008	P	1 inch	11/26/2019	SF	Plastic	Installed after lead ban
4203	Nicolet Dr	N	P	N	1 inch	3/1/2008	C	1 inch	4/27/2009	SF	Plastic	Installed after lead ban
4209	Nicolet Dr	N	P	N	1 inch	3/1/2008	P	1 inch	12/16/2024	SF	Plastic	Installed after lead ban
4217	Nicolet Dr	N	P	N	1 inch	2/28/2008	C	1 inch	11/18/2010	SF	Copper	Installed after lead ban
4223	Nicolet Dr	N	P	N	1.5 inch	2/28/2008	P	1.5 inch	11/23/2010	SF	Copper	Installed after lead ban
4231	Nicolet Dr	N	P	N	1 inch	10/14/2010	P	1 inch	1/28/2011	SF	Plastic	Installed after lead ban
4241	Nicolet Dr	N	P	N	1.25 inch	2/28/2008	P	1.25 inch	1/3/2011	SF	Plastic	Installed after lead ban
4256	Nicolet Dr	N	P	N	1 inch	2/27/2008	C	1 inch	11/23/2010	SF	Copper	Installed after lead ban
4260	Nicolet Dr	N	P	N	1 inch	2/27/2008	P	1 inch	11/26/2010	SF	Plastic	Installed after lead ban
4268	Nicolet Dr	N	P	N	1 inch	2/27/2008	P	1 inch	11/26/2010	SF	Plastic	Installed after lead ban
4276	Nicolet Dr	N	P	N	1 inch	2/26/2008	C	1 inch	11/26/2010	SF	Copper	Installed after lead ban
4280	Nicolet Dr	N	P	N	1 inch	2/26/2008	C	1 inch	11/18/2010	SF	Copper	Installed after lead ban
4285	Nicolet Dr	N	P	N	1 inch	2/26/2008	P	1 inch	8/15/2014	SF	Plastic	Installed after lead ban
4293	Nicolet Dr	N	P	N	1 inch	2/23/2008	P	1 inch	12/7/2010	SF	Plastic	Installed after lead ban
4305	Nicolet Dr	N	P	N	1 inch	2/23/2008	P	1 inch	12/7/2010	SF	Plastic	Installed after lead ban
4311	Nicolet Dr	N	P	N	1 inch	2/23/2008	P	1 inch	7/2/2013	SF	Plastic	Installed after lead ban
4325	Nicolet Dr	N	P	N	1 inch	2/23/2008	P	1 inch	12/31/2011	SF	Plastic	Installed after lead ban
4329	Nicolet Dr	N	P	N	1 inch	2/23/2008	P	1 inch	4/1/2009	SF	Plastic	Installed after lead ban
4345	Nicolet Dr	N	P	N	1.5 inch	2/22/2008	P	1.5 inch	7/14/2010	SF	Plastic	Installed after lead ban
4361	Nicolet Dr	N	P	N	1 inch	2/22/2008	C	1 inch	2/7/2022	SF	Plastic	Installed after lead ban
4367	Nicolet Dr	N	P	N	1.5 inch	2/22/2008	P	1.5 inch	4/22/2020	SF	Plastic	Installed after lead ban
4373	Nicolet Dr	N	P	N	1.5 inch	2/22/2008	P	1.5 inch	3/2/2018	SF	Plastic	Installed after lead ban
4381	Nicolet Dr	N	P	N	1.5 inch	2/21/2008	P	1.5 inch	11/26/2010	SF	Plastic	Installed after lead ban
4383	Nicolet Dr	N	P	N	1 inch	2/21/2008	P	1 inch	11/30/2010	SF	Plastic	Installed after lead ban
4392	Nicolet Dr	N	P	N	1 inch	2/21/2008	Not Connected	Not Connected	Not Connected	SF		Installed after lead ban
4414	Nicolet Dr	N	P	N	1 inch	2/17/2008	P	1 inch	11/23/2010	SF	Copper	Installed after lead ban
4418	Nicolet Dr	N	P	N	1 inch	2/17/2008	P	1 inch	11/23/2010	SF	Copper	Installed after lead ban
4422	Nicolet Dr	N	P	N	1 inch	2/17/2008	P	1 inch	11/26/2010	SF	Plastic	Installed after lead ban
4429	Nicolet Dr	N	P	N	1 inch	2/16/2008	P	1 inch	11/2/2009	SF	Plastic	Installed after lead ban

## Shorecrest and Scotchman Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
	3730 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	5/25/2005	SF	Plastic	Installed after lead ban
	3739 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	9/9/2007	SF	Plastic	Installed after lead ban
	3740 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	10/11/2005	SF	Plastic	Installed after lead ban
	3745 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	6/16/2012	SF	Plastic	Installed after lead ban
	3750 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	7/1/2004	SF	Plastic	Installed after lead ban
	3760 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	8/30/2005	SF	Plastic	Installed after lead ban
	3763 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	3/23/2012	SF	Plastic	Installed after lead ban
	3780 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	10/4/2007	SF	Plastic	Installed after lead ban
	3785 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	10/26/2015	SF	Plastic	Installed after lead ban
	3790 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	5/5/2007	SF	Plastic	Installed after lead ban
	3793 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	3/12/2008	SF	Plastic	Installed after lead ban
	3808 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	4/27/2007	SF	Plastic	Installed after lead ban
	3810 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	6/30/2013	SF	Plastic	Installed after lead ban
	3811 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	11/3/2022	SF	Plastic	Installed after lead ban
	3815 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	11/3/2022	SF	Plastic	Installed after lead ban
	3816 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	2/13/2013	SF	Plastic	Installed after lead ban
	3820 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	4/1/2013	SF	Plastic	Installed after lead ban
	3823 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	3/25/2016	SF	Plastic	Installed after lead ban
	3825 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	5/1/2016	SF	Plastic	Installed after lead ban
	3826 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	7/20/2014	SF	Plastic	Installed after lead ban
	3830 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	10/12/2015	SF	Plastic	Installed after lead ban
	3831 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	8/1/2016	SF	Plastic	Installed after lead ban
	3834 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	7/7/2015	SF	Plastic	Installed after lead ban
	3834 Shorecrest Ct	N	C	N	1 inch	2/19/2004	P	1 inch	8/21/2006	SF	Plastic	Installed after lead ban
D7	3835 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	6/6/2016	SF	Plastic	Installed after lead ban
	3835 Shorecrest Ct	N	C	N	1 inch	2/19/2004	P	1 inch	3/23/2004	SF	Plastic	Installed after lead ban
	3836 Shorecrest Ct	N	C	N	1 inch	2/19/2004	P	1 inch	8/21/2006	SF	Plastic	Installed after lead ban
	3838 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	5/27/2021	SF	Plastic	Installed after lead ban
	3839 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	10/21/2022	SF	Plastic	Installed after lead ban
	3840 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	5/27/2021	SF	Plastic	Installed after lead ban
	3840 Shorecrest Ct	N	C	N	1 inch	2/19/2004	P	1 inch	5/1/2017	SF	Plastic	Installed after lead ban
	3841 Shorecrest Ln	N	P	N	1 inch	1/15/2007	P	1 inch	10/21/2022	SF	Plastic	Installed after lead ban
	3841 Shorecrest Ct	N	C	N	1 inch	2/19/2004	P	1 inch	4/14/2012	SF	Plastic	Installed after lead ban
	3844 Shorecrest Ct	N	C	N	1 inch	2/19/2004	P	1 inch	9/19/2011	SF	Plastic	Installed after lead ban
	3848 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	2/12/2007	SF	Plastic	Installed after lead ban
	3852 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	6/20/2006	SF	Plastic	Installed after lead ban
	3853 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	5/25/2006	SF	Plastic	Installed after lead ban
	3858 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	8/26/2011	SF	Plastic	Installed after lead ban
	3859 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	7/5/2012	SF	Plastic	Installed after lead ban
	3862 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	5/25/2006	SF	Plastic	Installed after lead ban
	3868 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	3/14/2007	SF	Plastic	Installed after lead ban
	3871 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	10/10/2016	SF	Plastic	Installed after lead ban
	3876 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	2/21/2009	SF	Plastic	Installed after lead ban

Shorecrest and Scotchman  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
	3886 Shorecrest Trail	N	C	N	1 inch	2/19/2004	P	1 inch	11/11/2010	SF	Plastic	Installed after lead ban
	3896 Shorecrest Trail	N	C	N	1 inch	2/18/2004	P	1 inch	8/28/2013	SF	Plastic	Installed after lead ban
	3756 Scotchman	N	C	N	1 inch	2/18/2004	P	1 inch	2/14/2014	SF	Plastic	Installed after lead ban
	3764 Scotchman	N	C	N	1 inch	2/18/2004	P	1 inch	2/14/2014	SF	Plastic	Installed after lead ban
	3771 Scotchman	N	C	N	1 inch	2/18/2004	P	1 inch	7/5/2012	SF	Plastic	Installed after lead ban
	3786 Scotchman	N	C	N	1 inch	2/18/2004	P	1 inch	3/30/2015	SF	Plastic	Installed after lead ban
	3787 Scotchman	N	C	N	1 inch	2/18/2004	P	1 inch	4/28/2004	SF	Plastic	Installed after lead ban
	3794 Scotchman	N	C	N	1 inch	2/18/2004	P	1 inch	10/2/2015	SF	Plastic	Installed after lead ban
	3795 Scotchman	N	C	N	1 inch	2/18/2004	P	1 inch	7/7/2005	SF	Plastic	Installed after lead ban
	3801 Scotchman	N	P	N	1 inch	1/15/2007	C	1 inch	7/21/2011	SF	Plastic	Installed after lead ban
	3805 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	3/12/2009	SF	Plastic	Installed after lead ban
	3809 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	3/12/2009	SF	Plastic	Installed after lead ban
	3810 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	9/9/2012	SF	Plastic	Installed after lead ban
	3815 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	6/12/2009	SF	Plastic	Installed after lead ban
	3817 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	9/3/2011	SF	Plastic	Installed after lead ban
	3818 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	10/14/2011	SF	Plastic	Installed after lead ban
	3821 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	1/20/2009	SF	Plastic	Installed after lead ban
	3822 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	9/12/2018	SF	Plastic	Installed after lead ban
	3829 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	4/28/2014	SF	Plastic	Installed after lead ban
	3830 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	5/25/2010	SF	Plastic	Installed after lead ban
	3832 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	10/26/2016	SF	Plastic	Installed after lead ban
	3835 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	6/15/2013	SF	Plastic	Installed after lead ban
	3841 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	6/15/2013	SF	Plastic	Installed after lead ban
	3855 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	6/15/2013	SF	Plastic	Installed after lead ban
	3865 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	4/7/2014	SF	Plastic	Installed after lead ban
	3869 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	3/29/2013	SF	Plastic	Installed after lead ban
	3871 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	3/29/2013	SF	Plastic	Installed after lead ban
	3881 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	7/10/2015	SF	Plastic	Installed after lead ban
	3891 Scotchman	N	P	N	1 inch	1/15/2007	P	1 inch	7/10/2015	SF	Plastic	Installed after lead ban

Meunier Ln, Fischer Rd, Point Ln, Web Rd, and Grove Rd

Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
	3860 Muenier	N	P	N	1 inch	1/15/2007	Empty Lot		Empty Lot			Installed after lead ban
	3861 Muenier	N	P	N	1 inch	1/15/2007	P	1 inch	6/10/2019	SF	Plastic	Installed after lead ban
	3864 Muenier	N	P	N	1 inch	1/15/2007	Empty Lot		Empty Lot			Installed after lead ban
	3865 Muenier	N	P	N	1 inch	1/15/2007	P	1 inch	6/29/2018	SF	Plastic	Installed after lead ban
	3868 Muenier	N	P	N	1 inch	1/15/2007	P	1 inch	12/17/2025	SF	Plastic	Installed after lead ban
	3869 Muenier	N	P	N	1 inch	1/15/2007	P	1 inch	11/1/2016	SF	Plastic	Installed after lead ban
	3872 Muenier	N	P	N	1 inch	1/15/2007	P	1 inch	10/30/2019	SF	Plastic	Installed after lead ban
	3876 Muenier	N	P	N	1 inch	1/15/2007	P	1 inch	6/17/2025	SF	Plastic	Installed after lead ban
	3877 Muenier	N	P	N	1 inch	1/15/2007	P	1 inch	4/11/2017	SF	Plastic	Installed after lead ban
	3800 Fischer Rd	N	C	N	1 inch	3/1/2004	P	1 inch	8/2/2016	SF	Plastic	Installed after lead ban
	3820 Fischer Rd	N	C	N	1 inch	3/1/2004	P	1 inch	5/5/2005	SF	Plastic	Installed after lead ban
	3833 Fischer Rd	N	C	N	1 inch	3/1/2004	Not Connected		Not Connected			Installed after lead ban
	3850 Fischer Rd	N	C	N	1 inch	3/1/2004	P	1 inch	8/23/2004	SF	Plastic	Installed after lead ban
LC16	3625 Point Ln	N	C	N	1 inch	8/17/1981	P	1 inch	7/4/2011	SF	Plastic	1980 Material Manual
	3637 Point Ln	N	C	N	1 inch	8/18/1981	C	1 inch	12/18/1981	SF	Copper	1980 Material Manual
	3641 Point Ln	N	C	N	1 inch	8/18/1981	P	1 inch	6/15/2009	SF	Plastic	1980 Material Manual
	3647 Point Ln	N	C	N	1 inch	8/18/1981	C	1 inch	1/11/1982	SF	Copper	1980 Material Manual
	3649 Point Ln	N	C	N	1 inch	8/17/1981	P	1 inch	4/14/2000	SF	Plastic	1980 Material Manual
LC9	3659 Point Ln	N	C	N	1 inch	8/17/1981	C	1 inch	12/12/1981	SF	Copper	1980 Material Manual
	3665 Point Ln	N	C	N	1 inch	8/6/1981	C	1 inch	12/11/1981	SF	Copper	1980 Material Manual
	3669 Point Ln	N	C	N	1 inch	8/6/1981	C	1 inch	3/5/1982	SF	Copper	1980 Material Manual
	3683 Point Ln	N	C	N	1 inch	8/6/1981	C	1 inch	3/5/1982	SF	Copper	1980 Material Manual
	3689 Point Ln	N	C	N	1 inch	8/10/1981	C	1 inch	12/1/1981	SF	Copper	1980 Material Manual
	3699 Point Ln	N	C	N	1 inch	8/10/1981	C	1 inch	9/16/1982	SF	Copper	1980 Material Manual
	3709 Point Ln	N	C	N	1 inch	8/10/1981	C	1 inch	7/19/1992	SF	Copper	1980 Material Manual
	3779 Point Ln	N	C	N	1 inch	7/23/1981	C	1 inch	7/19/1982	SF	Copper	1980 Material Manual
	3901 Web Rd	N	C	N	1 inch	7/23/1981	C	1 inch	5/14/1990	SF	Copper	1980 Material Manual
	3904 Web Rd	N	C	N	1 inch	12/9/1980	C	1 inch	7/28/1982	SF	Copper	1980 Material Manual
	3908 Web Rd	N	C	N	1 inch	12/29/1980	C	1 inch	6/16/1982	SF	Copper	1980 Material Manual
	3909 Web Rd	N	C	N	1 inch	12/29/1980	P	1 inch	3/21/1998	SF	Plastic	1980 Material Manual
	3910 Web Rd	N	C	N	1 inch	12/29/1980	C	1 inch	8/10/2004	SF	Copper	1980 Material Manual
	3915 Web Rd	N	C	N	1 inch	1/6/1981	P	1 inch	9/9/1999	SF	Plastic	1980 Material Manual
	3929 Web Rd	N	C	N	1 inch	1/6/1981	C	1 inch	1/9/1982	SF	Not connected	1980 Material Manual
	3709 Grove Rd	N	C	N	1 inch	1/6/1981	C	1 inch	12/13/1981	SF	Copper	1980 Material Manual
	3719 Grove Rd	N	C	N	1 inch	1/6/1981	P	1 inch	9/11/2023	SF	Plastic	1980 Material Manual
	3720 Grove Rd	N	P	N	1 inch		Empty Lot		Empty Lot			
	3725 Grove Rd	N	C	N	1 inch	1/7/1981	C	1 inch	5/1/1983	SF	Copper	1980 Material Manual
LC14	3730 Grove Rd	N	C	N	1 inch	1/7/1981	C	1 inch	11/3/1981	SF	Copper	1980 Material Manual
	3731 Grove Rd	N	C	N	1 inch	1/21/1981	P	1 inch	12/21/1981	SF	Plastic	1980 Material Manual
	3734 Grove Rd	N	C	N	1 inch	1/21/1981	P	1 inch	5/20/1982	SF	Plastic	1980 Material Manual

Meunier Ln, Fischer Rd, Point Ln, Web Rd, and Grove Rd

Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
	3737 Grove Rd	N	C	N	1 inch	1/21/1981	C	1 inch	12/24/1981	SF	Copper	1980 Material Manual
	3742 Grove Rd	N	C	N	1 inch	1/12/1981	C	1 inch	1/6/1982	SF	Copper	1980 Material Manual
	3745 Grove Rd	N	C	N	1 inch	12/13/1981	C	1 inch	2/25/1982	SF	Copper	1980 Material Manual
	3748 Grove Rd	N	C	N	1 inch	12/13/1981	C	1 inch	10/10/1992	SF	Copper	1980 Material Manual
LC8	3755 Grove Rd	N	C	N	1 inch	1/22/1981	C	1 inch	2/26/1982	SF	Copper	1980 Material Manual
	3759 Grove Rd	N	C	N	1 inch	7/30/1981	P	1 inch	3/8/1982	SF	Plastic	1980 Material Manual
LC13	3763 Grove Rd	N	C	N	1 inch	1/12/1981	C	1 inch	1/7/1982	SF	Copper	1980 Material Manual
	3765 Grove Rd	N	C	N	1 inch	1/12/1981	C	1 inch	12/24/1981	SF	Copper	1980 Material Manual
	3773 Grove Rd	N	C	N	1 inch	1/28/1981	C	1 inch	1/30/1982	SF	Copper	1980 Material Manual
	3774 Grove Rd	N	C	N	1 inch	1/28/1981	C	1 inch	1/2/1987	SF	Copper	1980 Material Manual
LC7	3775 Grove Rd	N	C	N	1 inch	1/27/1981	C	1 inch	3/17/1982	SF	Copper	1980 Material Manual
	3776 Grove Rd	N	C	N	1 inch	1/27/1981	C	1 inch	5/7/1982	SF	Copper	1980 Material Manual
	3779 Grove Rd	N	C	N	1 inch	7/30/1981	C	1 inch	12/10/1981	SF	Copper	1980 Material Manual
	3780 Grove Rd	N	C	N	1 inch	7/30/1981	C	1 inch	7/23/1987	SF	Copper	1980 Material Manual
	3783 Grove Rd	N	C	N	1 inch	7/30/1981	C	1 inch	3/2/1982	SF	Copper	1980 Material Manual
	3787 Grove Rd	N	C	N	1 inch	7/30/1981	P	1 inch	3/2/1982	SF	Plastic	1980 Material Manual
	3791 Grove Rd	N	C	N	1 inch	7/30/1981	C	1 inch	6/12/1981	SF	Copper	1980 Material Manual

Lloyd St and Agamaite Rd  
Lead and Copper Report

Site ID	Address	Gooseneck	Street side material	Previously lead	Street side service size	Street side install date	Property side line material	Property side size	Property side install date	Building type	Plumbing Mat.	Basis of street side classification
3906	Lloyd St	N	C	N	1 inch	7/22/1981	P	1 inch	11/11/1982	SF	Plastic	1980 Material Manual
3911	Lloyd St	N	C	N	1 inch	7/22/1981	C	1 inch	4/9/1982	SF	Copper	1980 Material Manual
3912	Lloyd St	N	C	N	1 inch	7/23/1981	P	1 inch	4/29/1999	SF	Plastic	1980 Material Manual
3915	Lloyd St	N	C	N	1 inch	7/23/1981	C	1 inch	4/9/1982	SF	Copper	1980 Material Manual
3916	Lloyd St	N	C	N	1 inch	7/27/1981	C	1 inch	4/29/1999	SF	Copper	1980 Material Manual
3918	Lloyd St	N	C	N	1 inch	7/27/1981	P	1 inch	5/30/2001	SF	Plastic	1980 Material Manual
3919	Lloyd St	N	C	N	1 inch	7/27/1981	P	1 inch	8/12/2003	SF	Plastic	1980 Material Manual
3922	Lloyd St	N	C	N	1 inch	7/27/1981	P	1 inch	10/4/2001	SF	Plastic	1980 Material Manual
3923	Lloyd St	N	C	N	1 inch	7/27/1981	P	1 inch	6/1/2003	SF	Plastic	1980 Material Manual
3927	Lloyd St	N	C	N	1 inch	7/27/1981	P	1 inch	6/1/2003	SF	Plastic	1980 Material Manual
3933	Lloyd St	N	C	N	1 inch	7/27/1981	C	1 inch	5/10/1982	SF	Copper	1980 Material Manual
3917	Agamaite	N	C	N	1 inch	7/22/1981	P	1 inch	5/10/1996	SF	Plastic	1980 Material Manual
3921	Agamaite	N	C	N	1 inch	2/3/1981	C	1 inch	5/10/1996	SF	Copper	1980 Material Manual
3925	Agamaite	N	C	N	1 inch	2/3/1981	C	1 inch	7/12/1995	SF	Copper	1980 Material Manual
3926	Agamaite	N	C	N	1 inch	2/3/1981	C	1 inch	10/10/1993	SF	Copper	1980 Material Manual
3929	Agamaite	N	C	N	1 inch	2/3/1981	C	1 inch	2/27/1982	SF	Copper	1980 Material Manual
3930	Agamaite	N	C	N	1 inch	2/4/1981	P	1 inch	8/1/2000	SF	Plastic	1980 Material Manual
3933	Agamaite	N	C	N	1 inch	2/4/1981	C	1 inch	2/2/1982	SF	Copper	1980 Material Manual
3934	Agamaite	N	C	N	1 inch	2/4/1981	C	1 inch	2/2/1982	SF	Copper	1980 Material Manual
3939	Agamaite	N	C	N	1 inch	2/4/1981	C	1 inch	2/25/1982	SF	Copper	1980 Material Manual
3940	Agamaite	N	C	N	1 inch	2/5/1981	C	1 inch	3/14/1982	SF	Copper	1980 Material Manual
3943	Agamaite	N	C	N	1 inch	2/5/1981	C	1 inch	2/25/1982	SF	Copper	1980 Material Manual
3946	Agamaite	N	C	N	1 inch	2/5/1981	C	1 inch	3/14/1982	SF	Copper	1980 Material Manual
3947	Agamaite	N	C	N	1 inch	2/5/1981	C	1 inch	2/25/1982	SF	Copper	1980 Material Manual
3952	Agamaite	N	C	N	1 inch	2/5/1981	P	1 inch	9/9/2000	SF	Plastic	1980 Material Manual